

3,500 NEW MAD CO.-H.W.  
Noranda Aluminum, Inc.



JOHN ASHCROFT  
Governor

G. TRACY MEHAN III  
Director

STATE OF MISSOURI

Division of Energy  
Division of Environmental Quality  
Division of Geology and Land Survey  
Division of Management Services  
Division of Parks, Recreation,  
and Historic Preservation

## DEPARTMENT OF NATURAL RESOURCES

### MEMORANDUM

DATE: June 24, 1991

TO: Mr. Arthur Groner, Section Chief, Hazardous Waste Enforcement Unit, Waste Management Program

FROM: Mr. Albert R. Wampler, Environmental Engineer,  
*Aew* Southeast Regional Office

SUBJECT: Noranda Aluminum, Inc. (New Madrid) (RCRA Inspection)

Attached is a RCRA Report on Inspection for Noranda Aluminum, Inc. located at New Madrid, Missouri. The facility has been determined to be a large quantity generator of hazardous waste.

ARW/sw

Attachments

POLAROID  
21

JUN 02 1991

HAZARDOUS WASTE PROGRAM  
MISSOURI DEPARTMENT OF NATURAL RESOURCES  
JUN 02 1991

R00013215  
RCRA Records Center

3,500 NEW MADI CO.-H.W.  
Noranda Aluminum, Inc.



JOHN ASHCROFT  
Governor

G. TRACY MEHAN III  
Director

STATE OF MISSOURI  
DEPARTMENT OF NATURAL RESOURCES

Division of Energy  
Division of Environmental Quality  
Division of Geology and Land Survey  
Division of Management Services  
Division of Parks, Recreation,  
and Historic Preservation

DIVISION OF ENVIRONMENTAL QUALITY

Poplar Bluff Regional Office  
948 Lester St.  
P.O. Box 1420  
Poplar Bluff, MO 63901  
314-785-0832

June 24, 1991

Mr. David Hart  
Environmental/Energy Manager  
Noranda Aluminum, Inc.  
P.O. Box 70  
New Madrid, Missouri 63869

CERTIFIED MAIL: P 307 200 668  
L.O.W. 91-SE 003

Dear Mr. Hart:

Enclosed is a Report on Inspection for Noranda Aluminum, Inc. conducted on June 19, 1991. This inspection was made to determine if Noranda Aluminum, Inc. was in compliance with the environmental laws of the State of Missouri and rules of the Department of Natural Resources and the United States Environmental Protection Agency pertaining to hazardous waste management. The contents of this report are believed to be self-explanatory. If, however, you have any questions concerning any part of the report, please call Albert R. Wampler at our Southeast Regional Office, (314) 785-0832.

During this inspection, violations of Missouri's Hazardous Waste Management Law and regulations were found. It is our purpose by this report to notify you of these apparent violations and to persuade you to take steps as outlined in the report to eliminate these violations as rapidly as possible.

The Department of Natural Resources strongly urges that the recommendations contained in this report be given your immediate attention. The recommendations are in our best judgment, necessary actions to return your facility to compliance. Your facility should submit copies of documentation requested in this report to the Department of Natural Resources, Waste Management Program, Attn: Bruce Martin, Chief, Hazardous Waste Enforcement Unit, P.O. Box 176, Jefferson City, MO 65102 and to the Department of Natural Resources, Regional Administrator, Southeast Regional Office, P.O. Box 1420, Poplar Bluff, MO 63901.

Mr. David Hart  
June 24, 1991  
Page 2

Compliance should be completed within thirty (30) days of the receipt of this report and documentation of compliance should be mailed to each above mentioned office within thirty (30) days of the receipt of this report.

A follow-up investigation will be conducted by staff of the Department to determine if deficiencies have been corrected.

Sincerely,



James A. Burris, P.E.  
Regional Administrator

JAB/ARW/sw

Enclosures

RESOURCE CONSERVATION AND RECOVERY ACT  
AND  
MISSOURI HAZARDOUS WASTE MANAGEMENT LAW  
COMPLIANCE EVALUATION INSPECTION REPORT

FACILITY

Noranda Aluminum, Inc.  
P.O. Box 70  
New Madrid, Missouri 63869  
314-643-2361

EPA ID-MOD093750966  
MO Generator ID-001562

PARTICIPANTS

Department of Natural Resources

Mr. Albert R. Wampler  
Environmental Engineer  
Southeast Regional Office

Noranda Aluminum, Inc.

Mr. David Hart  
Environmental/Energy Manager

Mr. Troy Long  
Director, Safety and Security

INTRODUCTION

On June 19, 1991, Albert R. Wampler, representing the Missouri Department of Natural Resources, Southeast Regional Office, conducted an inspection of the Noranda Aluminum, Inc. facility located near New Madrid, Missouri. The inspection was conducted to determine compliance of the facility with the Resource Conservation and Recovery Act, the Missouri Hazardous Waste Management Law, and applicable state and federal regulations promulgated thereunder. Authority to conduct such inspections has been granted under Section 260.375(9) and 260.377 RSMo.

Appropriate credentials were presented and an explanation given as to the purpose and authority to conduct the inspection. Representatives of the facility were informed of the facility's rights to confidentiality and informed that photocopies of documents and photographs may be requested and taken during the inspection.

Facility personnel were informed of the inspection procedure to be followed, which would consist of the initial opening conference, a file review, visual facility inspection, and a closing conference.

FACILITY DESCRIPTION

Noranda Aluminum, Inc. is a primary aluminum reduction facility with an annual metal production of 225,000 tons. Initial production was started from the Rod Mill, being supplied by purchased metal, in 1969. The first metal produced by the reduction plant was in early 1971. Metal produced was used by the adjacent Rod Mill for conversion into aluminum rod used in electrical conductor products. Metal is also used for supplying Noranda's customers with extrusion billet, sheet ingot or casting ingot. A major portion of metal is shipped to facilities owned by Noranda used for building products and sheet and foil manufacture. Aluminum sales are made world wide.

Noranda Aluminum, Inc., at the New Madrid facility, employs approximately 1200 people, working on a three (3) shift schedule.

Aluminum is received by barge as is calcined petroleum coke, a material essential to aluminum production. Other materials such as cryolite are received by rail. Steel cells lined with carbon are charged with alumina, cryolite (sodium aluminum fluoride) and aluminum fluoride. A carbon electrode is introduced into the mixture and direct current applied. This process frees the aluminum metal, which is drawn off daily and routed to adjacent plant operations.

Carbon anodes are a requirement in the metal production and Noranda manufactures the anodes from calcined petroleum coke and coal tar pitch. The carbon (coke) is crushed, sized and mixed with coal tar pitch and heated to 150°C. The mixture is then pressed into carbon anode blocks. The blocks are baked in furnaces heating to approximately 1150°C. Upon cooling the anodes are cleaned and sent to be secured (two blocks) to an aluminum rod assembly. The anodes are then coated with a layer of molten aluminum and the completed unit delivered to the cells (pots).

The major waste stream produced by Noranda is that of spent potliner material (K088). Generation rate varies with 698,820 pounds being generated in the first quarter of 1991. This waste is transported by U.S. Pollution Control, Inc. (H-1024) and Union Pacific Railroad (R-1536) to USPI's facility located in Clive, Utah (UTD991301748), manifested as RQ Hazardous Solid N.O.S. ORME NA 9189 (K088) (Spent Potliner).

Waste petroleum naptha (D001) is generated at the various parts washers at an average rate of 2425 pounds per month. Safety-Kleen Corporation manages this waste for recycling purposes.

Intermittent waste streams that are or have been generated by Noranda are carbon bake reactor bags (D006), waste lab solvents (F001-F005), fume duct sludge from the green mill (D008), and waste oil and grease. A copy of Noranda's aluminum hazardous waste shipments manifest file and a copy of the 1st quarter, quarterly report have been included in this report as Attachments 1 and 2.

#### UNSATISFACTORY FEATURES

The following unsatisfactory features list the regulatory or statutory provisions which Noranda Aluminum, Inc. were in violation of at the time of the inspection. Any 40 CFR regulations cited have been adopted by reference in the Missouri hazardous waste regulations.

1. Failure to document all transporters', Missouri hazardous waste transporter identification number on the manifest. 10 CSR 25-5.262(2). Manifests indicated that three (3), two (2) U.S. Pollution Control transporters (truck) and one (1) railroad (Union Pacific) were being used. Noranda Aluminum, Inc. had not documented the railroads identification number (R-1536) as required. This MO Transporter ID number should be documented on each manifest when Union Pacific Railroad is used to transport the waste.
2. Failure to document the license plate number for the waste carrying portion of the vehicle used to transport shipments of hazardous waste, including the state of registration on the manifests. 10 CSR 25-5.262(2)B2C. The license plate number and state of registration for the waste carrying portion of the vehicle must be documented on the manifest for each shipment.
3. Failure to send copies of the facility contingency plan to all local police departments, fire departments, hospitals, and state and local emergency response teams that may be called upon to provide emergency services. 40 CFR 262.34(4) referenced to 40 CFR 265 Subpart D referenced to 40 CFR 265.53(b). The facility maintained and had on file a copy of the contingency plan but the facility director of safety and security stated that the plan had not been mailed to the above named emergency agencies. The facility should immediately mail a copy of the contingency plan to all agencies which may be called upon for emergency service.

4. Failure to have on file adequate documentation for personnel training. 262.34(4) as referenced to 40 CFR 265.16(d). The complete written job description and title for each position related to hazardous waste management and the name of that person(s) filling that position must be documented. The job description must include requisite skill, education or other qualification, and duties of personnel assigned to each position. Records should be kept on file documenting that on the job training or job experience required has been given to and completed by facility personnel listed in 40 CFR 265.16(a)(b)(c)(d). A written description of the type and amount of introductory and continuing training that will be given to each person filling a position related to hazardous waste management should be documented in the training file.

ADDITIONAL COMMENTS

During the inspection, it was observed that water, as a result of precipitation, had accumulated inside the containment area where waste oil storage tanks were located. The containment areas should be inspected or monitored regularly to insure that any accumulation of rainfall is removed in a timely manner. It should be noted by Noranda Aluminum, Inc. that any recommendations made in this report are for your facility's use as guidelines for implementations of corrective actions. It will be the responsibility of Noranda Aluminum, Inc. to implement specific corrective actions, and satisfactorily document them to demonstrate a return to compliance with the Hazardous Waste Law and regulations.

SUBMITTED BY:

*Albert R. Wampler*  
Albert R. Wampler  
Environmental Engineer II

ARW/JAB/sw

Attachments

APPROVED BY:


*James A. Burris*  
James A. Burris, P.E.  
Regional Administrator

Photographs taken June 19, 1991

Noranda Aluminum, Inc.  
New Madrid, Missouri

Taken by Albert R. Wampler  
Southeast Regional Office

סוכן כבישית מירוץ  
1-800-262-0222  
STOCK # PPA840-000



EMPTY DRUMS DEDICATED  
MANAGEMENT ENVIRONMENTAL ENERGY  
IN PHOTO TAKEN 6/19/91

BY A.R.W., SERO

NORANDA Aluminum, Inc.

TAKEN BY WASTE OIL  
STORAGE AREA

CONTAINER HOLDING SPENT  
POT LINER STORED IN ENCLOSED  
BUILDING, PROPER LADING  
TAKEN 6/19/91 BY A.R.W.  
SERO, NORANDA Aluminum, Inc.  
NEW MADRID, MO

STORAGE BUILDING FOR  
SPENT POT LINER MASTERS

SIX' IN BACK GROUND IS  
FROM REARDED CELL

TAKEN 6/19/91 BY A.R.W.  
SERO


NORANDA Aluminum, Inc.

VIEW OF BUILDING HOUSES  
CELLS, SHOWS OVERALL SIZE  
OF BUILDINGS

TAKEN 6/19/91 BY A.R.W., SERO

NORANDA Aluminum, Inc.

NEW MADRID, MO.



WASTE OIL STORAGE TANKS

FULLY CONTAINED .0001 OF ONE (1)

TANK CONTAINED WASTE OIL

OTHER EMPTY 6/19/91

BY ADAC, SERO

NORANDA Aluminum, Inc.

STORAGE AREA FOR WASTE  
MATERIAL DEEMED NON-HAZARDOUS

NOTE SAFETY-KLEEN PERSONNEL  
LOADING THIS WASTE mostly  
OFF SPEC OILS AND GREASE  
6/19/91 TAKEN BY ADAC

SERO

NORANDA Aluminum Inc.

SOME MATERIAL CURRENTLY BEING ANALYZED  
FOR POSSIBLE HAZARDOUS CONSTITUENTS

WASTE OIL STORAGE AREA

LARGE TANKS USED FOR  
WASTE OIL ACCUMULATION

SMALL AMOUNT OF SPILLAGE  
BUT AREA WAS RELATIVELY  
CLEAR OF OIL WASTE

NORANDA Aluminum, Inc.

6/19/91 BY ADAC SERO

## LARGE QUANTITY GENERATOR CHECKLIST

Name of Facility: NORANDA ALUMINUM, INC.Date: JUNE 19, 1991Address: P.O. Box 70  
NEW MADRID, MISSOURI 63869Other Inspections Done:  
RR TRANS LDR  
OTHERPhone: (314) 643-2361 MO ID# 001562 EPA ID# M00093250966Facility Representative: DAVID HART Title: [ENVIRONMENTAL/ENERGY]  
TROY LONG MANAGER  
DIRECTOR SAFETY AND SECURITY

Briefly describe manufacturing process(es). (Use continuation sheet, if needed.)

NORANDA ALUMINUM, INC. IS AN ALUMINUM REDUCTION COMPLEX PRODUCING APPROXIMATELY 225,000 TONS OF METAL PER YEAR. MOLTEN METAL IS PRODUCED IN A SERIES OF REDUCTION CELLS, (POTS). ALUMINA, CARBONATE AND ALUMINUM FLUORIDE ARE MIXED IN STEEL CELLS LINED WITH CARBON. A CARBON ELECTRODE IS PLACED INTO THIS MIXTURE AND DIRECT ELECTRICAL CURRENT APPLIED. THE CURRENT IS CARRIED THROUGH THE MOLTEN METAL TO THE CARBON CATHODE LINER. OXYGEN JOINS CARBON IN ANODE AS CO<sub>2</sub> RELEASING THE ALUMINUM.

List of wastes generated. (Use continuation sheet, if needed.)

<u>Waste</u>	<u>Amount/Month</u>	<u>Disposition</u>
1. (DOD) WASTE PETROLEUM NAPHTHA	~ 2425	P FOR SAFETY-KLEEN RECYCLE
2. (KOPP) SPENT POT LINERS	~ 300,000 #/MO	HAZARDOUS WASTE LANDFILL USPCJ CLIVE, IA OR ASSY MOUNTAIN FACILITY
3. (ATTACHED SHEET MANIFEST FORM SHOWS IRREGULAR WASTE GENERATED)		
4.		
5.		

- A. MANIFESTS AND RECORDKEEPING 10 CSR 25-5.262(2) AND 5.262(2)(3) AND (D)  
 Generator's MO and EPA I.D. Numbers. . . . . ✓  
 Manifest document number (MO I.D. & Shipment #). . . . . ✓  
 EPA Waste I.D. codes . . . . . ✓  
 Generator's name, address, phone # . . . . . ✓  
 All Transporters' names, phone #'s, MO and EPA I.D. #'s. RN14004 R-1536 ✓  
 Designated facility name, address, phone # and MO and EPA I.D. # . . . . ✓  
 Proper DOT Shipping Name, Hazard Class and I.D. # . . . . ✓  
 Containers, Quantity and Unit Wt/Vol being shipped properly designated . . . ✓  
 Proper certification including waste minimization. . . . . ✓  
 Manifest properly signed and dated . . . . . ✓  
 No more than 10 days time between generator and facility signatures. . . . ✓  
 Manifests returned within 35 days. . . . . ✓  
 If not, exception generator report submitted within 45 days. . . . . ✓  
 Completed manifests and Summary Manifest Report and Certification. . . . ✓  
 Spills of reportable quantities reported to DNR. . . . . NA
- B. PRETRANSPORT, CONTAINERIZATION AND LABELING 10 CSR 25-5.262(2) AND 5.262(2)(C)  
 Waste Packaged, marked and labeled per DOT during entire on-site storage period and prior to transport. . . . . ✓  
 Placards available for use by transporters . . . . . ✓  
 Satellite accumulation requirements met (if applicable). . . . . ✓  
 a. Stored in satellite areas less than 1 year. . . . . ✓  
 b. Containers marked identifying contents and beginning date . . . . . ✓  
 c. Containers kept closed/compatible/good condition. . . . . ✓  
 d. Quantities accumulated not exceeding 55 gal. (1 qt. acutely hg. waste). . . . . ✓  
 C. STORAGE STANDARDS 10 CSR 25-5.262(2) AND 5.262(2)(C)2 AND 3  
 Facility inspected and maintained. . . . . ✓  
 Date of accumulation marked. . . . . ✓  
 Storage less than 90 days (unless small quantity generator). . . . . ✓  
 D. CONTAINER STORAGE 10 CSR 25-5.262(2) AND 5.262(2)(C)2  
 Containers in good condition . . . . . ✓  
 Containers kept closed in storage. . . . . ✓  
 Containers storing incompatible wastes separated or protected from each other. . . . . ✓  
 Containers of ignitable or reactive waste stored > 50 feet from property line . . . . . ✓  
 Containers stored within a containment system (if applicable) meeting criteria of 10 CSR 25-5.262(2)(C)2.B. . . . ✓

LICENSE # 6)  
STATE OF REGISTRATION 6)

E. STORAGE TANKS 10 CSR 25-5.262(2) AND 5.262(2)(C)1.C.  
(See tank checklist) *Waste oil only*

F. PERSONNEL TRAINING 10 CSR 25-5.262(2)

Documentation of hazardous waste director's qualifications or training.

Completed classroom or on-the-job training.

Job title, description, and name of person filling position

Written record of the type and amount of training given

Documentation confirming that training has been given

G. PREPAREDNESS AND PREVENTION 10 CSR 25-5.262(2) AND 5.262(2)(C)1.E.

Internal communication or alarm system.

Device in the hazardous waste operation area capable of summoning emergency assistance.

Fire control, spill control, and decontamination equipment available.

Adequate water supply for fire control equipment

Adequate and proper safety equipment available

Adequate aisle space.

Arrangements with local emergency agencies.

H. CONTINGENCY PLAN AND EMERGENCY PROCEDURES 10 CSR 25-5.262(2)

Contingency Plan.

Detailed description of procedures that personnel must implement to respond to fires, explosions, or releases of hazardous waste.

Describe formal arrangements with emergency agencies.

Name, addresses, and phone numbers (home & office) of emergency coordinators.

Emergency equipment including its description and location.

Evacuation plan if applicable.

*COPY OF CONTINGENCY PLAN  
NOT SENT TO EMERGENCY AGENCIES*

I. WASTE OIL 10 CSR 25-11.010

Written waste oil contract maintained.

Waste oil properly stored and transported.

COMMENTS:

---

---

---

---

---

Inspector Signature & Title: Albert R. Wangler Environmental Engineer  
Office: southeast Regional office

IN COMPLIANCE

IN VIOLATION OR  
ABSENT

Noranda Aluminum, Inc.  
P.O. Box 70  
New Madrid, Missouri 63869  
(314) 643-2361

**noranda**

April 30, 1991

CERTIFIED MAIL

Waste Management Program  
Department of Natural Resources  
P. O. Box 176  
Jefferson City, Missouri 65102

RE: FIRST QUARTER, 1991

Attached please find Noranda Aluminum, Inc.'s Generator's Hazardous Waste Report for the period ending March 31, 1991.

Sincerely,

*David Hart*  
David Hart  
Environmental/Energy Manager

DEH:maj  
Enclosure

CC: R. Ebersole

ATTACHMENT

P 537 573 546 MO  
 D. HART, NORANDA 1ST QTR GEN  
 RECEIPT FOR CERTIFIED MAIL REPT

NO INSURANCE COVERAGE PROVIDED  
 NOT FOR INTERNATIONAL MAIL  
 (See Reverse)

SENT TO <b>WASTE MGT. PRGRAM, MODNR</b>	
Street and No. <b>P.O. BOX 176</b>	
P.O., State and ZIP Code <b>JEFFERSON CITY MO 65102</b>	
Postage	\$
Certified Fee	<input checked="" type="checkbox"/>
Special Delivery Fee	<input type="checkbox"/>
Restricted Delivery Fee	<input type="checkbox"/>
Return Receipt showing to whom and Date Delivered	<input checked="" type="checkbox"/>
Return Receipt showing to whom, Date, and Address of Delivery	<input type="checkbox"/>
TOTAL Postage and Fees	\$
Postmark or Paid MO MAY 3 1991	

\* U.S.G.P.O. 1989-234-555

PS Form 3800, June 1985

<b>● SENDER:</b> Complete items 1 and 2 when additional services are desired, and complete items 3 and 4. Put your address in the "RETURN TO" Space on the reverse side. Failure to do this will prevent this card from being returned to you. <u>The return receipt fee will provide you the name of the person delivered to and the date of delivery.</u> For additional fees the following services are available. Consult postmaster for fees and check box(es) for additional service(s) requested.	
1. <input checked="" type="checkbox"/> Show to whom delivered, date, and addressee's address.    2. <input type="checkbox"/> Restricted Delivery <i>(Extra charge)</i>	
3. Article Addressed to: <b>WASTE MANAGEMENT PROGRAM</b> <b>MO DNR, P.O. BOX 176</b> <b>JEFFERSON CITY, MO 65102</b>	
4. Article Number <b>P 537 573 546</b> Type of Service: <input type="checkbox"/> Registered <input type="checkbox"/> Insured <input checked="" type="checkbox"/> Certified <input type="checkbox"/> COD <input type="checkbox"/> Express Mail <input type="checkbox"/> Return Receipt for Merchandise	
Always obtain signature of addressee or agent and <u>DATE DELIVERED</u> .	
5. Signature Addressee <input checked="" type="checkbox"/> <i>[Signature]</i>	
6. Signature <input checked="" type="checkbox"/> <i>[Signature]</i>	
7. Date of Delivery <b>MAY 03 1991</b>	

PS Form 3811, Apr. 1989

\* U.S.G.P.O. 1989-238-815

DOMESTIC RETURN RECEIPT



MISSOURI DEPARTMENT OF NATURAL RESOURCES  
P.O. BOX 176 14) 751-3176  
JEFFERSON CITY, MISSOURI 65102

## GENERATOR'S HAZARDOUS WASTE REPORT SUMMARY SHEET

PART I  
OFFICE USE ONLY

### NOTE ► PLEASE READ INSTRUCTIONS AND EITHER PRINT OR TYPE

Regardless of whether any off-site shipment occurred, as a registered generator of hazardous waste, you must complete, sign, and transmit this form to the Department of Natural Resources.

#### SECTION A: REPORT IDENTIFICATION

1. TYPE OF REPORT (CHECK ONE)	2. FOR THE PERIOD ENDING (CHECK ONE & FILL IN YEAR)	3. PAGE
<input checked="" type="checkbox"/> QUARTERLY <input type="checkbox"/> ANNUAL (NON-GENERATOR) (IF ANNUAL CHECKED, PLACE X IN 6-30 BOX)	<input type="checkbox"/> 9-30- ____ (YEAR) <input type="checkbox"/> 12-31- ____ (YEAR) <input checked="" type="checkbox"/> 3-31- 91 (YEAR) <input type="checkbox"/> 6-30- ____ (YEAR)	1 OF 4

#### SECTION B: GENERATOR IDENTIFICATION

4. GENERATOR'S NAME		5. GENERATOR'S USEPA I.D. NUMBER	
Noranda Aluminum, Inc.		M.O.D.O.9.3.7.5.0.9.6.6	
6. GENERATOR CONTACT PERSON (NAME)		TELEPHONE NUMBER	
Don Backfisch		314-643-2361	
8. MAILING ADDRESS		CITY	STATE ZIP CODE
P. O. Box 70		New Madrid	MO 63869
9. PLANT ADDRESS		CITY	STATE ZIP CODE
St. Jude Industrial Park		New Madrid	MO 63869
10. NAME OF PARENT FIRM			OFFICE USE ONLY
Noranda Aluminum, Inc.			

#### SECTION C: STATUS OF WASTE GENERATED (CHECK ONE)

11. SHIPPED OFF-SITE. Complete part 2, attach completed hazardous waste manifests, sign certification and transmit to the department.	12. <input type="checkbox"/> REPORTABLE QUANTITY NOT GENERATED. Sign certification and transmit to the department.	13. <input type="checkbox"/> REPORTABLE QUANTITY GENERATED BUT NOT SHIPPED OFF-SITE THIS QUARTER. Sign certification and transmit to the department. (Do not complete Part 2).
---	--	--

#### SECTION D: COMMENTS

14.

#### SECTION E: CERTIFICATION STATEMENT

I certify under penalty of law that I have personally examined and am familiar with the information submitted in this and all attached documents and that based on my inquiry of those individuals immediately responsible for obtaining the information, I believe that the submitted information is true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment.

PRINT NAME	SIGNATURE	DATE
David Hart		APRIL 30, 1991



## MISSOURI DEPARTMENT OF NATURAL RESOURCES

P.O. BOX 176 4) 751-3176  
JEFFERSON CITY, MISSOURI 65102

## GENERATOR'S HAZARDOUS WASTE REPORT SUMMARY SHEET

PART II

OFFICE USE ONLY

## NOTE ► PLEASE READ INSTRUCTIONS AND EITHER PRINT OR TYPE

Entries made on this page must summarize the total amount of waste transported off-site to an individual facility during the specified quarter. Separate sheets must be completed for each facility utilized.

## SECTION F: REPORT IDENTIFICATION

1. FOR THE PERIOD ENDING (CHECK ONE & FILL IN YEAR)	2. PAGE	3. GENERATOR'S MISSOURI I.D. NUMBER
<input type="checkbox"/> 9-30- ____ (YEAR)	<input type="checkbox"/> 12-31- ____ (YEAR)	
<input checked="" type="checkbox"/> 3-31- 91 (YEAR)	<input type="checkbox"/> 6-30- ____ (YEAR)	0 0 1 5 6 2

## SECTION G: FACILITY IDENTIFICATION

4. FACILITY NAME (NAME OF OFF-SITE LOCATION WHERE WASTE WAS DELIVERED)  
**Safety-Kleen Corp.**

5. FACILITY'S EPA I.D. NUMBER

**M O D 0 0 0 6 6 9 0 5 1**

6. FACILITY SITE ADDRESS

**Route #2, Box 529-D Behind Cook's Garage**

7. FACILITY'S MISSOURI I.D. NUMBER

**H H 0 0 1 9**

CITY

**Cape Girardeau**

STATE

**MO**

ZIP CODE

**63701**

## SECTION H: WASTE IDENTIFICATION

LINE	8. DESCRIPTION OF WASTE	9. DOT HAZARD CODE	10. EPA HAZARDOUS WASTE NUMBER	11. PREVIOUSLY REPORTED (SEE INST.)	12. TOTAL AMOUNT OF WASTE	13. UNIT OF MEAS.	14. SPECIFIC GRAVITY	15. HANDLING CODE
1	Waste Petroleum Naphtha Combustible Liquid	1 3	D 0 0 1 . . .		7270	P	.	T 0 4
2	ORMA; UN 1255	.	. . . . .				.	.
3		.	. . . . .				.	.
4		.	. . . . .				.	.
5		.	. . . . .				.	.
6		.	. . . . .				.	.
7		.	. . . . .				.	.
8		.	. . . . .				.	.
9		.	. . . . .				.	.
10		.	. . . . .				.	.

## SECTION I: TRANSPORTATION SERVICES UTILIZED

	16. COMPANY NAME	17. MISSOURI ID NO.	18. USEPA I.D. NUMBER
a	<b>Safety-Kleen Corporation</b>	H - 1 2 7 3	M O D 0 0 0 6 6 9 0 5 1
b		H - . . . .	.....
c		H - . . . .	.....
d		H - . . . .	.....

## SECTION J: COMMENTS

19.

**Material is recycled.**

5-030-01

INSTRUCTIONS FOR THE COMPLETION OF THIS FORM ARE ON REVERSE SIDE.

THIS DOCUMENT MUST BE USED FOR ALL MISSOURI-DESTINED SHIPMENTS.

## MISSOURI DEPARTMENT OF NATURAL RESOURCES

Division of Environmental Quality

Waste Management Program

P.O. Box 176 Jefferson City, Missouri 65102

314-751-3176

## HAZARDOUS WASTE MANIFEST

EMERGENCY RESPONSE  
NUMBER  
1-800-424-1362  
THE MATREC  
TEL 342-1363  
DEPT. OF NATURAL RESOURCES  
314-751-3176

Form Approved. OMB No. 2050-0039. Expires 9-30-91

<b>UNIFORM HAZARDOUS WASTE MANIFEST</b>		1. Generator's US EPA ID No. <b>MOD 093750966</b>	Manifest Document No. <b>29746</b>	2. Page <b>1</b> of <b>1</b>	Information in the shaded areas is required by State Law.
3. Generator's Name and Mailing Address <b>NORANDA ALUMINUM MOBILE SHOP NEW MADRID</b>		MOBILE SHOP MO 63869		A. Missouri Manifest Document Number <b>0 0 1 5 6 2 S K 50</b>	
4. Generator's Phone <b>314 643-2361</b>		6. US EPA ID Number <b>MOD 000669051</b>		C. MO. Transporter's ID <b>H-1273</b>	
5. Transporter 1 Company Name <b>SAFETY-KLEEN CORP.</b>		8. US EPA ID Number		D. Transporter's Phone <b>314 335-1616</b>	
7. Transporter 2 Company Name				E. MO. Transporter's ID	
9. Designated Facility Name and Site Address <b>SAFETY-KLEEN CORP. BEHIND COOKS GE CAPE GIRARDEAU, MO 63701</b>		10. US EPA ID Number <b>5-030-01 MOD 000669051</b>		F. Transporter's Phone	
11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID NUMBER) <b>a. WASTE PETROLEUM NAPHTHA COMBUSTIBLE LIQUID UN1255(D001)(ERG #27)</b>		12. Containers <b>15</b>	13. Total Quantity <b>1290 P</b>	14. Unit Wt/Vol	I. Waste No. <b>D001 D039</b>
b.				EPA WASTE CODE	
c.				EPA WASTE CODE	
d.				EPA WASTE CODE	
J. Additional Descriptions for Materials Listed Above <b>a. D018</b>		K. Handling Codes for Wastes Listed Above			
a. <b>D018</b>					
b.					
c.					
d.					
15. Special Handling Instructions and Additional Information <b>IF UNDELIVERABLE, RETURN TO GENERATOR.</b>		<b>SKDOT# A: 501 B: C: D:</b> <b>EMERG RESP#708-888-4660</b>			
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations and applicable state regulations.					
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.					
Printed/Typed Name <b>Don Buckfisch</b>		Signature <b>Don Buckfisch</b>		Month Day Year <b>01/03/91</b>	Date
17. Transporter 1 Acknowledgement of Receipt of Materials Printed/Typed Name <b>Deon M. Alay</b>		Signature <b>Deon M. Alay</b>		Month Day Year <b>01/03/91</b>	Date
18. Transporter 2 Acknowledgement of Receipt of Materials Printed/Typed Name		Signature		Month Day Year	
19. Discrepancy Indication Space					
20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19. Printed/Typed Name <b>Nancy Gann</b>		Signature <b>Nancy Gann</b>		Month Day Year <b>01/03/91</b>	

5-030-01

INSTRUCTIONS FOR THE COMPLETION OF THIS FORM ARE ON  
REVERSE SIDE!  
THIS DOCUMENT MUST BE USED  
FOR ALL MISSOURI-DESTINED  
SHIPMENTS.

MISSOURI DEPARTMENT OF NATURAL RE CES  
Division of Environmental Quality  
Waste Management Program  
P.O. Box 176 Jefferson City, Missouri 65102  
314-751-3176

EMERGENCY RESPONSE  
U.S. COAST GUARD  
1-800-424-8802  
CHEM TREC  
1-800-424-9300  
DEPT. OF NATURAL RESOURCES  
314-634-2436

## HAZARDOUS WASTE MANIFEST

Form Approved. OMB No. 2050-0039. Expires 9-30-91

<b>UNIFORM HAZARDOUS WASTE MANIFEST</b>		1. Generator's US EPA ID No. <b>MOD 093750966</b>	Manifest Document No. <b>62284</b>	2. Page <b>1</b> of <b>1</b>	Information in the shaded areas is required by State Law.	
3. Generator's Name and Mailing Address <b>NORANDA ALUMINUM MOBILE SHOP NEW MADRID</b>		MOBILE SHOP MO 63869		A. Missouri Manifest Document Number <b>00156228403</b>		
4. Generator's Phone ( <b>314) 643-2361</b> )		6. US EPA ID Number <b>MOD 000669051</b>		B. State Generator's ID - other		
5. Transporter 1 Company Name <b>SAFETY-KLEEN CORP.</b>		8. US EPA ID Number		C. MO. Transporter's ID <b>H-1273</b>		
7. Transporter 2 Company Name				D. Transporter's Phone <b>314 335-1616</b>		
9. Designated Facility Name and Site Address <b>SAFETY-KLEEN CORP. BEHIND COOKS GE CAPE GIRARDEAU, MO 63701</b>		10. US EPA ID Number <b>5-030-01 MOD 000669051</b>		E. MO. Transporter's ID		
11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID NUMBER)		12. Containers	13. Total Quantity	14. Unit Wt/Vol.	I. Waste No.	
a. <b>WASTE PETROLEUM NAPHTHA COMBUSTIBLE LIQUID UN1255(D001)(ERG #27)</b>	11	DM	1,404	P	EPA WASTE CODE <b>D001</b> <b>D039</b>	
b.					EPA WASTE CODE	
c.					EPA WASTE CODE	
d.					EPA WASTE CODE	
J. Additional Descriptions for Materials Listed Above		K. Handling Codes for Wastes Listed Above				
a. <b>D018</b>						
b.						
c.						
d.						
15. Special Handling Instructions and Additional Information <b>IF UNDELIVERABLE, RETURN TO GENERATOR.</b> 9105 23420045 562284 5-030-01-7018 03 <b>EMERG RESP#708-888-4660</b>						
SKDOT# A: <b>501</b> B: <b>B</b> C: <b>C</b> D: <b>D</b>						
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations and applicable state regulations.						
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, If I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.						
Printed/Typed Name <b>RICH HOLLAND</b>		Signature <b>Rich Holland</b>		Month	Day	Year
17. Transporter 1 Acknowledgement of Receipt of Materials						
Printed/Typed Name <b>REX MILLER</b>		Signature <b>Rex Miller</b>		Month	Day	Year
18. Transporter 2 Acknowledgement of Receipt of Materials				Date		
Printed/Typed Name		Signature		Month	Day	Year
19. Discrepancy Indication Space <b>Section A changed Missouri manifest number to SK51-032111</b>						
20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.		Signature <b>Nancy Gann</b>		Month	Day	Year

MISSOURI DNR FINAL COPY — PART 1

THIS COPY MUST BE SENT BACK TO THE GENERATOR BY THE DESIGNATED FACILITY THEN TRANSFERRED TO THE DEPARTMENT BY THE GENERATOR.

5-030-01

INSTRUCTIONS FOR THE COMPLETION OF THIS FORM ARE ON REVERSE SIDE.

THIS DOCUMENT MUST BE USED FOR ALL MISSOURI-DESTINED SHIPMENTS.

## MISSOURI DEPARTMENT OF NATURAL RESOURCES

Division of Environmental Quality

Waste Management Program  
P.O. Box 176 Jefferson City, Missouri 65102  
314-751-3176

EMERGENCY RESPONSE  
U.S. COAST GUARD  
1-800-424-8802  
CDEM TREC  
1-800-424-9360  
DEPT. OF NATURAL RESOURCES  
314-634-2436

## HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12-Pitch) typewriter.)

Form Approved. OMB No. 2050-0039. Expires 9-30-91

<b>UNIFORM HAZARDOUS WASTE MANIFEST</b>		1. Generator's US EPA ID No. <b>MOD 093750966</b>	Manifest Document No. <b>10296</b>	2. Page <b>1</b> of <b>1</b>	Information in the shaded areas is required by State Law.
3. Generator's Name and Mailing Address <b>NORANDA ALUMINUM MOBILE SHOP NEW MADRID</b>		MOBILE SHOP <b>MO 63869</b>		A. Missouri Manifest Document Number <b>0 0 1 5 6 2 SK 5 2</b>	
4. Generator's Phone ( <b>314) 643-2361</b> )		6. US EPA ID Number <b>MOD 000669051</b>		B. G.S.I. (Gen. Site Address)	
5. Transporter 1 Company Name <b>SAFETY-KLEEN CORP.</b>		8. US EPA ID Number		C. MO. Transporter's ID <b>H-1273</b>	
7. Transporter 2 Company Name				D. Transporter's Phone <b>314 335-1616</b>	
9. Designated Facility Name and Site Address <b>SAFETY-KLEEN CORP. BEHIND COCKS GE CAPE GIRARDEAU, MO 63701</b>		10. US EPA ID Number <b>5-030-01 MOD 000669051</b>		E. MO. Transporter's ID	
11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID NUMBER) <b>a. WASTE PETROLEUM NAPHTHA COMBUSTIBLE LIQUID UN1255(D001)(ERG #27)</b>		12. Containers	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
a.		<b>23</b>	<b>DM</b>	<b>3,055 P</b>	EPA WASTE CODE <b>D001</b>
b.					STATE
c.					EPA WASTE CODE
RECEIVED 6 1991					STATE
d.					EPA WASTE CODE
					STATE
J. Additional Descriptions for Materials Listed Above <b>a. DC39 D018</b>		K. Handling Code (Facility Use Only)			
a.		<b>SO2T04</b>	Interim	Final	Comments
b.					
c.					
d.					
15. Special Handling Instructions and Additional Information <b>9109 24358897 910296 5-030-01-7018 02 IF UNDELIVERABLE, RETURN TO GENERATOR. EMERG RESP# 708-888-4660</b>					
<b>SKDOT# A: 501 B: C: D:</b>					
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations and applicable state regulations.					
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.					
Printed/Typed Name <b>Don Backfish</b>		Signature <b>Don Backfish</b>		Month	Day Year
<b>03 04 91</b>					
Date					
17. Transporter 1 Acknowledgement of Receipt of Materials <b>Rex Mulkeydore</b>		Signature <b>Rex Mulkeydore</b>		Month	Day Year
<b>03 04 91</b>					
Date					
18. Transporter 2 Acknowledgement of Receipt of Materials <b>Eileen Jenkinson</b>		Signature <b>Eileen Jenkinson</b>		Month	Day Year
<b>03 05 91</b>					
Date					
19. Discrepancy Indication Space					
20. Designated Facility Owner or Operator: Certification of receipt and handling of hazardous materials covered by this manifest except as noted in Item 19. <b>Eileen Jenkinson</b>					
Printed/Typed Name <b>Eileen Jenkinson</b>		Signature <b>Eileen Jenkinson</b>		Month	Day Year
<b>03 05 91</b>					

5-030-01

INSTRUCTIONS FOR THE COMPLETION OF THIS FORM ARE ON REVERSE SIDE.

THIS DOCUMENT MUST BE USED FOR ALL MISSOURI-DESTINED SHIPMENTS.

## MISSOURI DEPARTMENT OF NATURAL RESOURCES

Division of Environmental Quality  
Waste Management Program  
P.O. Box 176 Jefferson City, Missouri 65102  
314-751-3176

EMERGENCY RESPONSE  
U.S. COAST GUARD  
1-800-424-5602  
CHEM TREC  
1-800-424-9300  
DEPT. OF NATURAL RESOURCES  
314-634-2436

## HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12-Pitch) typewriter.)

Form Approved. OMB No. 2050-0039. Expires 9-30-91

<b>UNIFORM HAZARDOUS WASTE MANIFEST</b>		1. Generator's US EPA ID No. <b>MOD 093750966</b>	Manifest Document No. <b>54763 OSK53</b>	2. Page <b>1</b> of <b>1</b>	Information in the shaded areas is required by State Law.	
3. Generator's Name and Mailing Address <b>NORANDA ALUMINUM MOBILE SHOP NEW MADRID</b>		MOBILE SHOP MO 63869		A. Missouri Manifest Document Number <b>0 0 1 5 6 2 S K 5 3</b>		
4. Generator's Phone ( <b>314 643-2361</b> )		6. US EPA ID Number <b>MOD 000669051</b>		B. G.S.I. (Gen. Site Address)		
5. Transporter 1 Company Name <b>SAFETY-KLEEN CORP.</b>		8. US EPA ID Number		C. MO. Transporter's ID <b>H-1273</b>		
7. Transporter 2 Company Name				D. Transporter's Phone <b>314 335-1616</b>		
9. Designated Facility Name and Site Address <b>SAFETY-KLEEN CORP. BEHIND COOKS GE CAPE GIRARDEAU, MO 63701</b>		10. US EPA ID Number <b>5-030-01</b>		E. MO. Transporter's ID		
11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID NUMBER)		12. Containers	13. Total Quantity	14. Unit Wt/Vol.	I. Waste No.	
a. <b>WASTE PETROLEUM NAPHTHA COMBUSTIBLE LIQUID UN1255(D001)(ERG #27)</b>	<b>11</b>	<b>D 1</b>	<b>1521</b>	<b>P</b>	EPA WASTE CODE <b>D001</b> STATE	
b.					EPA WASTE CODE STATE	
c.					EPA WASTE CODE STATE	
d. <b>RECEIVED MAR 27 1991 — NORANDA ALUMINUM, INC. Environmental Energy Mkt</b>					EPA WASTE CODE STATE	
J. Additional Descriptions for Materials Listed Above		K. Handling Code (Facility Use Only)				
a. <b>D039 D018</b>		a. <b>S02 T04</b>	DISTILLATION			
b.		b.				
c.		c.				
d.		d.				
15. Special Handling Instructions and Additional Information <b>9113 25265351 254763 5-030-01-7018 02 EMERGENCY RESP#708-888-4660 24HR. IF UNDELIVERABLE RETURN TO GENERATOR.</b>						
<b>SKDOT# A: 501 B: C: D:</b>						
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations and applicable state regulations.						
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.						
Printed/Typed Name <b>Don Backisch</b>		Signature <b>Don Backisch</b>		Month	Day	Year
<b>10 31 25 19 11</b>						
Date						
17. Transporter 1 Acknowledgement of Receipt of Materials Printed/Typed Name <b>Rex Mullenend</b>		Signature <b>Rex Mullenend</b>		Month	Day	Year
<b>10 31 25 19 11</b>						
Date						
18. Transporter 2 Acknowledgement of Receipt of Materials Printed/Typed Name		Signature		Month	Day	Year
Date						
19. Discrepancy Indication Space <b>Note change in manifest document #</b>						
20. Designated Facility Owner or Operator: Certification of receipt and handling of hazardous materials covered by this manifest except as noted in Item 19. Printed/Typed Name <b>Eileen Jenkinson</b>		Signature <b>Eileen Jenkinson</b>		Month	Day	Year
<b>10 31 25 19 11</b>						



MISSOURI DEPARTMENT OF NATURAL RESOURCES  
P.O. BOX 176                  4) 751-3176  
JEFFERSON CITY,                MO 65102

## GENERATOR'S HAZARDOUS WASTE REPORT SUMMARY SHEET

	PART II OFFICE USE ONLY
--	----------------------------

NOTE ► PLEASE READ INSTRUCTIONS AND EITHER PRINT OR TYPE

Entries made on this page must summarize the total amount of waste transported off-site to an individual facility during the specified quarter. Separate sheets must be completed for each facility utilized.

### SECTION I - REPORT IDENTIFICATION

1. FOR THE PERIOD ENDING (CHECK ONE & FILL IN YEAR)

- 9-30- \_\_\_\_ (YEAR)       12-31- \_\_\_\_ (YEAR)  
 3-31- 91 (YEAR)       6-30- \_\_\_\_ (YEAR)

2. PAGE

3 OF 4

3. GENERATOR'S MISSOURI

I.D. NUMBER  
0 0 1 5 6 2

### SECTION II - FACILITY IDENTIFICATION

4. FACILITY NAME (NAME OF OFF-SITE LOCATION WHERE WASTE WAS DELIVERED)

**U. S. POLLUTION CONTROL, INC.**

5. FACILITY'S EPA I.D. NUMBER

0 K D 0 6 5 4 3 8 3 7 6

6. FACILITY SITE ADDRESS

ROUTE #2, BOX 170

7. FACILITY'S MISSOURI I.D. NUMBER

CITY

WAYNOKA

STATE

OK

ZIP CODE

73860

### SECTION III - WASTE IDENTIFICATION

LINE	DESCRIPTION OF WASTE	DOT HAZARD CODE	10. EPA HAZARDOUS WASTE NUMBER	11. PREVIOUSLY REPORTED (SEE INST.)	12. TOTAL AMOUNT OF WASTE	13. UNIT OF MEAS.	14. SPECIFIC GRAVITY	15. HANDLING CODE
1	RQ HAZARDOUS SOLID N.O.S. ORM-E NA9189	1 3	K 0 8 8		498,060	P	.	D 8.0
2			.....				.	..
3			.....				.	..
4			.....				.	..
5			.....				.	..
6			.....				.	..
7			.....				.	..
8			.....				.	..
9			.....				.	..
10			.....				.	..

### SECTION IV - TRANSPORTATION SERVICES UTILIZED

16. COMPANY NAME	17. MISSOURI I.D. NO.	18. USEPA I.D. NUMBER
a U.S. POLLUTION CONTROL, INC.	H - 1 0 2 4	0 K D 9 8 1 5 1 4 4 7 4
b	H - - - - -	- - - - - - - - - - -
c	H - - - - -	- - - - - - - - - - -
d	H - - - - -	- - - - - - - - - - -

### SECTION V - COMMENTS

19.

MATERIAL IS BEING LANDILLED AS DESCRIBED IN  
MODNR WASTE HANDLING CODE - D80 AND  
RCRA WASTE HANDLING CODE - D81

INSTRUCTIONS FOR THE COMPLETION OF THIS FORM ARE ON A SEPARATE SHEET.

THIS DOCUMENT MUST BE USED FOR ALL MISSOURI-DESTINED SHIPMENTS.

MISSOURI DEPARTMENT OF NATURAL RESOURCES

Division of Environmental Quality  
Waste Management Program  
P.O. Box 176 Jefferson City, Missouri 65102  
314-751-3176

Order # 11589

**EMERGENCY RESPONSE  
U.S. COAST GUARD  
1-800-424-8802  
CHEM TREC  
1-800-424-9300**  
**DEPT. OF NATURAL RESOURCES  
314-634-2436**

## **HAZARDOUS WASTE MANIFEST**

Please print or type (Form designed for use on elite (12-pitch) typewriter.)

Form Approved. OMB No. 2050-0039. Expires 9-30-91.

**THIS COPY MUST BE SENT BACK TO THE GENERATOR BY THE DESIGNATED  
FEDERAL CONTRACTOR OR SUBCONTRACTOR**

INSTRUCTIONS FOR THE COMPLETION OF THIS FORM ARE ON A SEPARATE SHEET.

THIS DOCUMENT MUST BE USED FOR ALL MISSOURI-DESTINED SHIPMENTS.

### MISSOURI DEPARTMENT OF NATURAL RESOURCES

Division of Environmental Quality  
Waste Management Program  
P.O. Box 176 Jefferson City, Missouri 65102  
314-751-3176

## HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12-pitch) typewriter.)

EMERGENCY RESPONSE  
U.S. COAST GUARD  
1-600-424-6802  
CHEM TREC  
1-800-424-9300  
DEPT. OF NATURAL RESOURCES  
314-634-2435

Order # 11593

Form Approved. OMB No. 2050-0039. Expires 9-30-91

<b>UNIFORM HAZARDOUS WASTE MANIFEST</b>		1. Generator's US EPA ID No. <b>M 0 D 0 9 3 7 5 0 9 6 6 0 0 3 1 3</b>	Manifest Document No.	2. Page <b>4</b> of <b>4</b>	Information in the shaded areas is required by State law.
3. Generator's Name and Mailing Address <b>Noranda Aluminum, Inc.</b> <b>P.O. Box 70 New Madrid, MO 63869</b>					
4. Generator's Phone ( 314) 643-2361					
5. Transporter 1 Company Name <b>Joe Brown</b>					
6. US EPA ID Number <b>OKD045347093</b>					
7. Transporter 2 Company Name <b>St. Jude Industrial Park</b>					
8. US EPA ID Number					
9. Designated Facility Name and Site Address <b>U.S. Pollution Control, Inc.</b> <b>Lone Mountain Facility</b> <b>Route 2, Box 180A</b> <b>Waynoka, OK 73860</b> <b>OKD065438376</b> <b>(405)697-3236</b>					
10. US EPA ID Number					
11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)					
a.	12. Containers Number	13. Total Quantity	14. Unit Wt/Vol.	I. Waste No.	EPA WASTE CODE
a.	D T XX	39320	P	STATE 0 8 8 N O N E	EPA WASTE CODE
b.	#LOAD 11593 Ticket 1057047	RECEIVED			STATE
c.		MAR 8 1991			EPA WASTE CODE
d.		NORANDA ALUMINUM INC. Environmental Energy Ma			STATE
J. Additional Descriptions for Materials Listed Above <b>SW 39,800</b>					
a.	K. HANDLING CODE (FACILITY USE ONLY) INTERIM	FINAL	COMMENTS		
a.		080	Modur		
c.		1811	RCCR		
d.					
15. Special Handling Instructions and Additional Information <b>Spent Potliner LM90-0905 XXXXXXXXXX</b> <b>USPCI 24 Hour Emergency Number: (800) 877-0454</b> <b>NORANDA Emergency Contact: Dave Hart (314)643-2361</b>					
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations and applicable state regulations. If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method available to me that I can afford.					
Printed/Typed Name <b>DON BACKFISCH</b>		Signature <b>Don Backfisch</b>		Month	Day Year
				03	01 1991
17. Transporter 1 Acknowledgement of Receipt of Materials Printed/Typed Name <b>George Jackson</b>					
Printed/Typed Name <b>George Jackson</b>		Signature <b>George Jackson</b>		Month	Day Year
				03	01 1991
18. Transporter 2 Acknowledgement of Receipt of Materials Printed/Typed Name					
Printed/Typed Name		Signature		Month	Day Year
19. Discrepancy Indication Space <b>91-1375</b>					
20. Designated Facility Owner or Operator. Certification of receipt and handling of hazardous materials covered by this manifest except as noted in Item 19.					
Printed/Typed Name <b>Alan J. Adair</b>		Signature <b>Alan J. Adair</b>		Month	Day Year
				03	01 1991

INSTRUCTIONS FOR THE COMPLETION OF THIS FORM ARE ON A SEPARATE SHEET.

THIS DOCUMENT MUST BE USED FOR ALL MISSOURI-DESTINED SHIPMENTS.

MISSOURI DEPARTMENT OF NATURAL RESOURCES

Division of Environmental Quality

Waste Management Program

P.O. Box 176 Jefferson City, Missouri 65102

314-751-3176

HAZARDOUS WASTE MANIFEST

Order #11591

EMERGENCY RESPONSE  
U.S. COAST GUARD  
1-800-424-8802  
CHEM TREC  
1-800-424-9300  
DEPT. OF NATURAL RESOURCES  
314-634-2436

Form Approved, OMB No. 2050-0039. Expires 9-30-91

Please print or type (Form designed for use on elite (12-pitch) typewriter.)

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. <b>M O D 0 9 3 7 5 0 9 6 6 0 0 3 1 4</b>	Manifest Document No. <b>0 0 1 5 6 2 0 2 9 1</b>	2. Page <b>1</b> of <b>1</b>	Information in the shaded areas is required by State law.
G E N E R A T O R	3. Generator's Name and Mailing Address <b>Noranda Aluminum, Inc.</b> <b>P.O. Box 70 New Madrid, MO 63869</b>	4. Generator's Phone ( <b>314</b> ) <b>643-2361</b>	5. Transporter 1 Company Name <b>JOE Brown</b>	6. US EPA ID Number <b>OKD045347093</b>	A. Missouri Manifest Document Number <b>0 0 1 5 6 2 0 2 9 1</b>
	7. Transporter 2 Company Name	8. US EPA ID Number	9. Designated Facility Name and Site Address <b>U.S. Pollution Control, Inc.</b> <b>Lone Mountain Facility</b> <b>Route 2, Box 180A</b> <b>Waynoka, OK 73860</b>	10. US EPA ID Number <b>OKD065438376</b>	B. G.S.I. (Gen. Site Address) <b>St. Jude Industrial Park</b>
	11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers Number	13. Total Quantity	14. Unit Wt/Vol.	I. Waste No.
	a. <b>RQ Hazardous Solid, N.O.S.</b> <b>ORM-E NA9189 (K088)</b>	<b>D T</b> <b>XXM</b> <b>XXX</b>	<b>41440</b>	<b>P</b>	EPA WASTE CODE <b>K 10 8 8</b> STATE <b>N O N E</b>
	b. <b>LOAD # 1057045</b>	<b>RECEIVED</b>			EPA WASTE CODE STATE
	c. <b>ORDER # 11591</b>	<b>MAR 8 1991</b>			EPA WASTE CODE STATE
	d.				EPA WASTE CODE STATE
	J. Additional Descriptions for Materials Listed Above	K. HANDLING CODE (FACILITY USE ONLY)			COMMENTS
	a. <b>SW 42,620</b>	a. <b>INTERIM</b>	<b>D 8 0</b>	<b>moore</b>	
	b. <b>13Y</b>	b. <b>FINAL</b>	<b>0 8 1</b>	<b>RCRA</b>	
	c.	c.			
	d.	d.			
	15. Special Handling Instructions and Additional Information <b>Spent Potliner LM90-0905 XXXXXXXXXXXXXXXXXXXXXXX</b> <b>USPCI 24 Hour Emergency Number: (800) 877-0454</b> <b>NORANDA Emergency Contact: Dave Hart (314)643-2361</b>				
	16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations and applicable state regulations. If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method available to me that I can afford.				
	Printed/Typed Name <b>DON BACKFISCH</b>	Signature <i>Don Backfisch</i>	Month <b>0</b> Day <b>3</b> Year <b>10 1 9 1</b>	Date	
	17. Transporter 1 Acknowledgement of Receipt of Materials Printed/Typed Name <b>JEFF R LAMB</b>	Signature <i>Jeff R Lamb</i>	Month <b>0</b> Day <b>3</b> Year <b>10 1 9 1</b>	Date	
	18. Transporter 2 Acknowledgement of Receipt of Materials Printed/Typed Name	Signature	Month <b>0</b> Day <b>3</b> Year <b>10 1 9 1</b>	Date	
	19. Discrepancy Indication Space				
	20. Designated Facility Owner or Operator: Certification of receipt and handling of hazardous materials covered by this manifest except as noted in Item 19.				
Printed/Typed Name <b>ALAN J ADAIR</b>	Signature <i>Alan J Adair</i>	Month <b>0</b> Day <b>3</b> Year <b>10 2 9 1</b>	Date		

INSTRUCTIONS FOR THE COMPLETION OF THIS FORM ARE ON A SEPARATE SHEET.  
THIS DOCUMENT MUST BE USED FOR ALL MISSOURI-DESTINED SHIPMENTS.

### MISSOURI DEPARTMENT OF NATURAL RESOURCES

Division of Environmental Quality  
Waste Management Program  
P.O. Box 176 Jefferson City, Missouri 65102  
314-751-3176

Order #11590

EMERGENCY RESPONSE  
U.S. COAST GUARD  
1-800-424-8802  
CHEM TREC  
1-800-424-9300  
DEPT. OF NATURAL RESOURCE  
314-634-2476

### HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12-pitch) typewriter.)

Form Approved. OMB No. 2050-0039. Expires 9-30-91

<b>A UNIFORM HAZARDOUS WASTE MANIFEST</b>		1. Generator's US EPA ID No. <b>M O D 0 9 3 7 5 0 9 6 6 0 0 3 1 5</b>	Manifest Document No. <b>0 0 3 1 5</b>	2. Page <b>1</b> of <b>1</b>	Information in the shaded areas is required by State law.
3. Generator's Name and Mailing Address <b>Noranda Aluminum, Inc.</b> <b>P.O. Box 70 New Madrid, MO 63869</b>					
4. Generator's Phone ( <b>314</b> ) <b>643-2361</b>					
5. Transporter 1 Company Name <b>JOE BROWN</b>					
6. US EPA ID Number <b>10KID04534D093</b>					
7. Transporter 2 Company Name <b>St. Jude Industrial Park</b>					
8. US EPA ID Number <b>                                  </b>					
9. Designated Facility Name and Site Address <b>U.S. Pollution Control, Inc.</b> <b>Lone Mountain Facility</b> <b>Route 2, Box 180A</b> <b>Waynoka, OK 73860</b>					
10. US EPA ID Number <b>10 K D 0 6 5 4 3 8 3 7 6</b>					
11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)					
12. Containers Number      Type      13. Total Quantity      14. Unit Wt/Vol.      I. Waste No.					
a.	<b>RQ Hazardous Solid, N.O.S.</b> <b>ORM-E NA9189 (K088)</b>	<b>RECEIVED</b>	<b>D T</b> <b>XXXX</b>	<b>36740</b>	EPA WASTE CODE <b>K 0 8 8</b> STATE <b>N O N E</b>
b.		<b>MAR 8 1991</b>			EPA WASTE CODE STATE
c.	<b>NORANDA ALUMINUM, INC.</b> Environmental - Energy Mgt.	<b>RECEIVED</b>			EPA WASTE CODE STATE
d.	<b>NORANDA ALUMINUM, INC.</b> Environmental - Energy Mgt.				EPA WASTE CODE STATE
J. Additional Descriptions for Materials Listed Above <b>SW 30,00</b>					
K. HANDLING CODE (FACILITY USE ONLY) INTERIM      FINAL      COMMENTS					
a.	<b>11.5Y</b>	<b>DIBO</b>	<b>MO ONE</b>		
b.		<b>DIBI</b>	<b>RCRA</b>		
c.					
d.					
15. Special Handling Instructions and Additional Information <b>Spent Potliner LM90-0905 XXXXXXXXXXXXXXXXXXXXXXXXXX #11590</b> <b>USPCI 24 Hour Emergency Number: (800) 877-0454</b> <b>NORANDA Emergency Contact: Dave Hart (314)643-2361</b> #105-70-44					
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations and applicable state regulations.					
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method available to me that I can afford.					
Printed/Typed Name <b>DON BACKFISCH</b>		Signature <i>Don Backfisch</i>		Month   Day   Year <b>0 3 0 1 9 1</b>	Date
17. Transporter 1 Acknowledgement of Receipt of Materials Printed/Typed Name <b>Bob Farley</b>					
Signature <i>Bob Farley</i> Month   Day   Year <b>13 0 1 9 1</b>					
18. Transporter 2 Acknowledgement of Receipt of Materials Printed/Typed Name					
Signature      Month   Day   Year <b>                                  </b>					
19. Discrepancy Indication Space <b>91-1371</b>					
20. Designated Facility Owner or Operator. Certification of receipt and handling of hazardous materials covered by this manifest except as noted in Item 19.					
Printed/Typed Name <b>Alan J. Adair</b>		Signature <i>Alan J. Adair</i>		Month   Day   Year <b>13 1 2 9 1</b>	Date

INSTRUCTIONS FOR THE COMPLETION OF THIS FORM ARE ON A SEPARATE SHEET.

THIS DOCUMENT MUST BE USED FOR ALL MISSOURI-DESTINED SHIPMENTS.

MISMOUR DEPARTMENT OF NATURAL RES  
Division of Environmental Quality  
Waste Management Program  
P.O. Box 176 Jefferson City, Missouri 65102  
314-751-3176

ES

Order # 11592

EMERGENCY RESPONSE  
U.S. COAST GUARD  
1-800-424-8802  
CHEM TREC  
1-800-424-9300  
DEPT. OF NATURAL RESOURCES  
314-634-2436

## HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12-pitch) typewriter.)

Form Approved. OMB No. 2050-0039. Expires 9-30-91

<b>UNIFORM HAZARDOUS WASTE MANIFEST</b>		1. Generator's US EPA ID No. <b>M O D 0 9 3 7 5 0 9 6 6 0 0 3 1 6</b>	Manifest Document No. <b>1</b>	2. Page <b>1</b> of <b>1</b>	Information in the shaded areas is required by State law.		
G E N E R A T O R	3. Generator's Name and Mailing Address <b>Noranda Aluminum, Inc.</b> <b>P.O. Box 70 New Madrid, MO 63869</b>	A. Missouri Manifest Document Number <b>0 0 1 5 6 2 0 2 9 3</b>					
	4. Generator's Phone ( 314 ) 643-2361	B. G.S.I. (Gen. Site Address) <b>St. Jude Industrial Park</b>					
	5. Transporter 1 Company Name <b>JOE BROWN</b>	6. US EPA ID Number <b>OKD045347093</b>	C. MO. Trans. ID <b>H1592</b>				
	7. Transporter 2 Company Name	8. US EPA ID Number	D. Transporter's Phone <b>425-670-4931</b>				
	9. Designated Facility Name and Site Address <b>U.S. Pollution Control, Inc.</b> <b>Route 2, Box 180A</b> <b>Waynoka, OK 73860</b>	10. US EPA ID Number <b>OKD065438376</b>	E. MO. Trans. ID				
			F. Transporter's Phone				
			G. State Facility's ID				
			H. Facility's Phone <b>(405)697-3236</b>				
			12. Containers Number <b>0 0 1</b>	Type <b>D T XXN XXX</b>	13. Total Quantity <b>43860</b>	14. Unit Wt/Vol <b>P</b>	I. Waste No. <b>K 1 0 1 8 1 8 N O N E</b>
	a. RQ Hazardous Solid, N.O.S. ORM-E NA9189 (K088)						EPA WASTE CODE <b>STATE</b>
b.	RECEIVED MAR 8 1991					EPA WASTE CODE <b>STATE</b>	
c. NORANDA ALUMINUM, INC. Environmental - Energy Mgt.						EPA WASTE CODE <b>STATE</b>	
d.						EPA WASTE CODE <b>STATE</b>	
J. Additional Descriptions for Materials Listed Above a. SW 41, 900 b. 13Y c. d.		K. HANDLING CODE (FACILITY USE ONLY) INTERIM a. <b>1</b> <b>P 8 0</b> <b>MDNR</b> b. <b>1</b> <b>D 8 1</b> <b>PCPA</b> c. d.	FINAL	COMMENTS			
15. Special Handling Instructions and Additional Information <b>Spent Potliner LM90-0905 Material is non-regulated in Missouri</b> <b>USPCI 24 Hour Emergency Number: (800) 877-0454</b> <b>NORANDA Emergency Contact: Dave Hart (314)643-2361</b>				order No 11592			
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations and applicable state regulations. If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method available to me that I can afford.				Load ticket 1057046			
Printed/Typed Name <b>DON BACKFISCH</b>	Signature <b>Don Backfisch</b>	Month <b>0</b>	Day <b>30</b>	Year <b>1991</b>			
17. Transporter 1 Acknowledgement of Receipt of Materials Printed/Typed Name <b>MARK WRIGHT</b>	Signature <b>Mark Wright</b>	Month <b>0</b>	Day <b>30</b>	Year <b>1991</b>	Date		
18. Transporter 2 Acknowledgement of Receipt of Materials Printed/Typed Name	Signature	Month	Day	Year	Date		
19. Discrepancy Indication Space							
20. Designated Facility Owner or Operator: Certification of receipt and handling of hazardous materials covered by this manifest except as noted in Item 19.		Date					
Printed/Typed Name <b>Alan J. Adair</b>	Signature <b>Alan J. Adair</b>	Month <b>0</b>	Day <b>31</b>	Year <b>1991</b>	Date		

INSTRUCTIONS FOR THE COMPLETION OF THIS FORM ARE ON A SEPARATE SHEET.  
THIS DOCUMENT MUST BE USED FOR ALL MISSOURI-DESTINED SHIPMENTS.

### MISSOURI DEPARTMENT OF NATURAL RESOURCES

Division of Environmental Quality  
Waste Management Program  
P.O. Box 176 Jefferson City, Missouri 65102  
314-751-3176

EMERGENCY RESPONSE  
U.S. COAST GUARD  
1-800-424-8802  
CHEM TREC  
1-800-424-9300  
DEPT. OF NATURAL RESOURCES  
314-534-2436

### HAZARDOUS WASTE MANIFEST

Order # 11594

Form Approved. OMB No. 2050-0039. Expires 9-30-91

<b>UNIFORM HAZARDOUS WASTE MANIFEST</b>		1. Generator's US EPA ID No. <b>M O D 0 9 3 7 5 0 9 6 6 0 0 3 1 7</b>	Manifest Document No. <b>0 0 1 1 5 6 2 0 2 9 4</b>	2. Page <b>1</b> of <b>1</b>	Information in the shaded areas is required by State law.
G E N E R A T O R	3. Generator's Name and Mailing Address  <b>Noranda Aluminum, Inc.</b> <b>P.O. Box 70 New Madrid, MO 63869</b>	A. Missouri Manifest Document Number <b>0 0 1 1 5 6 2 0 2 9 4</b>			
	4. Generator's Phone ( <b>314</b> ) <b>643-2361</b>	B. G.S.I. (Gen. Site Address) <b>St. Jude Industrial Park</b>			
	5. Transporter 1 Company Name  <b>JOE BROWN</b>	C. MO. Trans. ID <b>H1572</b>			
	6. US EPA ID Number <b>OKD045347093</b>	D. Transporter's Phone <b>405-670-4431</b>			
	7. Transporter 2 Company Name	E. MO. Trans. ID			
	8. US EPA ID Number	F. Transporter's Phone			
	9. Designated Facility Name and Site Address  <b>U.S. Pollution Control, Inc.</b> <b>Route 2, Box 180A</b> <b>Waynoka, OK 73860</b>	G. State Facility's ID			
	10. US EPA ID Number <b>OKD065438376</b>	H. Facility's Phone <b>(405)697-3236</b>			
	11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)  <b>RQ Hazardous Solid, N.O.S.</b> <b>ORM-E NA9189 (K088)</b>	12. Containers Number <b>0 0 1</b>	13. Total Quantity <b>36200</b>	14. Unit Wt/Vol. <b>P</b>	I. Waste No.  <b>K 0 8 8</b> <b>N O N E</b>
	a. <b>RECEIVED</b>  <b>MAR 8 1991</b>	EPA WASTE CODE <b>X X X X</b>			
b.	STATE				
c. <b>NORANDA ALUMINUM, INC.</b> <b>Environmental - Energy Mat.</b>	EPA WASTE CODE <b>X X X X</b>				
d.	STATE				
J. Additional Descriptions for Materials Listed Above  <b>SW 35,000</b> <b>11Y</b>	K. HANDLING CODE (FACILITY USE ONLY)  <b>INTERIM</b> <b>FINAL</b>	COMMENTS  <b>D 8 0</b> <b>no DNR</b> <b>D 8 1</b> <b>RCRA</b>			
a.	a.	a.	a.	a.	
b.	b.	b.	b.	b.	
c.	c.	c.	c.	c.	
d.	d.	d.	d.	d.	
15. Special Handling Instructions and Additional Information  <b>Spent Potliner LM90-0905</b> <del>xxxxxxxxxxxxxxxxxxxxxx</del> <b>USPCI 24 Hour Emergency Number: (800) 877-0454</b> <b>NORANDA Emergency Contact: Dave Hart (314)643-2361</b>	Ld to 1037048 Order # 11594				
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations and applicable state regulations. If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method available to me that I can afford.					
Printed/Typed Name <b>DON BACKFISCH</b>	Signature <b>Don B. Backfisch</b>				Month <b>0 3</b> Day <b>0 1</b> Year <b>9 1</b>
17. Transporter 1 Acknowledgement of Receipt of Materials  Printed/Typed Name <b>J.R. Sober</b>	Signature <b>J.R. Sober</b>				Month <b>0 3</b> Day <b>0 1</b> Year <b>9 1</b>
18. Transporter 2 Acknowledgement of Receipt of Materials  Printed/Typed Name	Signature				Date
19. Discrepancy Indication Space					
20. Designated Facility Owner or Operator: Certification of receipt and handling of hazardous materials covered by this manifest except as noted in Item 19.					Date
Printed/Typed Name <b>Alan J. Adair</b>	Signature <b>Alan J. Adair</b>				Month <b>0 3</b> Day <b>0 1</b> Year <b>9 1</b>

INSTRUCTIONS FOR THE COMPLETION OF THIS FORM ARE ON A SEPARATE SHEET.

MISSOURI DEPARTMENT OF NATURAL RESOURCES

## Division of Environmental Quality

#### **Waste Management Program**

P.O. Box 176 Jefferson City, Missouri 65102

314-751-3176

## **HAZARDOUS WASTE MANIFEST**

Please print or type (Form designed for use on elite (12-pitch) typewriter.)

<b>UNIFORM HAZARDOUS WASTE MANIFEST</b>		1. Generator's US EPA ID No. <b>M O D 0 9 3 7 5 0 9 6 6 0 0 3 1 8</b>	Manifest Document No.	2. Page <b>1</b> of <b>1</b>	Information in the shaded areas is required by State law.				
3. Generator's Name and Mailing Address <b>Noranda Aluminum, Inc.</b> <b>P.O. Box 70</b> <b>New Madrid, MO 63869</b>									
4. Generator's Phone ( <b>314</b> ) 643-2361									
5. Transporter 1 Company Name      6. US EPA ID Number <b>U.S. Pollution Control</b> <b>b K D 9 8 1 5 1 4 4 4 4</b>									
7. Transporter 2 Company Name      8. US EPA ID Number [Redacted]									
9. Designated Facility Name and Site Address      10. US EPA ID Number <b>U.S. Pollution Control, Inc.</b> <b>Route 2, Box 4804/7022</b> <b>Waynoka, OK 73860-9620</b> <b>Lone Mountain Facility</b> <b>10 K D 0 6 5 4 3 8 3 7 6</b>									
11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)						12. Containers	13. Total Quantity	14. Unit Wt/Vol.	I. Waste No.
a.	RQ Hazardous Solid, N.O.S. ORM-E NA9189 (K088)	Number <b>0 0 1</b>	Type <b>C M XXX</b>	<b>31580</b>	P	EPA WASTE CODE <b>K 0 8 . 8</b> STATE <b>N O N E</b>			
b.						EPA WASTE CODE [Redacted]			
c.						EPA WASTE CODE [Redacted]			
d.	NORANDA ALUMINUM, INC. Environmental - Energy Mat.					EPA WASTE CODE [Redacted]			
J. Additional Descriptions for Materials Listed Above						K. HANDLING CODE (FACILITY USE ONLY)			
a.	<b>SW 28,800</b>	a.	INTERIM	FINAL	COMMENTS <b>D 8 0</b> <b>MO DUR</b>				
b.	<b>9 Y</b>	b.			<b>0 8 1</b> <b>RCRS</b>				
c.		c.							
d.		d.							
15. Special Handling Instructions and Additional Information <b>Spent Potliner LM90-0905</b> <b>XXXXXXXXXXXXXX</b> <b>USPCI 24 Hour Emergency Number: (800) 877-0454</b> <b>NORANDA Emergency Contact: Dave Hart (314)643-2361</b>									
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations and applicable state regulations.									
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method available to me that I can afford.									
Printed/Typed Name <b>DON BACKFISCH</b>			Signature <i>Don Backfisch by mj</i>			Month	Day	Year	
17. Transporter 1 Acknowledgement of Receipt of Materials									Date
Printed/Typed Name <i>G B Leron</i>			Signature <i>C B Leron</i>			Month	Day	Year	
18. Transporter 2 Acknowledgement of Receipt of Materials									Date
Printed/Typed Name			Signature			Month	Day	Year	
19. Discrepancy Indication Space									
20. Designated Facility Owner or Operator: Certification of receipt and handling of hazardous materials covered by this manifest except as noted in Item 19.									Date <i>9/15/94</i>
Printed/Typed Name <i>Hillie Blodawik</i>			Signature <i>Hillie Blodawik</i>			Month	Day	Year <i>9/15/94</i>	

MISSOURI DNR FINAL COPY — PART 1

THE CIRCUIT MUST BE CUT BACK TO THE DESIGNATED POINTS IN ORDER TO TEST THE GENERATOR.

INSTRUCTIONS FOR THE COMPLETION OF THIS FORM ARE ON A SEPARATE SHEET.

THIS DOCUMENT MUST BE USED FOR ALL MISSOURI-DESTINED SHIPMENTS.

# MISSOURI DEPARTMENT OF NATURAL RESOURCES

Division of Environmental Quality

Waste Management Program

P.O. Box 176 Jefferson City, Missouri 65102

314-751-3176

EMERGENCY RESPONSE  
U.S. COAST GUARD  
1-800-424-8602  
CHEM TREC  
1-800-424-9300  
DEPT. OF NATURAL RESOURCES  
314-634-2436

## HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12-pitch) typewriter.)

12156

Form Approved. OMB No. 2050-0039. Expires 9-30-91

<b>A UNIFORM HAZARDOUS WASTE MANIFEST</b>		1. Generator's US EPA ID No. <b>M, O, D, 0, 9, 3, 7, 5, 0, 9, 6, 6   0, 0, 3, 1, 9</b>	Manifest Document No. <b>0, 0, 1, 5, 6, 2   0, 2, 9, 6</b>	2. Page <b>1</b> of <b>1</b>	Information in the shaded areas is required by State law.																
3. Generator's Name and Mailing Address <b>Noranda Aluminum, Inc. P.O. Box 70 New Madrid, MO 63869</b>		A. Missouri Manifest Document Number <b>0, 0, 1, 5, 6, 2   0, 2, 9, 6</b>																			
4. Generator's Phone ( 314 ) 643-2361		B. G.S.I. (Gen. Site Address) <b>St. Jude Industrial Park</b>																			
5. Transporter 1 Company Name <b>U.S. Pollution Control Inc</b>		6. US EPA ID Number <b>OKD981514474</b>	C. MO. Trans. ID <b>OK2004</b>																		
7. Transporter 2 Company Name		8. US EPA ID Number <b>OKD065438376</b>	D. Transporter's Phone <b>405-324-5052</b>																		
9. Designated Facility Name and Site Address <b>U.S. Pollution Control, Inc. Lone Mountain Facility Route 2, Box 180A 170 (S) Waynoka, OK 73860-9622 (S)</b>		10. US EPA ID Number <b>OKD065438376</b>	E. MO. Trans. ID <b>(405)697-3236</b>																		
11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)		12. Containers Number <b>0, 0, 1</b>	Type <b>CM XXX</b>	13. Total Quantity <b>31, 46, 0</b>	14. Unit Wt/Vol. <b>P</b>	I. Waste No. <b>K, 0, 8, 8 STATE N, O, N, E</b>															
<b>G E N E R A T O R</b>	a. RQ Hazardous Solid, N.O.S. ORM-E NA9189 (K088)					EPA WASTE CODE <b>K, 0, 8, 8 STATE N, O, N, E</b>															
	b.					EPA WASTE CODE <b>STATE</b>															
	c.					EPA WASTE CODE <b>STATE</b>															
	d. <b>RECEIVED</b> <b>MAR 20 1991</b> <b>NORANDA ALUMINUM, INC. Environmental - Energy Mgt.</b>					EPA WASTE CODE <b>STATE</b>															
J. Additional Descriptions for Materials Listed Above <b>10y SW 30120</b>		K. HANDLING CODE (FACILITY USE ONLY) <table border="1"><tr><td>INTERIM</td><td>FINAL</td><td>COMMENTS</td></tr><tr><td>a.    </td><td><b>D 8 0</b></td><td><b>MDNR</b></td></tr><tr><td>b.    </td><td><b>D 8 1</b></td><td><b>RCRA</b></td></tr><tr><td>c.    </td><td></td><td></td></tr><tr><td>d.    </td><td></td><td></td></tr></table>					INTERIM	FINAL	COMMENTS	a.	<b>D 8 0</b>	<b>MDNR</b>	b.	<b>D 8 1</b>	<b>RCRA</b>	c.			d.		
INTERIM	FINAL	COMMENTS																			
a.	<b>D 8 0</b>	<b>MDNR</b>																			
b.	<b>D 8 1</b>	<b>RCRA</b>																			
c.																					
d.																					
15. Special Handling Instructions and Additional Information <b>Spent Potliner LM90-0905 XXXXXXXXXXXXXXXXX USPCI 24 Hour Emergency Number: (800) 877-0454 NORANDA Emergency Contact: Dave Hart (314)643-2361</b>																					
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations and applicable state regulations. If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method available to me that I can afford.																					
Printed/Typed Name <b>DON BACKFISCH</b>		Signature <i>Don Backfisch, Jr., Jr.</i>		Month <b>3</b>	Day <b>11</b>	Year <b>1991</b>															
17. Transporter 1 Acknowledgement of Receipt of Materials Printed/Typed Name <b>Doug Betterton</b>		Signature <i>Doug Betterton</i>		Month <b>3</b>	Day <b>11</b>	Year <b>1991</b>															
18. Transporter 2 Acknowledgement of Receipt of Materials Printed/Typed Name		Signature		Month	Day	Year															
19. Discrepancy Indication Space																					
20. Designated Facility Owner or Operator: Certification of receipt and handling of hazardous materials covered by this manifest except as noted in Item 19.																					
Printed/Typed Name <b>Lee Ann Stine</b>		Signature <i>Lee Ann Stine</i>		Month <b>3</b>	Day <b>11</b>	Year <b>1991</b>															

INSTRUCTIONS FOR THE COMPLETION OF THIS FORM ARE ON A SEPARATE SHEET.

THIS DOCUMENT MUST BE USED FOR ALL MISSOURI-DESTINED SHIPMENTS.

# MISSOURI DEPARTMENT OF NATURAL RESOURCES

Division of Environmental Quality

Waste Management Program

P.O. Box 176 Jefferson City, Missouri 65102

314-751-3176

EMERGENCY RESPONSE  
U.S. COAST GUARD  
300-424-8802  
CHEM TREC  
1-800-424-9300  
DEPT. OF NATURAL RESOURCE  
314-634-2435

## HAZARDOUS WASTE MANIFEST

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form Approved. OMB No 2050-0039. Expires 9-30-91

UNIFORM HAZARDOUS WASTE MANIFEST		Generator's US EPA ID No. <b>M O D O 9 3 7 5 0 9 6 6</b>	Manifest Document No. <b>0 0 3 2 0</b>	2. Page <b>1</b> of _____	Information in the shaded areas is required by State law.	
3. Generator's Name and Mailing Address <b>Noranda Aluminum, Inc.</b> P.O. Box 70 New Madrid, MO 63869 314 643-2361				4. Missouri Manifest Document Number <b>0 2 9 7</b>		
4. Generator's Phone ( )		6. US EPA ID Number <b>OK 0 9 8 1 5 7 4 7 4</b>		C. MO. Trans. ID <b>OK 2004 11</b>		
5. Transporter 1 Company Name <b>U.S. Pollution Control</b>		8. US EPA ID Number		D. Transporter's Phone <b>HOS-324-5007</b>		
7. Transporter 2 Company Name				E. MO. Trans. ID		
9. Designated Facility Name and Site Address <b>U.S. Pollution Control, Inc.</b> Route 2, Box 180A 170 Waynoka, OK 73860-4622		10. US EPA ID Number <b>Lone Mountain Facility</b> <b>O K D 0 6 5 4 3 8 3 7 6</b>		F. Transporter's Phone		
				G. State Facility's ID		
				H. Facility (405) 697-3236 3500		
11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)		12. Containers	13. Total Quantity	14. Unit Wt/Mt	I. Waste No.	
a. RQ Hazardous Solid, N.O.S. ORM-E NA9189 (K088)		Number <b>0 0 1</b>	Type <b>XXX</b>	<b>28 760</b>	EPA WASTE CODE <b>8</b> STATE <b>N O O N I E</b>	
b.					EPA WASTE CODE STATE	
c.					EPA WASTE CODE STATE	
d. NORANDA ALUMINUM, INC. Environmental - Energy Mfg.					EPA WASTE CODE STATE	
J. Additional Descriptions for Materials Listed Above <b>Qty SW 28760</b>		K. HANDLING CODE (FACILITY USE ONLY)	COMMENTS			
a.		INTERIM	FINAL	D 8 0      MOONE		
b.		<b>a</b>	<b>D 1 8 1</b>	RCRA		
c.						
d.						
15. Special Handling Instructions and Additional Information <b>Spent Potting Liner 1190-0905 XXXXXXXXXXXXXXXXX</b> <b>USPCI 24 Hour Emergency Number: (800) 877-0454</b> <b>NORANDA Emergency Contact: Dave Hart (314)643-2361</b>						
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations and applicable state regulations. If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method available to me that I can afford.						
Printed/Typed Name <b>DON BACKFISCH</b>		Signature <i>Don Backfisch</i>		Month <b>03</b>	Day <b>11</b>	Year <b>1991</b>
17. Transporter 1 Acknowledgement of Receipt of Materials						Date
Printed/Typed Name <b>Billy C Stephens</b>		Signature <i>Billy C Stephens</i>		Month <b>03</b>	Day <b>11</b>	Year <b>1991</b>
18. Transporter 2 Acknowledgement of Receipt of Materials						Date
Printed/Typed Name		Signature		Month	Day	Year
19. Discrepancy Indication Space <i>Rec'd 16 - date 3-11-91 (rec'd per. from backfisch) 3-12-91 Changed Sect. 13 per conversation with Rhonda at USPCI 4/3/91 91-1569</i>						Date
20. Designated Facility Owner or Operator: Certification of receipt and handling of hazardous materials covered by this manifest except as noted in Item 19.						Date
Printed/Typed Name <b>Lee Ann Stine</b>		Signature <i>Lee Ann Stine</i>		Month <b>03</b>	Day <b>11</b>	Year <b>1991</b>

INSTRUCTIONS FOR THE COMPLETION OF THIS FORM ARE ON A SEPARATE SHEET.

THIS DOCUMENT MUST BE USED FOR ALL MISSOURI-DESTINED SHIPMENTS.

# MISSOURI DEPARTMENT OF NATURAL RESOURCES

Division of Environmental Quality

Waste Management Program

P.O. Box 176 Jefferson City, Missouri 65102

314-751-3176

EMERGENCY RESPONSE  
U.S. COAST GUARD  
1-800-424-8802  
CHEM TREC  
1-800-424-9300  
DEPT. OF NATURAL RESOURCES  
314-534-2436

## HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12-pitch) typewriter.)

12155

Form Approved. OMB No. 2050-0039. Expires 9-30-91

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. <b>M O D 0 9 3 7 5 0 9 6 6   0 0 3   2 1</b>	Manifest Document No. <b>0 0 1 5 6 2   0 2 9 8</b>	2. Page <b>1</b> of <b>1</b>	Information in the shaded areas is required by State law.		
GENERATOR	3. Generator's Name and Mailing Address <b>Noranda Aluminum, Inc. P.O. Box 70 New Madrid, MO 63869</b>	4. Generator's Phone (314) 643-2361	6. US EPA ID Number <b>OKP 981514474</b>	A. Missouri Manifest Document Number <b>0 0 1 5 6 2   0 2 9 8</b>	B. G.S.I. (Gen. Site Address) <b>St. Jude Industrial Park</b>		
	5. Transporter 1 Company Name <b>US PCI</b>	7. Transporter 2 Company Name <b>38</b>	8. US EPA ID Number <b>10 K D 0 6 5 4 3 8 3 7 6</b>	C. MO. Trans. ID <b>OK2004</b>	D. Transporter's Phone <b>405-324-6077</b>		
	9. Designated Facility Name and Site Address <b>U.S. Pollution Control, Inc. Lone Mountain Facility Route 2, Box 100A-170 Waynoka, OK 73860 - 9122</b>	10. US EPA ID Number <b>RECEIVED</b>	11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number) <b>RQ Hazardous Solid, N.O.S. ORM-E NA9189 (K088)</b>	12. Containers Number <b>0, 0, 1</b>	13. Total Quantity <b>XXX 29626</b>	14. Unit Wt/Vol. <b>P N O N E</b>	I. Waste No. <b>K 1 0 1 8 1 8</b>
	a. <b>60 waste</b>						EPA WASTE CODE <b>STATE</b>
	b.						STATE
	c.						EPA WASTE CODE <b>STATE</b>
	d.						EPA WASTE CODE <b>STATE</b>
	J. Additional Descriptions for Materials Listed Above <b>Spent Potliner LM90-0905</b>	<b>SW 31580</b>	K. HANDLING CODE (FACILITY USE ONLY) <b>INTERIM FINAL COMMENTS</b>	<b>D 8 0</b> <b>D 8 1 1</b> <b>RCRA</b>	<b>MO DUE</b>		
	a.	<b>9.54</b>	a.	<b>1 1</b>	<b>RCRA</b>		
	b.		a.	<b>1 1</b>			
c.		c.	<b>1 1</b>				
d.		d.	<b>1 1</b>				
15. Special Handling Instructions and Additional Information <b>Spent Potliner LM90-0905</b> <del>xxxxxxxxxxxxxxxxxxxxxx</del> <b>USPCI 24 Hour Emergency Number: (800) 877-0454</b> <b>NORANDA Emergency Contact: Dave Hart (314)643-2361</b>							
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations and applicable state regulations. If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method available to me that I can afford.							
Printed/Typed Name <b>DON BACKFISCH</b>		Signature <b>Don Backfisch by mij 3-8-91</b>		Month Day Year <b>3 18 91</b>			
17. Transporter 1 Acknowledgement of Receipt of Materials Printed/Typed Name <b>Jim Collier</b>		Signature <b>Jim Collier</b>		Month Day Year <b>10 31 91</b>			
18. Transporter 2 Acknowledgement of Receipt of Materials Printed/Typed Name		Signature		Date			
19. Discrepancy Indication Space				Month Day Year			
20. Designated Facility Owner or Operator. Certification of receipt and handling of hazardous materials covered by this manifest except as noted in Item 19. Printed/Typed Name <b>Sheila Finley</b>		Signature <b>Sheila Finley</b>		Date <b>91-1591 11/30/91</b>			

INSTRUCTIONS FOR THE COMPLETION OF THIS FORM ARE ON A SEPARATE SHEET.

THIS DOCUMENT MUST BE USED FOR ALL MISSOURI-DESTINED SHIPMENTS.

### MISSOURI DEPARTMENT OF NATURAL RESOURCES

Division of Environmental Quality

Waste Management Program

P.O. Box 176 Jefferson City, Missouri 65102

314-751-3176

Order # 12154

EMERGENCY RESPONSE  
U.S. COAST GUARD  
1-800-424-8802  
CHEM TREC  
1-800-424-9300  
DEPT. OF NATURAL RESOURCES  
314-534-2436

## HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12-pitch) typewriter.)

Form Approved. OMB No. 2050-0039. Expires 9-30-91

<b>UNIFORM HAZARDOUS WASTE MANIFEST</b>		1. Generator's US EPA ID No. <b>M O D 0 9 3 7 5 0 9 6 6   0 0 3 2 2</b>	Manifest Document No. <b>0 0 1 1 5 6 2   0 2 9 9</b>	2. Page <b>1</b> of <b>1</b> Information in the shaded areas is required by State law.	
A G E N E R A T O R  T R A N S P O R T  F A C I L I T Y	3. Generator's Name and Mailing Address <b>Noranda Aluminum, Inc. P.O. Box 70 New Madrid, MO 63869</b>	4. Generator's Phone (314) 643-2361	5. Transporter 1 Company Name <b>US PCI</b>	6. US EPA ID Number <b>OKD981514474</b>	
	7. Transporter 2 Company Name	8. US EPA ID Number	9. Designated Facility Name and Site Address <b>U.S. Pollution Control, Inc. Route 2, Box 180A 170 (FS) Waynoka, OK 73860 - 9622 (FS)</b>	10. US EPA ID Number <b>OKD065438376</b>	
	11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers Number	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
	a. RQ Hazardous Solid, N.O.S. ORM-E NA9189 (K088)	0 0 1 XXXX	3 2 3 5 C	P	EPA WASTE CODE <b>K 0 8 8</b> STATE <b>N O N E</b>
	b.				EPA WASTE CODE STATE
	c.				EPA WASTE CODE STATE
	d.				EPA WASTE CODE STATE
	J. Additional Descriptions for Materials Listed Above	K. HANDLING CODE (FACILITY USE ONLY) INTERIM	FINAL	COMMENTS	
	a. SW 31,820	a.	0 8 0	NO DMR RCRA	
b. 9.5%	b.	0 8 1			
c.	c.				
d.	d.				
15. Special Handling Instructions and Additional Information <b>Spent Potliner LM90-0905</b>					
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations and applicable state regulations. If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method available to me that I can afford.					
Printed/Typed Name <b>DON BACKFISCH</b>	Signature <b>Don Backfisch, Jr., Jr.</b> Month Day Year <b>10/30/79/1</b>				
17. Transporter 1 Acknowledgement of Receipt of Materials Printed/Typed Name <b>CHARLES HARLEY</b>	Signature <b>Charles Harley</b> Month Day Year <b>10/30/79/1</b>				
18. Transporter 2 Acknowledgement of Receipt of Materials Printed/Typed Name	Signature				
19. Discrepancy Indication Space	<b>91-1495</b>				
20. Designated Facility Owner or Operator: Certification of receipt and handling of hazardous materials covered by this manifest except as noted in Item 19. Printed/Typed Name <b>Alvin J. ADAIR</b>	Signature <b>Alvin J. Adair</b> Date <b>11/30/81/91</b>				

INSTRUCTIONS FOR THE COMPLETION OF THIS FORM ARE ON A SEPARATE SHEET.

THIS DOCUMENT MUST BE USED FOR ALL MISSOURI-DESTINED SHIPMENTS.

# MISSOURI DEPARTMENT OF NATURAL RESOURCES

Division of Environmental Quality

Waste Management Program

P.O. Box 176 Jefferson City, Missouri 65102  
314-751-3176

EMERGENCY RESPONSE  
U.S. COAST GUARD  
1-800-424-8802  
CHEM TREC  
1-800-424-9300  
DEPT. OF NATURAL RESOURCES  
314-634-2436

## HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12-pitch) typewriter.)

15142

Form Approved. OMB No. 2050-0039. Expires 9-30-91

### UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No.

M O D 0 9 3 7 5 0 9 6 6 0 0 3 , 2 3

Manifest Document No.

0 0 3 , 2 3

2. Page

1 of 1

Information in the shaded areas is required by State law.

3. Generator's Name and Mailing Address

Noranda Aluminum, Inc.

P.O. Box 70 New Madrid, MO 63869

4. Generator's Phone (314) 643-2361

5. Transporter 1 Company Name

USPC I (85)

6. US EPA ID Number

OKD981514474

7. Transporter 2 Company Name

8. US EPA ID Number

9. Designated Facility Name and Site Address

U.S. Pollution Control, Inc.

Route 2, Box 180A (85)  
Waynoka, OK 73860 - 9622 (85)

Lone Mountain Facility

10. US EPA ID Number

OKD065438376

11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)

a. RQ Hazardous Solid, N.O.S.  
ORM-E NA9189 (K088)

12. Containers Number	Type	13. Total Quantity	14. Unit Wt/Vol.	I. Waste No.
0 0 1	C M EXX	25540	P	EPA WASTE CODE K 0 8 8 STATE NATION E
				EPA WASTE CODE
				STATE
				EPA WASTE CODE
				STATE
				EPA WASTE CODE
				STATE

RECEIVED

APR 3 1991

NORANDA ALUMINUM, INC.  
Environmental - Energy Mgt.

J. Additional Descriptions for Materials Listed Above

- a. LM90-0905 SW 26,380  
b. 8Y

K. HANDLING CODE (FACILITY USE ONLY)	INTERIM	FINAL	COMMENTS
a.		0 8 0	MOONIE
b.	α	0 8 1	RCEA
c.			
d.			

15. Special Handling Instructions and Additional Information

Spent Potliner LM90-0905 ~~xxxxxxxxxxxxxx~~ loaded in Missouri

USPCI 24 Hour Emergency Number: (800) 877-0454

NORANDA Emergency Contact: Dave Hart (314)643-2361

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations and applicable state regulations. If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method available to me that I can afford.

Printed/Typed Name

DON BACKFISCH

Signature

Month Day Year

10.31.91

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name

George Curran

Signature

Date

Month Day Year

10.31.91

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name

Signature

Date

Month Day Year

10.31.91

19. Discrepancy Indication Space

20. Designated Facility Owner or Operator Certification of receipt and handling of hazardous materials covered by this manifest except as noted in Item 19.

Printed/Typed Name

Lee Ann Stine

Signature

Month Day Year

10.31.91

INSTRUCTIONS FOR THE COMPLETION OF THIS FORM ARE ON A SEPARATE SHEET.

THIS DOCUMENT MUST BE USED FOR ALL MISSOURI-DESTINED SHIPMENTS.

### MISSOURI DEPARTMENT OF NATURAL RESOURCES

Division of Environmental Quality

Waste Management Program

P.O. Box 176 Jefferson City, Missouri 65102

314-751-3176

EMERGENCY RESPONSE  
U.S. COAST GUARD  
1-203-424-8802  
CHEM TREC  
1-800-424-9300  
DEPT. OF NATURAL RESOURCE  
314-534-2476

## HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12-pitch) typewriter.)

12164

Form Approved. OMB No. 2050-0039. Expires 9-30-91

A  GENERATOR  G E N E R A T O R	UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No.	Manifest Document No.	2. Page of	Information in the shaded areas is required by State law.		
			M O D 0 9 3 7 5 0 9 6 6 0 0 3 2 5		1			
	3. Generator's Name and Mailing Address		Noranda Aluminum, Inc. P.O. Box 70 New Madrid, MO 63869					
	4. Generator's Phone (314) 643-2361		6. US EPA ID Number 10 K D 9 8 1 5 1 4 4 7 4					
	5. Transporter 1 Company Name U.S. Pollution Control		8. US EPA ID Number 10 K D 0 6 5 4 3 8 3 7 6					
	7. Transporter 2 Company Name		10. US EPA ID Number Lone Mountain Facility					
	9. Designated Facility Name and Site Address U.S. Pollution Control, Inc. Route 2, Box 100A 170 Waynoka, OK 73860 - 9622		11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number) RQ Hazardous Solid, N.O.S. ORM-E NA9189 (K088)					
	12. Containers		Number	Type	13. Total Quantity	14. Unit Weight	I. Waste No.	
			0 0 1	C M 2 1 2 8 0			EPA WASTE CODE STATE 0 8 8 N O N E	
	c.						STATE	
	d.						EPA WASTE CODE STATE	
	15. Special Handling Instructions and Additional Information Spent Potliner LM90-0905 USPCI 24 Hour Emergency Number: (800) 877-0454 NORANDA Emergency Contact: (314) 643-2361		RECEIVED MAR 21 1991					
	J. Additional Descriptions for Materials Listed Above Environmental Protection Agency		K. HANDLING CODE (FACILITY USE ONLY) INTERIM FINAL COMMENTS					
	a.		a.		0 8 0	NO DMR		
	b.		b.		0 8 1 1	RCRs		
	c.		c.					
	d.		d.					
	16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations and applicable state regulations. If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method available to me that I can afford.							
	Printed/Typed Name DON BACKFISCH		Signature Don Backfisch Month Day Year 10/31/91					
17. Transporter 1 Acknowledgement of Receipt of Materials Printed/Typed Name CHARLES HARLEY		Signature Charles Harley Date Month Day Year 10/31/91						
18. Transporter 2 Acknowledgement of Receipt of Materials Printed/Typed Name		Signature Month Day Year						
19. Discrepancy Indication Space								
20. Designated Facility Owner or Operator: Certification of receipt and handling of hazardous materials covered by this manifest except as noted in Item 19. Printed/Typed Name Lee Ann Stine		Signature Lee Ann Stine Date Month Day Year 10/31/91						

INSTRUCTIONS FOR THE COMPLETION OF THIS FORM ARE ON A SEPARATE SHEET.

THIS DOCUMENT MUST BE USED FOR ALL MISSOURI-DESTINED SHIPMENTS.

### MISSOURI DEPARTMENT OF NATURAL RESOURCES

Division of Environmental Quality

Waste Management Program

P.O. Box 176 Jefferson City, Missouri 65102  
314-751-3176

EMERGENCY RESPONSE  
U.S. COAST GUARD  
1-800-424-8802  
CHEM TREC  
1-800-424-9300  
DEPT. OF NATURAL RESOURCES  
314-634-2436

## HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12-pitch) typewriter.)

<b>UNIFORM HAZARDOUS WASTE MANIFEST</b>		1. Generator's US EPA ID No. <b>M O D 0 9 3 7 5 0 9 6 6 0 0 3 2 6</b>	Manifest Document No. <b>12165</b>	2. Page <b>1</b> of <b>1</b>	Information in the shaded areas is required by State law.
G E N E R A T O R	3. Generator's Name and Mailing Address <b>Noranda Aluminum, Inc.</b> <b>P.O. Box 70</b> <b>New Madrid, MO 63869</b>	4. Generator's Phone (314) 643-2361	6. US EPA ID Number <b>10K.D981514474</b>	A. Missouri Manifest Document Number <b>0 0 - 1 - 5 - 6 - 2 - 0 - 3 0 3</b>	
	5. Transporter 1 Company Name <b>U.S. Pollution Control</b>	7. Transporter 2 Company Name	8. US EPA ID Number	B. G.S.I. (Gen. Site Address) <b>St. Jude Industrial Park</b>	
	9. Designated Facility Name and Site Address <b>U.S. Pollution Control, Inc.</b> <b>Route 2, Box 180A 170 (S)</b> <b>Waynoka, OK 73860 - 9622 (S)</b>	10. US EPA ID Number <b>Lone Mountain Facility</b> <b>10 K D 0 6 5 4 3 8 3 7 6</b>	C. MO. Trans. ID <b>OK2004</b>		
	11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number) <b>RQ Hazardous Solid, N.O.S.</b> <b>ORM-E NA9189 (K088)</b>	12. Containers Number <b>0 0 1</b>	13. Total Quantity <b>C M 3 2 6 0 0</b>	14. Unit Wt/Vol. <b>P N O N E</b>	I. Waste No. <b>EPA WASTE CODE K 0 8 8 STATE P N O N E</b>
					EPA WASTE CODE <b>STATE</b>
					EPA WASTE CODE <b>STATE</b>
					EPA WASTE CODE <b>STATE</b>
					EPA WASTE CODE <b>STATE</b>
	J. Additional Descriptions for Materials Listed Above <b>Sui 34480 10y</b>	K. HANDLING CODE (FACILITY USE ONLY) INTERIM <b>a. 1 1</b>	FINAL <b>b. 1 1</b>	COMMENTS <b>D 8 0 D 8 1</b>	<b>MOPUE RCRA</b>
		c. 1 1	1 1		
	d. 1 1	1 1			
15. Special Handling Instructions and Additional Information <b>Spent Potliner LM90-0905</b> <b>USPCI 24 Hour Emergency Number: (800) 877-0454</b> <b>NORANDA Emergency Contact: (314)643-2361</b>					
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations and applicable state regulations. If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method available to me that I can afford.					
Printed/Typed Name <b>DON BACKFISCH</b>	Signature <b>Don Backfisch</b>				Month Day Year <b>10/31/1991</b>
17. Transporter 1 Acknowledgement of Receipt of Materials Printed/Typed Name <b>Shubert 10/31/91</b>	Signature <b>Shubert 10/31/91</b>				Month Day Year <b>10/31/1991</b>
18. Transporter 2 Acknowledgement of Receipt of Materials Printed/Typed Name	Signature				Month Day Year <b>10/31/91</b>
19. Discrepancy Indication Space					
20. Designated Facility Owner or Operator: Certification of receipt and handling of hazardous materials covered by this manifest except as noted in Item 19. Printed/Typed Name <b>Lee Ann Stine</b>	Signature <b>Lee Ann Stine</b>				Month Day Year <b>10/16/95</b>

INSTRUCTIONS FOR THE COMPLETION OF THIS FORM ARE ON A SEPARATE SHEET.  
THIS DOCUMENT MUST BE USED FOR ALL MISSOURI-DESTINED SHIPMENTS.

MISSOURI DEPARTMENT OF NATURAL RESOURCES  
Division of Environmental Quality  
Waste Management Program  
P.O. Box 176 Jefferson City, Missouri 65102  
314-751-3176

EMERGENCY RESPONSE  
U.S. COAST GUARD  
1-800-424-8802  
CHEM TREC  
1-800-424-9300  
DEPT. OF NATURAL RESOURCE  
114-634-2435

# HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12-pitch) typewriter.)

15149

Form Approved. OMB No. 2050-0039. Expires 9-30-91

<b>UNIFORM HAZARDOUS WASTE MANIFEST</b>		1. Generator's US EPA ID No. <b>M 0 2 0 9 3 7 5 0 9 6 6 0 0 3 2 8</b>	Manifest Document No.	2. Page <b>1</b> of <b>1</b>	Information in the shaded areas is required by State law.
3. Generator's Name and Mailing Address <b>Noranda Aluminum, Inc. P.O. Box 70 New Madrid, MO 63869</b>		A. Missouri Manifest Document Number <b>0 0 1 5 6 2 0 3 0 5</b>			
4. Generator's Phone ( <b>314</b> ) 643-2361		B. G.S.I. (Gen. Site Address) <b>St. Jude Industrial Park</b>			
5. Transporter 1 Company Name <b>USPCF</b>		C. MO. Trans. ID <b>OK2004 11</b>			
7. Transporter 2 Company Name		D. Transporter's Phone <b>405-3295087</b>			
9. Designated Facility Name and Site Address <b>U.S. Pollution Control, Inc. Route 2, Box 480A 10700 Waynoka, OK 73860 - 96.22 (75)</b>		E. MO. Trans. ID <b>3500</b>			
		F. Transporter's Phone <b>(405)697-3236</b>			
11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)		10. US EPA ID Number <b>OK D 0 6 5 4 3 8 3 7 6</b>	12. Containers Number <b>0 0 1 C 1</b>	13. Total Quantity <b>27820</b>	14. Unit Wt/Vol <b>03</b>
G E N E R A T O R	a. RQ Hazardous Solid, N.O.S. ORM-E NA9189 (K088)	EPA WASTE CODE <b>K 0 8 8 P N O N E</b>			
	b.	EPA WASTE CODE <b>STATE</b>			
	c.	EPA WASTE CODE <b>STATE</b>			
	d.	EPA WASTE CODE <b>STATE</b>			
J. Additional Descriptions for Materials Listed Above <b>Spent Potliner LM90-0905 USPCI 24 Hour Emergency Number: (800) 877-0454 NORANDA Emergency Contact: (314)643-2361</b>		K. HANDLING CODE (FACILITY USE ONLY) INTERIM <b>D 8 0</b>	FINAL <b>D 8 1</b>	COMMENTS <b>MO DNR DCEA</b>	
a.	<b>a.</b>	<b>a.</b>	<b>a.</b>		
b.	<b>b.</b>	<b>b.</b>	<b>b.</b>		
c.	<b>c.</b>	<b>c.</b>	<b>c.</b>		
d.	<b>d.</b>	<b>d.</b>	<b>d.</b>		
15. Special Handling Instructions and Additional Information <b>Spent Potliner LM90-0905 USPCI 24 Hour Emergency Number: (800) 877-0454 NORANDA Emergency Contact: (314)643-2361</b>					
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations and applicable state regulations. If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method available to me that I can afford.					
Printed/Typed Name <b>DON BACKFISCH</b>		Signature <b>Don Backfisch</b>			
17. Transporter 1 Acknowledgement of Receipt of Materials Printed/Typed Name <b>J.E. Morrissey</b>		Signature <b>J.E. Morrissey</b>			
18. Transporter 2 Acknowledgement of Receipt of Materials Printed/Typed Name		Signature			
19. Discrepancy Indication Space <b>Changed wt on Item #13 per conversation with Rhonda at USPCI 4/3/91. AS</b>					
20. Designated Facility Owner or Operator: Certification of receipt and handling of hazardous materials covered by this manifest except as noted in Item 19. Printed/Typed Name <b>Lee Ann Stine</b>		Signature <b>Lee Ann Stine</b>			

MISSOURI DNR FINAL COPY — PART 1

This copy must be sent back to the generator by the designated time.



## MISSOURI DEPARTMENT OF NATURAL RESOURCES

P.O. BOX 176 14) 751-3176  
JEFFERSON CITY, SOUTHERN 65102

## GENERATOR'S HAZARDOUS WASTE REPORT SUMMARY SHEET

	PART II OFFICE USE ONLY
--	----------------------------

## NOTE ► PLEASE READ INSTRUCTIONS AND EITHER PRINT OR TYPE

Entries made on this page must summarize the total amount of waste transported off-site to an individual facility during the specified quarter. Separate sheets must be completed for each facility utilized.

## SECTION I: REPORT IDENTIFICATION

1. FOR THE PERIOD ENDING (CHECK ONE & FILL IN YEAR)		2. PAGE	3. GENERATOR'S MISSOURI I.D. NUMBER
<input type="checkbox"/> 9-30- <u>      </u> (YEAR)	<input type="checkbox"/> 12-31- <u>      </u> (YEAR)	<u>4</u> OF <u>4</u>	<u>0 0 1 5 6 2</u>
<input checked="" type="checkbox"/> 3-31- <u>91</u> (YEAR)	<input type="checkbox"/> 6-30- <u>      </u> (YEAR)		

## SECTION II: FACILITY IDENTIFICATION

4. FACILITY NAME (NAME OF OFF-SITE LOCATION WHERE WASTE WAS DELIVERED)

U.S. POLLUTION CONTROL, INC.

5. FACILITY'S EPA I.D. NUMBER

U T D 9 9 1 3 0 1 7 4 8

6. FACILITY SITE ADDRESS

3 MI. EAST AND 7 MI. NORTH OF KNOLLS, EXIT #41 OFF I-80

7. FACILITY'S MISSOURI I.D. NUMBER

CITY <b>CLIVE</b>	STATE <b>UT</b>	ZIP CODE
----------------------	--------------------	----------

## SECTION III: WASTE IDENTIFICATION

LINE	8 DESCRIPTION OF WASTE	9. DOT HAZARD CODE	10. EPA HAZARDOUS WASTE NUMBER	11. PREVIOUSLY REPORTED (SEE INST.)	12. TOTAL AMOUNT OF WASTE	13. UNIT OF MEAS.	14. SPECIFIC GRAVITY	15. HANDLING CODE
1	RQ HAZARDOUS SOLID N.O.S. ORM-E NA9189	1 5	K 0 8 8 . . . .		200,760	P	.	D 8 0
2			. . . . . . . .				.	.
3			. . . . . . . .				.	.
4			. . . . . . . .				.	.
5			. . . . . . . .				.	.
6			. . . . . . . .				.	.
7			. . . . . . . .				.	.
8			. . . . . . . .				.	.
9			. . . . . . . .				.	.
10			. . . . . . . .				.	.

## SECTION IV: TRANSPORTATION SERVICES UTILIZED

16. COMPANY NAME	17. MISSOURI ID NO.	18. USEPA I.D. NUMBER
a U. S. POLLUTION CONTROL, INC.	H - - 1 0 2 4	O K D 9 8 1 5 1 4 4 7 4
b UNION PACIFIC RAILROAD	H - - - - -	N E D 0 0 1 7 9 2 9 1 0
c	H - - - - -	-----
d	H - - - - -	-----

## SECTION V: COMMENTS

19. MATERIAL IS BEING LANDFILLED AS DESCRIBED IN  
MODNR WASTE HANDLING CODE - D80 AND  
RCRA WASTE HANDLING CODE - D81

INSTRUCTIONS FOR THE COMPLETION OF THIS FORM ARE ON A SEPARATE SHEET.

THIS DOCUMENT MUST BE USED FOR ALL MISSOURI-DESTINED SHIPMENTS.

## MISSOURI DEPARTMENT OF NATURAL RESOURCES

Division of Environmental Quality

Waste Management Program

P.O. Box 176 Jefferson City, Missouri 65102  
314-751-3176

EMERGENCY RESPONSE  
U.S. COAST GUARD  
1-800-424-8802  
CHEM TREC  
1-800-424-9300  
DEPT. OF NATURAL RESOURCES  
314-634-2436

## HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12-pitch) typewriter.)

Form Approved. OMB No. 2050-0039. Expires 9-30-91

<b>UNIFORM HAZARDOUS WASTE MANIFEST</b>		1. Generator's US EPA ID No. <b>M O D 0 9 3 7 5 0 9 6 6   0 0 3 2 7</b>	Manifest Document No. <b>0 0 1 5 6 2   0 3 0 4</b>	2. Page <b>1</b> of <b>2</b>	Information in the shaded areas is required by State law.
G E N E R A T O R	3. Generator's Name and Mailing Address <b>Noranda Aluminum, Inc. P.O. Box 70 New Madrid, MO 63869</b>	A. Missouri Manifest Document Number <b>0 0 1 5 6 2   0 3 0 4</b>			
	4. Generator's Phone ( <b>314</b> ) 643-2361	B. G.S.I. (Gen. Site Address) <b>St. Jude Industrial Park</b>			
	5. Transporter 1 Company Name <b>U.S. Pollution Control, Inc.</b>	C. MO. Trans. ID <b>H-1024</b>			
	7. Transporter 2 Company Name <b>Union Pacific Railroad</b>	D. Transporter's Phone <b>(405)324-5011</b>			
	9. Designated Facility Name and Site Address <b>U.S. Pollution Control, Inc. Grassy Mountain Facility 3 Mi. East and 7 Mi. North of Knolls Exit #41 off I-80 Clive, UT</b>	E. MO. Trans. ID <b>F. Transporter's Phone (402)271-4400</b>			
	11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number) <b>RQ Hazardous Solid, N.O.S. ORM-E NA9189 (K088)</b>	G. State Facility's ID			
	a.	12. Containers Number <b>0 0 1</b>	13. Type <b>C M</b>	14. Total Quantity <b>3 1 5 0 0</b>	I. Waste No. <b>K 0 8 8 N O N E</b>
	b.				EPA WASTE CODE STATE
	c.				EPA WASTE CODE STATE
	d.				EPA WASTE CODE STATE
<b>RECEIVED</b>					
APR 19 1991					
NORANDA ALUMINUM, INC. Environmental Energy Mgt.					
J. Additional Descriptions for Materials Listed Above					K. HANDLING CODE (FACILITY USE ONLY)
a.	INTERIM <b>D 8 1</b>	FINAL <b>D 8 0</b>	COMMENTS <b>MO OUR RCRA</b>		
b.	<b>a</b>	<b>D 8 1</b>	<b>D 8 1</b>		
c.					
d.					
15. Special Handling Instructions and Additional Information <b>Spent Potliner GM90-3145 USPCI 24 Hour Emergency Number: (800) 877-0454 NORANDA Emergency Contact: (314)643-2361</b>					
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations and applicable state regulations. If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method available to me that I can afford.					
Printed/Typed Name <b>DON BACKFISCH</b>		Signature <b>Don Backfisch</b>			
		Month Day Year <b>10 31 1991</b>			
17. Transporter 1 Acknowledgement of Receipt of Materials					
Printed/Typed Name <b>J. E. Morrison</b>		Signature <b>J. E. Morrison</b>			
		Date Month Day Year <b>03 27 1991</b>			
18. Transporter 2 Acknowledgement of Receipt of Materials					
Printed/Typed Name <b>T. D. MILNER</b>		Signature <b>T. D. Milner</b>			
		Date Month Day Year <b>03 27 1991</b>			
19. Discrepancy Indication Space					
20. Designated Facility Owner or Operator: Certification of receipt and handling of hazardous materials covered by this manifest except as noted in Item 19.					
Printed/Typed Name <b>N. J. Kingsley</b>		Signature <b>N. J. Kingsley</b>			
		Date Month Day Year <b>04 02 1991</b>			

INSTRUCTIONS FOR THE COMPLETION OF THIS FORM ARE ON A SEPARATE SHEET.

THIS DOCUMENT MUST BE USED FOR ALL MISSOURI-DESTINED SHIPMENTS.

## MISSOURI DEPARTMENT OF NATURAL RESOURCES

Division of Environmental Quality

Waste Management Program

P.O. Box 176 Jefferson City, Missouri 65102  
314-751-3176

EMERGENCY RESPONSE  
U.S. COAST GUARD  
1-800-424-8802  
CHEM TREC  
1-800-424-9300  
DEPT. OF NATURAL RESOURCES  
314-634-2436

## HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12-pitch) typewriter.)

Form Approved. OMB No. 2050-0039, Expires 9-30-91

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. <b>M 0 D 0 9 3 7 5 0 9 6 6   0 0 3 2 7</b>	Manifest Document No.	2. Page <b>2</b> of <b>2</b>	Information in the shaded areas is required by State law.
3. Generator's Name and Mailing Address <b>Noranda Aluminum, Inc. P.O. Box 70 New Madrid, MO 63869</b>		6. US EPA ID Number <b>0 K D 9 8 1 5 1 4 4 7 4</b>	A. Missouri Manifest Document Number <b>0 0 1 5 6 2   0 3 0 4</b>		
4. Generator's Phone ( <b>314</b> ) 643-2361		8. US EPA ID Number	B. G.S.I. (Gen. Site Address) <b>St. Jude Industrial Park</b>	C. MO. Trans. ID <b>H-1024</b>	D. Transporter's Phone <b>(405)324-5011</b>
5. Transporter 1 Company Name <b>Transporter 3 U.S. Pollution Control, Inc.</b>		10. US EPA ID Number <b>U T D 9 9 1 3 0 1 7 4 8</b>	E. MO. Trans. ID	F. Transporter's Phone	G. State Facility's ID
7. Transporter 2 Company Name			H. Facility's Phone <b>(801)595-3900</b>		
9. Designated Facility Name and Site Address <b>U.S. Pollution Control, Inc. Grassy Mountain Facility 3 Mi. East and 7 Mi. North of Knolls Exit #41 off I-80 Clive, UT</b>		11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers Number	13. Total Quantity	14. Unit Wt/Vol.
a.				31500	EPA WASTE CODE STATE
b.					EPA WASTE CODE STATE
c.					EPA WASTE CODE STATE
d.					EPA WASTE CODE STATE
J. Additional Descriptions for Materials Listed Above		K. HANDLING CODE (FACILITY USE ONLY)			
a.		INTERIM	FINAL	COMMENTS	
b.					
c.					
d.					
15. Special Handling Instructions and Additional Information					
CONTINUATION SHEET - To Identify Third Transporter					
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations and applicable state regulations.					
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method available to me that I can afford.					
Printed/Typed Name <b>Claude McFerrand</b>		Signature 		Month <b>03</b>	Day <b>27</b> Year <b>1991</b>
17. Transporter 1 Acknowledgement of Receipt of Materials					
Printed/Typed Name <b>J. E. Morrison</b>		Signature 		Month <b>03</b>	Day <b>27</b> Year <b>1991</b>
18. Transporter 2 Acknowledgement of Receipt of Materials					
Printed/Typed Name <b>T. D. Milner</b>		Signature 		Month <b>03</b>	Day <b>27</b> Year <b>1991</b>
19. Discrepancy Indication Space					
20. Designated Facility Owner or Operator: Certification of receipt and handling of hazardous materials covered by this manifest except as noted in Item 19.					
Printed/Typed Name		Signature		Month <b>03</b>	Day <b>27</b> Year <b>1991</b>

INSTRUCTIONS FOR THE COMPLETION OF THIS FORM ARE ON A SEPARATE SHEET.

THIS DOCUMENT MUST BE USED FOR ALL MISSOURI-DESTINED SHIPMENTS.

# MISSOURI DEPARTMENT OF NATURAL RESOURCES

Division of Environmental Quality

Waste Management Program

P.O. Box 176 Jefferson City, Missouri 65102

314-751-3176

EMERGENCY RESPONSE  
U.S. COAST GUARD  
1-800-424-8802  
CHEM TREC  
1-800-424-9300  
DEPT. OF NATURAL RESOURCES  
314-634-2436

## HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12-pitch) typewriter.)

Form Approved. OMB No. 2050-0039. Expires 9-30-91

<b>UNIFORM HAZARDOUS WASTE MANIFEST</b>		1. Generator's US EPA ID No. <b>M 0 D 0 9 3 7 5 0 9 6 6   0 0 3 2 9</b>	Manifest Document No.	2. Page <b>1</b> of <b>2</b>	Information in the shaded areas is required by State law.
3. Generator's Name and Mailing Address <b>Noranda Aluminum, Inc. P.O. Box 70 New Madrid, MO 63869</b>		A. Missouri Manifest Document Number <b>0 0 1 5 6 2   0 1 3 0 6</b>			
4. Generator's Phone ( 314 ) 643-2361		B. G.S.I. (Gen. Site Address) <b>St. Jude Industrial Park</b>			
5. Transporter 1 Company Name <b>U.S. Pollution Control, Inc.</b>		6. US EPA ID Number <b>  0 K D 9 8 1 5 1 4 4 7 4</b>	C. MO. Trans. ID <b>H-1024</b>	D. Transporter's Phone <b>(405)324-5011</b>	
7. Transporter 2 Company Name <b>Union Pacific Railroad</b>		8. US EPA ID Number <b>  N E D 0 0 1 7 9 2 9 1 0</b>	E. MO. Trans. ID	F. Transporter's Phone <b>(402)271-4400</b>	
9. Designated Facility Name and Site Address <b>U.S. Pollution Control, Inc. Grassy Mountain Facility 3 Mi. East and 7 Mi. North of Knolls Exit #41 off I-80 Clive, UT</b>		10. US EPA ID Number <b>  U T D 9 9 1 3 0 1 7 4 8</b>	G. State Facility's ID	H. Facility's Phone <b>(801)595-3900</b>	
11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)		12. Containers Number <b>0 0 1</b>	13. Total Quantity <b>C M 3 9 2 4 0</b>	14. Unit Wt/Vol. <b>P N O N E</b>	I. Waste No. <b>EPA WASTE CODE K 0 1 8 8 STATE P N O N E</b>
a.	RQ Hazardous Solid, N.O.S. ORM-E NA9189 (K088)				EPA WASTE CODE <b>STATE</b>
b.					EPA WASTE CODE <b>STATE</b>
c.					EPA WASTE CODE <b>STATE</b>
d.					EPA WASTE CODE <b>STATE</b>
RECEIVED APR 29 1991 NORANDA ALUMINUM, INC. Environmental - Energy Mgt.		K. HANDLING CODE (FACILITY USE ONLY) INTERIM <b>D 8 1</b>	FINAL <b>D 8 1</b>	COMMENTS <b>RCRA MO DUR</b>	
J. Additional Descriptions for Materials Listed Above		a. <b>D 8 1</b>	<b>D 8 1</b>		
a.		b. <b>D 8 1</b>	<b>D 8 1 0</b>	<b>MO DUR</b>	
c.		d. <b>D 8 1</b>	<b>D 8 1</b>	<b>1 1</b>	
15. Special Handling Instructions and Additional Information <b>Spent Potliner GM90-3145 USPCI 24 Hour Emergency Number: (800) 877-0454 NORANDA Emergency Contact: (314)643-2361</b>					
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations and applicable state regulations. If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method available to me that I can afford.					
Printed/Typed Name <b>DON BACKFISCH</b>		Signature <b>Don Backfisch</b> Month Day Year <b>03 27 91</b>			
17. Transporter 1 Acknowledgement of Receipt of Materials Printed/Typed Name <b>George Current</b>		Signature <b>George Current</b> Month Day Year <b>03 27 91</b>			
18. Transporter 2 Acknowledgement of Receipt of Materials Printed/Typed Name <b>T. D. MILNER</b>		Signature <b>T. D. Milner</b> Month Day Year <b>03 27 91</b>			
19. Discrepancy Indication Space					
20. Designated Facility Owner or Operator: Certification of receipt and handling of hazardous materials covered by this manifest except as noted in Item 19. Printed/Typed Name <b>N. A. Kingsley</b> Signature <b>N. A. Kingsley</b> Date <b>04 02 91</b>					

INSTRUCTIONS FOR THE COMPLETION OF THIS FORM ARE ON A SEPARATE SHEET.

THIS DOCUMENT MUST BE USED FOR ALL MISSOURI-DESTINED SHIPMENTS.

MISSOURI DEPARTMENT OF NATURAL RESOURCES  
Division of Environmental Quality  
Waste Management Program  
P.O. Box 176 Jefferson City, Missouri 65102  
314-751-3176

EMERGENCY RESPONSE  
U.S. COAST GUARD  
1-800-424-8802  
CHEM TREC  
1-800-424-9300  
DEPT. OF NATURAL RESOURCES  
314-634-2436

# HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12-pitch) typewriter.)

Form Approved. OMB No 2050-0039. Expires 9-30-91

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. <b>M O D 0 9 3 7 5 0 9 6 6   0 0 3   2   9</b>	Manifest Document No.	2. Page <b>2</b> of <b>2</b>	Information in the shaded areas is required by State law.
GENERATOR	3. Generator's Name and Mailing Address <b>Noranda Aluminum, Inc. P.O. Box 70 New Madrid, MO 63869</b>	6. US EPA ID Number <b>0 K D 9 8 1 5 1 4 4 7 4</b>	A. Missouri Manifest Document Number <b>0 0 1 5 6 2   0 3 0 6</b>		
	4. Generator's Phone ( <b>314</b> ) 643-2361	8. US EPA ID Number	B. G.S.I. (Gen. Site Address) <b>St. Jude Industrial Park</b>		
	5. Transporter Company Name <b>Transporter 3 U.S. Pollution Control, Inc.</b>	10. US EPA ID Number <b>U T D 9 9 1 3 0 1 7 4 8</b>	C. MO. Trans. ID <b>H-1024</b>		
	7. Transporter 2 Company Name		D. Transporter's Phone <b>(405)324-5011</b>		
	9. Designated Facility Name and Site Address <b>U.S.Pollution Control, Inc. Grassy Mountain Facility 3 Mi. East and 7 Mi. North of Knolls Exit #41 off I-80 Clive, UT</b>		E. MO. Trans. ID		
			F. Transporter's Phone		
			G. State Facility's ID		
			H. Facility's Phone <b>(801)595-3900</b>		
	11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers Number	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
	a.				EPA WASTE CODE 
b.				STATE 	
c.				EPA WASTE CODE 	
d.				STATE 	
J. Additional Descriptions for Materials Listed Above	K. HANDLING CODE (FACILITY USE ONLY) INTERIM	FINAL	COMMENTS		
a.					
b.					
c.					
d.					
15. Special Handling Instructions and Additional Information					
<b>CONTINUATION SHEET - To Identify Third Transporter</b>					
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations and applicable state regulations. If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method available to me that I can afford.					
Printed/Typed Name <b>Herschel Bowden</b>		Signature <b>Herschel Bowden</b>		Month Day Year <b>03 27 91</b>	
17. Transporter 1 Acknowledgement of Receipt of Materials Printed/Typed Name <b>GARY HILL</b>		Signature <b>Gary Hill</b>		Date Month Day Year <b>04 08 91</b>	
18. Transporter 2 Acknowledgement of Receipt of Materials Printed/Typed Name <b>T. D. MILNER</b>		Signature <b>T. D. Milner</b>		Date Month Day Year <b>03 27 91</b>	
19. Discrepancy Indication Space					
20. Designated Facility Owner or Operator: Certification of receipt and handling of hazardous materials covered by this manifest except as noted in Item 19. Printed/Typed Name <b>915 3943</b>					

MISSOURI DNR FINAL COPY — PART 1

THIS COPY MUST BE SENT BACK TO THE GENERATOR BY THE DESIGNATED FACILITY THEN TRANSMITTED TO THE DEPARTMENT BY THE GENERATOR.

INSTRUCTIONS FOR THE COMPLETION OF THIS FORM ARE ON A SEPARATE SHEET.  
THIS DOCUMENT MUST BE USED FOR ALL MISSOURI-DESTINED SHIPMENTS.

### MISSOURI DEPARTMENT OF NATURAL RESOURCES

Division of Environmental Quality

Waste Management Program

P.O. Box 176 Jefferson City, Missouri 65102  
314-751-3176

EMERGENCY RESPONSE  
U.S. COAST GUARD  
300-424-8802  
CHEM TREC  
1-800-424-9300  
DEPT. OF NATURAL RESOURCES  
314-634-2436

## HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12-pitch) typewriter.)

Form Approved. OMB No. 2050-0039. Expires 9-30-91

<b>UNIFORM HAZARDOUS WASTE MANIFEST</b>		1. Generator's US EPA ID No. <b>M O D 0 9 3 7 5 0 9 6 6   0 0 3 3 2</b>	Manifest Document No.	2. Page <b>1</b> of <b>2</b>	Information in the shaded areas is required by State law.	
3. Generator's Name and Mailing Address <b>Noranda Aluminum, Inc.</b> <b>P.O. Box 70</b> <b>New Madrid, MO</b> <b>63869</b>		A. Missouri Manifest Document Number <b>0 0 1 5 6 2</b>				
4. Generator's Phone ( <b>314</b> , 643-2361)		B. G.S.I. (Gen. Site Address) <b>St. Jude Industrial Park</b>				
5. Transporter 1 Company Name <b>U.S. Pollution Control, Inc.</b>		6. US EPA ID Number <b>0 K D 9 8 1 5 1 4 4 7 4</b>	C. MO. Trans. ID <b>H-1024</b>			
7. Transporter 2 Company Name <b>Union Pacific Railroad</b>		8. US EPA ID Number <b>N E D 0 0 1 7 9 2 9 1 0</b>	D. Transporter's Phone <b>(405)324-5011</b>			
9. Designated Facility Name and Site Address <b>U.S. Pollution Control, Inc. Grassy Mountain Facility</b> <b>3 Mi. East and 7 Mi. North of Knolls Exit #41 off I-80</b> <b>Clive, UT</b>		10. US EPA ID Number <b>U T D 9 9 1 3 0 1 7 4 8</b>	E. MO. Trans. ID			
11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)		12. Containers Number	13. Total Quantity	14. Unit Wt/Vol.	I. Waste No.	
a.	RQ Hazardous Solid, N.O.S. ORM-E NA9189 (K088)	0 0 1	C M <b>3 3 5 8 0</b>	P	EPA WASTE CODE <b>K 0 1 8 8</b> STATE <b>N O N E</b>	
b.					EPA WASTE CODE STATE	
c.					EPA WASTE CODE STATE	
d.					EPA WASTE CODE STATE	
<b>RECEIVED</b>						
APR 19 1991						
NORANDA ALUMINUM, INC. Environmental - Energy Mgt.						
J. Additional Descriptions for Materials Listed Above						
a.	b.	c.	d.	K. HANDLING CODE (FACILITY USE ONLY)		
a.	b.	c.	d.	INTERIM	FINAL	
a.	<b>D 8 1</b>	<b>D 8 0</b>	<b>MO DNR</b>	COMMENTS		
c.		<b>D 8 1</b>	<b>RCRA</b>			
15. Special Handling Instructions and Additional Information <b>Spent Potliner GM90-3145</b> <b>USPCI 24 Hour Emergency Number: (800) 877-0454</b> <b>NORANDA Emergency Contact: (314)643-2361</b>						
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations and applicable state regulations. If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method available to me that I can afford.						
Printed/Typed Name <b>JEROME D. ROBBINS</b> Signature <b>Jerome D. Robbins</b> Month Day Year <b>10 31 26 19 91</b>						
17. Transporter 1 Acknowledgement of Receipt of Materials Printed/Typed Name <b>JOE BAKER</b> Signature <b>Joe Baker</b> Month Day Year <b>10 31 26 19 91</b>						
18. Transporter 2 Acknowledgement of Receipt of Materials Printed/Typed Name <b>H. D. Hodges</b> Signature <b>H. D. Hodges</b> Month Day Year <b>10 31 26 19 91</b>						
19. Discrepancy Indication Space						
20. Designated Facility Owner or Operator. Certification of receipt and handling of hazardous materials covered by this manifest except as noted in Item 19. Printed/Typed Name <b>N. J. Wesley</b> Signature <b>N. J. Wesley</b> Month Day Year <b>9/19 3944</b>						

INSTRUCTIONS FOR THE COMPLETION OF THIS FORM ARE ON A SEPARATE SHEET.

THIS DOCUMENT MUST BE USED FOR ALL MISSOURI-DESTINED SHIPMENTS.

## MISSOURI DEPARTMENT OF NATURAL RESOURCES

Division of Environmental Quality

Waste Management Program

P.O. Box 176 Jefferson City, Missouri 65102  
314-751-3176

EMERGENCY RESPONSE  
U.S. COAST GUARD  
1-800-424-8802  
CHEM TREC  
1-800-424-9300  
DEPT. OF NATURAL RESOURCES  
314-634-2436

# HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12-pitch) typewriter.)

Form Approved. OMB No 2050-0039. Expires 9-30-91

<b>UNIFORM HAZARDOUS WASTE MANIFEST</b>		1. Generator's US EPA ID No. <b>M O D O 9 3 7 5 0 9 6 6   0 0 3 3 2</b>	Manifest Document No. <b>0 0 1 5 6 2   0 3 1 0</b>	2. Page <b>2</b> of <b>2</b>	Information in the shaded areas is required by State law.	
3. Generator's Name and Mailing Address <b>Noranda Aluminum, Inc.</b> <b>P. O. Box 70      New Madrid, MO      63869</b>						
4. Generator's Phone ( <b>314) 643-2361</b> )						
5. Transporter 1 Company Name <b>Transporter 3</b> <b>U.S. Pollution Control, Inc.</b>						
6. US EPA ID Number <b>0 K D 9 8 1 5 1 4 4 7 4</b>						
7. Transporter 2 Company Name <b>U.S. Pollution Control, Inc. Grassy Mountain Facility</b> <b>3 Mi. East and 7 Mi. North of Knolls Exit #41 off I-80</b> <b>Clive, UT</b>						
8. US EPA ID Number <b>IUTD991301748</b>						
9. Designated Facility Name and Site Address <b>10. US EPA ID Number</b>						
11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)						
12. Containers						
a.	Number	Type	Total Quantity	Unit Wt/Vol	I. Waste No.	
b.					EPA WASTE CODE STATE	
c.					EPA WASTE CODE STATE	
d.					EPA WASTE CODE STATE	
J. Additional Descriptions for Materials Listed Above						
K. HANDLING CODE (FACILITY USE ONLY)						
a.	INTERIM	FINAL	COMMENTS			
b.						
c.						
d.						
15. Special Handling Instructions and Additional Information						
<b>CONTINUATION SHEET - To Identify Third Transporter</b>						
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations and applicable state regulations. If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method available to me that I can afford.						
Printed/Typed Name <b>J. B. H.</b>		Signature		Month	Day	Year
17. Transporter 1 Acknowledgement of Receipt of Materials						
Printed/Typed Name <b>GARY HILL</b>		Signature <b>Gary Hill</b>		Month	Day	Year
18. Transporter 2 Acknowledgement of Receipt of Materials						
Printed/Typed Name		Signature		Month	Day	Year
19. Discrepancy Indication Space						
20. Designated Facility Owner or Operator: Certification of receipt and handling of hazardous materials covered by this manifest except as noted in Item 19.						
Printed/Typed Name		Signature		Month	Day	Year

THIS COPY MUST BE SENT BACK TO THE GENERATOR BY THE DESIGNATED FACILITY OWNER OR OPERATOR AND RETURNED TO THE DEPARTMENT BY THE GENERATOR.

INSTRUCTIONS FOR THE COMPLETION OF THIS FORM ARE ON A SEPARATE SHEET.

THIS DOCUMENT MUST BE USED FOR ALL MISSOURI-DESTINED SHIPMENTS.

# MISSOURI DEPARTMENT OF NATURAL RE

Division of Environmental Quality  
Waste Management Program  
P.O. Box 176 Jefferson City, Missouri 65102  
314-751-3176

CES

EMERGENCY RESPONSE  
U.S. COAST GUARD  
1-800-424-8802  
CHEM TREC  
1-800-424-9300  
DEPT. OF NATURAL RESOURCES  
314-634-2436

## HAZARDOUS WASTE MANIFEST

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form Approved. OMB No. 2050-0039. Expires 9-30-91

<b>UNIFORM HAZARDOUS WASTE MANIFEST</b>		1. Generator's US EPA ID No. <b>M O D 0 9 3 7 5 0 9 6 6   0 0 3 3 3</b>	Manifest Document No. <b>0 0 1 5 6 2   0 3 1 1</b>	2. Page <b>1</b> of <b>2</b>	Information in the shaded areas / is required by State law.
3. Generator's Name and Mailing Address <b>Noranda Aluminum, Inc. P.O. Box 70 New Madrid, MO 63869</b>		A. Missouri Manifest Document Number <b>0 0 1 5 6 2   0 3 1 1</b>			
4. Generator's Phone ( 314 ) 643-2361		B. G.S.I. (Gen. Site Address) <b>St. Jude Industrial Park</b>			
5. Transporter 1 Company Name <b>U.S. Pollution Control, Inc.</b>		C. MO. Trans. ID <b>H-1024</b>			
7. Transporter 2 Company Name <b>Union Pacific Railroad</b>		D. Transporter's Phone <b>(405)324-5011</b>			
9. Designated Facility Name and Site Address <b>U.S. Pollution Control, Inc. Grassy Mountain Facility 3 Mi. East and 7 Mi. North of Knolls Exit #41 off I-80 Clive, UT</b>		E. MO. Trans. ID <b>(402)271-4400</b>			
11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)		F. Transporter's Phone <b>(801)595-3900</b>			
a. RQ Hazardous Solid, N.O.S. ORM-E NA9189 (K088)		12. Containers Number <b>0 0 1</b>	Type <b>C M</b>	13. Total Quantity <b>323.40</b>	I. Waste No. <b>K 0 8 8 STATE N O N E</b>
b.					EPA WASTE CODE <b>STATE</b>
c.					EPA WASTE CODE <b>STATE</b>
d.					EPA WASTE CODE <b>STATE</b>
J. Additional Descriptions for Materials Listed Above		K. HANDLING CODE (FACILITY USE ONLY)			
a.		INTERIM <b>D 8 1</b>	FINAL <b>D 8 1</b>	COMMENTS <b>RCPs MO DUR</b>	
b.		<b>a</b>	<b>D 8 1</b>	<b>D 8 0</b>	
c.					
d.					
15. Special Handling Instructions and Additional Information <b>Spent Potliner GM90-3145 USPCI 24 Hour Emergency Number: (800) 877-0454 NORANDA Emergency Contact: (314)643-2361</b>					
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in respects in proper condition for transport by highway according to applicable international and national government regulations and applicable state regulations. If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method available to me that I can afford.					
Printed/Typed Name <b>JEROME D. Robbins</b>		Signature <b>Jerome D. Robbins</b>			
		Month Day Year <b>03/26/91</b>			
17. Transporter 1 Acknowledgement of Receipt of Materials Printed/Typed Name <b>Edward Amos</b>		Signature <b>Edward Amos</b>			
		Month Day Year <b>03/26/91</b>			
18. Transporter 2 Acknowledgement of Receipt of Materials Printed/Typed Name <b>Henry D. Hodges</b>		Signature <b>Henry D. Hodges</b>			
		Month Day Year <b>03/26/91</b>			
19. Discrepancy Indication Space					
20. Designated Facility Owner or Operator: Certification of receipt and handling of hazardous materials covered by this manifest except as noted in Item 19. Printed/Typed Name <b>N. L. Kingsley</b>		Signature <b>N. L. Kingsley</b>			
		Date <b>04/02/91</b>			

INSTRUCTIONS FOR THE COMPLETION OF THIS FORM ARE ON A SEPARATE SHEET.  
THIS DOCUMENT MUST BE USED FOR ALL MISSOURI-DESTINED SHIPMENTS.

**SOURCE DEPARTMENT OF NATURAL RESOURCES**  
Division of Environmental Quality  
Waste Management Program  
P.O. Box 176 Jefferson City, Missouri 65102  
314-751-3176

EMERGENCY RESPONSE
U.S. COAST GUARD
1-800-424-8802
CHEM TREC
1-800-424-9300
DEPT. OF NATURAL RESOURCES
314-634-2436

# HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12-pitch) typewriter.)

Form Approved. OMB No. 2050-0039, Expires 9-30-91

<b>UNIFORM HAZARDOUS WASTE MANIFEST</b>		1. Generator's US EPA ID No. <b>M O D 0 9 3 7 5 0 9 6 6   0 0 3 3 3</b>	Manifest Document No. <b>0 0 1 5 6 2   0 3 1 1</b>	2. Page <b>2</b> of <b>2</b> Information in the shaded areas is required by State law.
3. Generator's Name and Mailing Address <b>Noranda Aluminum, Inc.</b> <b>P.O. Box 70 New Madrid, MO 63869</b>		A. Missouri Manifest Document Number <b>0 0 1 5 6 2   0 3 1 1</b>		
4. Generator's Phone ( <b>314</b> ) 643-2361		B. G.S.I. (Gen. Site Address) <b>St. Jude Industrial Park</b>		
5. Transporter 1 Company Name <b>Transporter 3 U.S. Pollution Control, Inc.</b>		C. MO. Trans. ID <b>H-1024</b>		
7. Transporter 2 Company Name		D. Transporter's Phone <b>(405)324-5011</b>		
9. Designated Facility Name and Site Address <b>U.S. Pollution Control, Inc. Grassy Mountain Facility</b> <b>3 Mi. East and 7 Mi. North of Knolls Exit #41 off I-80</b> <b>Clive, UT</b>		E. MO. Trans. ID		
		F. Transporter's Phone		
		G. State Facility's ID		
		H. Facility's Phone <b>(801)595-3900</b>		
11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)		12. Containers	13. Total Quantity	14. Unit Wt/Vol
a.				EPA WASTE CODE
b.				STATE
c.				EPA WASTE CODE
d.				STATE
J. Additional Descriptions for Materials Listed Above		K. HANDLING CODE (FACILITY USE ONLY)		
a.		INTERIM	FINAL	COMMENTS
b.				
c.				
d.				
15. Special Handling Instructions and Additional Information				
<b>CONTINUATION SHEET - To Identify Third Transporter</b>				
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations and applicable state regulations. If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method available to me that I can afford.				
Printed/Typed Name		Signature		
		Month Day Year		
17. Transporter 1 Acknowledgement of Receipt of Materials				
Printed/Typed Name		Signature		
		Date		
18. Transporter 2 Acknowledgement of Receipt of Materials				
Printed/Typed Name		Signature		
		Date		
19. Discrepancy Indication Space				
20. Designated Facility Owner or Operator: Certification of receipt and handling of hazardous materials covered by this manifest except as noted in Item 19.				
Printed/Typed Name		Signature		
		Date		

MISSOURI DNR FINAL COPY — PART 1

THIS COPY MUST BE SENT BACK TO THE GENERATOR BY THE DESIGNATED FACILITY. IT WILL THEN BE TRANSMITTED TO THE DEPARTMENT BY THE GENERATOR.

INSTRUCTIONS FOR THE COMPLETION OF THIS FORM ARE ON A SEPARATE SHEET.

THIS DOCUMENT MUST BE USED FOR ALL MISSOURI-DESTINED SHIPMENTS.

# MISSOURI DEPARTMENT OF NATURAL RESOURCES

Division of Environmental Quality

Waste Management Program

P.O. Box 176 Jefferson City, Missouri 65102  
314-751-3176

EMERGENCY RESPONSE  
U.S. COAST GUARD  
1-800-424-8802  
CH-E-M TREC  
1-800-424-9300  
DEPT. OF NATURAL RESOURCES  
314-634-2436

## HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12-pitch) typewriter.)

Form Approved. OMB No. 2050-0039. Expires 9-30-91

<b>UNIFORM HAZARDOUS WASTE MANIFEST</b>		1. Generator's US EPA ID No. <b>M O D 0 9 3 7 5 0 9 6 6   0 0 3 3 7</b>	Manifest Document No. <b>1</b>	2. Page <b>1</b> of <b>2</b>	Information in the shaded areas is required by State law.		
3. Generator's Name and Mailing Address <b>Noranda Aluminum, Inc. P.O. Box 70 New Madrid, MO 63869</b>							
4. Generator's Phone ( <b>314</b> ) 643-2361							
5. Transporter 1 Company Name <b>U.S. Pollution Control, Inc.</b>							
6. US EPA ID Number <b>0 K D 9 8 1 5 1 4 4 7 4</b>							
7. Transporter 2 Company Name <b>Union Pacific Railroad</b>							
8. US EPA ID Number <b>N E D 0 0 1 7 9 2 9 1 0</b>							
9. Designated Facility Name and Site Address <b>U.S. Pollution Control, Inc. Grassy Mountain Facility 3 Mi. East and 7 Mi. North of Knolls Exit #41 off I-80 Clive, UT</b>							
10. US EPA ID Number <b>U T D 9 9 1 3 0 1 7 4 8</b>							
11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)							
a. <b>RQ Hazardous Solid, N.O.S. ORM-E NA9189 (K088)</b>	12. Containers Number <b>0 0 1</b>	13. Total Quantity <b>C M   3 1 8 8   d</b>	14. Unit Wt/Vol. <b>P</b>	I. Waste No. <b>K 0 8 8</b>	EPA WASTE CODE <b>STATE N O N E</b>		
b.							
c.							
d.							
<b>RECEIVED</b> APR 19 1991							
J. Additional Descriptions for Materials Listed Above <b>NORANDA ALUMINUM, INC.</b> Environmental - Energy Mat.							
K. HANDLING CODE (FACILITY USE ONLY) INTERIM FINAL COMMENTS							
a.	<b>a</b>	<b>D 8 1</b>	<b>0 8 0</b>	<b>MODNR</b>	<b>RCRA</b>		
b.			<b>D 8 1</b>				
c.							
d.							
15. Special Handling Instructions and Additional Information <b>Spent Potliner GM90-3145 USPCI 24 Hour Emergency Number: (800) 877-0454 NORANDA Emergency Contact: (314)643-2361</b>							
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations and applicable state regulations. If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method available to me that I can afford.							
Printed/Typed Name <b>DON BACKFISCH</b>		Signature <i>Don Backfisch</i>		Month <b>03</b>	Day <b>28</b>	Year <b>1991</b>	
17. Transporter 1 Acknowledgement of Receipt of Materials							
Printed/Typed Name <b>Edward Amos</b>		Signature <i>Edward Amos</i>		Date			
18. Transporter 2 Acknowledgement of Receipt of Materials							
Printed/Typed Name <b>T. D. MILNER</b>		Signature <i>T. D. Milner</i>		Date			
19. Discrepancy Indication Space							
20. Designated Facility Owner or Operator: Certification of receipt and handling of hazardous materials covered by this manifest except as noted in Item 19							
Printed/Typed Name <b>Ph. Sengsley</b>		Signature <i>Ph. Sengsley</i>		Date <b>9/6-3862</b>	Month <b>04</b>	Day <b>10</b>	Year <b>1991</b>

INSTRUCTIONS FOR THE COMPLETION OF THIS FORM ARE ON A SEPARATE SHEET.  
THIS DOCUMENT MUST BE USED FOR ALL MISSOURI-DESTINED SHIPMENTS.

MISSOURI DEPARTMENT OF NATURAL RESOURCES  
Division of Environmental Quality  
Waste Management Program  
P.O. Box 176 Jefferson City, Missouri 65102  
314-751-3176

EMERGENCY RESPONSE  
U.S. COAST GUARD  
1-800-424-8802  
CHEM TREC  
1-800-424-9300  
DEPT. OF NATURAL RESOURCES  
314-634-2436

# HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12-pitch) typewriter.)

Form Approved. OMB No. 2050-0039, Expires 9-30-91

<b>A UNIFORM HAZARDOUS WASTE MANIFEST</b>		1. Generator's US EPA ID No. <b>M O D 0 9 3 7 5 0 9 6 6   0 0 3 3 7</b>	Manifest Document No. <b>0 0 1 5 6 2   0 3 1 4</b>	2. Page <b>2</b> of <b>2</b> Information in the shaded areas is required by State law.
3. Generator's Name and Mailing Address <b>Noranda Aluminum, Inc. P.O. Box 70 New Madrid, MO 63869</b>		A. Missouri Manifest Document Number <b>0 0 1 5 6 2   0 3 1 4</b>		
4. Generator's Phone ( <b>314</b> ) 643-2361		B. G.S.I. (Gen. Site Address) <b>St. Jude Industrial Park</b>		
5. Transporter 1 Company Name <b>Transporter 3 U.S. Pollution Control, Inc.</b>		6. US EPA ID Number <b>O K D 9 8 1 5 1 4 4 7 4</b>	C. MO. Trans. ID <b>H-1024</b>	D. Transporter's Phone <b>(405)324-5011</b>
7. Transporter 2 Company Name		8. US EPA ID Number	E. MO. Trans. ID	F. Transporter's Phone
9. Designated Facility Name and Site Address <b>U.S. Pollution Control, Inc. Grassy Mountain Facility 3 Mi. East and 7 Mi. North of Knolls Exit #41 off I-80 Clive, UT</b>		10. US EPA ID Number <b>U T D 9 9 1 3 0 1 7 4 8</b>	G. State Facility's ID	H. Facility's Phone <b>(801)595-3900</b>
11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)		12. Containers Number   Type	13. Total Quantity	14. Unit Wt/Vol
a.				I. Waste No. EPA WASTE CODE STATE
b.				EPA WASTE CODE STATE
c.				EPA WASTE CODE STATE
d.				EPA WASTE CODE STATE
J. Additional Descriptions for Materials Listed Above		K. HANDLING CODE (FACILITY USE ONLY) INTERIM   FINAL	COMMENTS	
a.		a.		
b.		b.		
c.		c.		
d.		d.		
15. Special Handling Instructions and Additional Information				
<b>CONTINUATION SHEET - To Identify Third Transporter</b>				
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations and applicable state regulations. If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method available to me that I can afford.				
Printed/Typed Name		Signature		
		Month Day Year		
17. Transporter 1 Acknowledgement of Receipt of Materials				
Printed/Typed Name <i>Gary Hicks</i>		Signature		
		Date		
18. Transporter 2 Acknowledgement of Receipt of Materials				
Printed/Typed Name		Signature		
		Date		
19. Discrepancy Indication Space				
20. Designated Facility Owner or Operator: Certification of receipt and handling of hazardous materials covered by this manifest except as noted in Item 19.				
Printed/Typed Name		Signature		
		Date		

THIS COPY MUST BE SENT BACK TO THE GENERATOR BY THE DESIGNATED TRANSPORTER AND RETURNED TO THE DEPARTMENT BY THE GENERATOR.

INSTRUCTIONS FOR THE COMPLETION OF THIS FORM ARE ON A SEPARATE SHEET.

THIS DOCUMENT MUST BE USED FOR ALL MISSOURI-DESTINED SHIPMENTS.

# MISSOURI DEPARTMENT OF NATURAL RESOURCES

Division of Environmental Quality

Waste Management Program

P.O. Box 176 Jefferson City, Missouri 65102  
314-751-3176

EMERGENCY RESPONSE  
U.S. COAST GUARD  
1-800-424-8802  
CHEM TREC  
1-800-424-9360  
DEPT. OF NATURAL RESOURCES  
314-634-2436

## HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12-pitch) typewriter.)

Form Approved. OMB No. 2050-0039. Expires 9-30-91

<b>UNIFORM HAZARDOUS WASTE MANIFEST</b>		1. Generator's US EPA ID No. <b>M O D 0 9 3 7 5 0 9 6 6   0 0 3 8</b>	Manifest Document No.	2. Page <b>1</b> of <b>2</b>	Information in the shaded areas is required by State law.
3. Generator's Name and Mailing Address <b>Noranda Aluminum, Inc.</b> <b>P.O. Box 70</b> New Madrid, MO 63869				A. Missouri Manifest Document Number <b>0 0 1 5 6 2   0 3 1 5</b>	
4. Generator's Phone ( <b>314</b> ) 643-2361		6. US EPA ID Number <b>U.S. Pollution Control, Inc.</b> <b>  0 K D 9 8 1 5 1 4 4 7 4</b>	8. US EPA ID Number <b>Union Pacific Railroad</b> <b>  N E D 0 0 1 7 9 2 9 1 0</b>	B. G.S.I. (Gen. Site Address) <b>St. Jude Industrial Park</b>	
5. Transporter 1 Company Name <b>U.S. Pollution Control, Inc.</b>		10. US EPA ID Number <b>U.S. Pollution Control, Inc. Grassy Mountain Facility</b> <b>3 Mi. East and 7 Mi. North of Knolls Exit #41 off I-80</b> <b>Clive, UT</b>	12. Containers Number <b>0 0 1</b>	13. Total Quantity <b>C M 3 2 2 2 0</b>	C. MO. Trans. ID <b>H-1024</b>
7. Transporter 2 Company Name <b>Union Pacific Railroad</b>		14. Unit Wt/Vol. <b>(402)271-4400</b>	D. Transporter's Phone <b>(405)324-5011</b>		E. MO. Trans. ID
9. Designated Facility Name and Site Address <b>U.S. Pollution Control, Inc. Grassy Mountain Facility</b> <b>3 Mi. East and 7 Mi. North of Knolls Exit #41 off I-80</b> <b>Clive, UT</b>		15. Facility's Phone <b>(801)595-3900</b>	F. Transporter's Phone <b>(402)271-4400</b>		G. State Facility's ID
11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)		16. Handled by ORM-E <b>NA9189 (K088)</b>	H. Facility's Phone <b>(801)595-3900</b>		I. Waste No.
a.					EPA WASTE CODE <b>K 0 1 8 8</b> STATE <b>N O N E</b>
b.					EPA WASTE CODE STATE
c.					EPA WASTE CODE STATE
d.					EPA WASTE CODE STATE
J. Additional Descriptions for Materials Listed Above		K. HANDLING CODE (FACILITY USE ONLY)			
a.		INTERIM <b>D 81</b>	FINAL <b>D 18 10</b>	COMMENTS <b>MO DNR</b>	
b.		<b>a</b>	<b>D 81</b>	<b>D 18 11</b>	<b>RCRA</b>
c.					
d.					
15. Special Handling Instructions and Additional Information <b>Spent Potliner GM90-3145</b> <b>USPCI 24 Hour Emergency Number: (800) 877-0454</b> <b>NORANDA Emergency Contact: (314)643-2361</b>					
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations and applicable state regulations. If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method available to me that I can afford.					
Printed/Typed Name <b>DON BACKFISCH</b>		Signature <i>Don Backfisch</i>		Month Day Year <b>10.31.2819/1</b>	Date
17. Transporter 1 Acknowledgment of Receipt of Materials Printed/Typed Name <b>USPCI - JOE BAKER</b>		Signature <i>Joe Baker</i>		Month Day Year <b>10.31.2819/1</b>	Date
18. Transporter 2 Acknowledgment of Receipt of Materials Printed/Typed Name <b>T. D. MILNER</b>		Signature <i>T. D. Milner</i>		Month Day Year <b>10.31.2819/1</b>	Date
19. Discrepancy Indication Space					
20. Designated Facility Owner or Operator. Certification of receipt and handling of hazardous materials covered by this manifest except as noted in Item 19.					
Printed/Typed Name <b>M. Kingsley</b>		Signature <i>M. Kingsley</i>		Month Day Year <b>9/6-3811</b>	Date

INSTRUCTIONS FOR THE COMPLETION OF THIS FORM ARE ON A SEPARATE SHEET.  
THIS DOCUMENT MUST BE USED FOR ALL MISSOURI-DESTINED SHIPMENTS.


MISSOURI DEPARTMENT OF NATURAL RESOURCES  
Division of Environmental Quality  
Waste Management Program  
P.O. Box 176 Jefferson City, Missouri 65102  
314-751-3176

EMERGENCY RESPONSE  
U.S. COAST GUARD  
1-800-424-8802  
CHEM TREC  
1-800-424-9300  
DEPT OF NATURAL RESOURCES  
314-634-2436

# HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12-pitch) typewriter.)

Form Approved. OMB No. 2050-0039. Expires 9-30-91

<b>UNIFORM HAZARDOUS WASTE MANIFEST</b>		1. Generator's US EPA ID No. <b>M O D 0 9 3 7 5 0 9 6 6 0 0 3 3 8</b>	Manifest Document No.	2. Page <b>2</b> of <b>2</b>	Information in the shaded areas is required by State law.	
3. Generator's Name and Mailing Address <b>Noranda Aluminum, Inc.</b> <b>P.O. Box 70 New Madrid, MO 63369</b>		A. Missouri Manifest Document Number <b>0 0 1 5 6 2 0 3 1 5</b>				
4. Generator's Phone ( <b>314</b> , 643-2361 )		B. G.S.I. (Gen. Site Address) <b>St. Jude Industrial Park</b>				
5. Transporter 1 Company Name <b>Transporter 3 U.S. Pollution Control, Inc.</b>		C. MO. Trans. ID <b>H-1024</b>				
6. US EPA ID Number <b>O K D 9 8 1 5 1 4 4 7 4</b>		D. Transporter's Phone <b>(405)324-5011</b>				
7. Transporter 2 Company Name		E. MO. Trans. ID				
8. US EPA ID Number		F. Transporter's Phone				
9. Designated Facility Name and Site Address <b>U.S. Pollution Control, Inc. Grassly Mountain Facility</b> <b>3 Mi. East and 7 Mi. North of Knolls Exit #41 off I-80</b> <b>Clive, UT</b>		G. State Facility's ID				
10. US EPA ID Number <b>U T D 9 9 1 3 0 1 7 4 8</b>		H. Facility's Phone <b>(801)595-3900</b>				
11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)		12. Containers Number	Type	13. Total Quantity	14. Unit Wt/Vol.	I. Waste No.
a.						EPA WASTE CODE
b.						STATE
c.						EPA WASTE CODE
d.						STATE
J. Additional Descriptions for Materials Listed Above		K. HANDLING CODE (FACILITY USE ONLY)				
a.		INTERIM	FINAL	COMMENTS		
b.						
c.						
d.						
15. Special Handling Instructions and Additional Information						
<b>CONTINUATION SHEET - To Identify Third Transporter</b>						
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations and applicable state regulations. If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method available to me that I can afford.						
Printed/Typed Name		Signature		Month	Day	Year
17. Transporter 1 Acknowledgement of Receipt of Materials Printed/Typed Name <b>Gary Hicks</b>		Signature 		Date <b>04/01/91</b>		
18. Transporter 2 Acknowledgement of Receipt of Materials Printed/Typed Name		Signature		Date		
19. Discrepancy Indication Space		Signature		Month	Day	Year
20 Designated Facility Owner or Operator: Certification of receipt and handling of hazardous materials covered by this manifest except as noted in Item 19.						
Printed/Typed Name		Signature		Month	Day	Year

THIS COPY MUST BE SENT BACK TO THE GENERATOR BY THE DESIGNATED TRANSPORTER THEN TRANSMITTED TO THE DEPARTMENT BY THE GENERATOR.

29746	SK50	SAFETY-KLEEN	SAFETY-KLEEN AT CAPE	1290	03-Jan-91		SOLVENTS FROM PARTS WASHERS
250	001562-0227	USPCI	USPCI LONE MOUNTAIN	23520	10-Jan-91		SPENT POTLINER (LM90-0905) ALCOA MATERIAL
259	001562-0236	TRIAD TRANSPORT	USPCI LONE MOUNTAIN	43360	17-Jan-91		SPENT POTLINER (LM90-0905)
251	001562-0228	TRIAD TRANSPORT	USPCI LONE MOUNTAIN	39280	17-Jan-91		SPENT POTLINER (LM90-0905)
255	001562-0232	JOE BROWN CO.	USPCI LONE MOUNTAIN	44540	17-Jan-91		SPENT POTLINER (LM90-0905)
252	001562-0229	TRIAD TRANSPORT	USPCI LONE MOUNTAIN	42020	17-Jan-91		SPENT POTLINER (LM90-0905)
256	001562-0233	JOE BROWN CO.	USPCI LONE MOUNTAIN	43460	17-Jan-91		SPENT POTLINER (LM90-0905)
253	001562-0230	TRIAD TRANSPORT	USPCI LONE MOUNTAIN	42840	17-Jan-91		SPENT POTLINER (LM90-0905)
257	001562-0234	JOE BROWN CO.	USPCI LONE MOUNTAIN	43720	17-Jan-91		SPENT POTLINER (LM90-0905)
254	001562-0231	JOE BROWN CO.	USPCI LONE MOUNTAIN	42040	17-Jan-91		SPENT POTLINER (LM90-0905)
258	001562-0235	JOE BROWN CO.	USPCI LONE MOUNTAIN	42560	17-Jan-91		SPENT POTLINER (LM90-0905)
260	001562-0237	TRIAD TRANSPORT	USPCI LONE MOUNTAIN	44540	17-Jan-91		SPENT POTLINER (LM90-0905)
262	001562-0239	JOE BROWN CO.	USPCI LONE MOUNTAIN	42260	22-Jan-91		SPENT POTLINER (LM90-0905)
268	001562-0245	TRIAD TRANSPORT	USPCI LONE MOUNTAIN	41800	22-Jan-91		SPENT POTLINER (LM90-0905)-
270	001562-0247	JOE BROWN CO.	USPCI LONE MOUNTAIN	46480	22-Jan-91		SPENT POTLINER (LM90-0905)
269	001562-0246	TRIAD TRANSPORT	USPCI LONE MOUNTAIN	43500	22-Jan-91		SPENT POTLINER (LM90-0905)
264	001562-0241	JOE BROWN CO.	USPCI LONE MOUNTAIN	43140	22-Jan-91		SPENT POTLINER (LM90-0905)
266	001562-0243	TRIAD TRANSPORT	USPCI LONE MOUNTAIN	45520	22-Jan-91		SPENT POTLINER (LM90-0905)
265	001562-0242	TRIAD TRANSPORT	USPCI LONE MOUNTAIN	45600	22-Jan-91		SPENT POTLINER (LM90-0905)
263	001562-0240	JOE BROWN CO.	USPCI LONE MOUNTAIN	47000	22-Jan-91		SPENT POTLINER (LM90-0905)
261	001562-0238	JOE BROWN CO.	USPCI LONE MOUNTAIN	37340	22-Jan-91		SPENT POTLINER (LM90-0905)
267	001562-0244	TRIAD TRANSPORT	USPCI LONE MOUNTAIN	39360	22-Jan-91		SPENT POTLINER (LM90-0905)
272	001562-0249	TRIAD TRANSPORT	USPCI LONE MOUNTAIN	48800	24-Jan-91		SPENT POTLINER (LM90-0905)
273	001562-0250	TRIAD TRANSPORT	USPCI LONE MOUNTAIN	43720	24-Jan-91		SPENT POTLINER (LM90-0905)
274	001562-0251	TRIAD TRANSPORT	USPCI LONE MOUNTAIN	46560	24-Jan-91		SPENT POTLINER (LM90-0905)
277	001562-0254	JOE BROWN CO.	USPCI LONE MOUNTAIN	38920	24-Jan-91	43020	9.5 SPENT POTLINER (LM90-0905)
275	001562-0252	TRIAD TRANSPORT	USPCI LONE MOUNTAIN	43780	24-Jan-91	43800	0.0 SPENT POTLINER (LM90-0905)
278	001562-0255	JOE BROWN CO.	USPCI LONE MOUNTAIN	38140	24-Jan-91	38060	-0.2 SPENT POTLINER (LM90-0905)
271	001562-0248	TRIAD TRANSPORT	USPCI LONE MOUNTAIN	43340	24-Jan-91		SPENT POTLINER (LM90-0905)
279	001562-256	JOE BROWN CO.	USPCI LONE MOUNTAIN	41440	24-Jan-91	41760	0.8 SPENT POTLINER (LM90-0905)
276	001562-0253	JOE BROWN CO.	USPCI LONE MOUNTAIN	42600	24-Jan-91	42660	0.1 SPENT POTLINER (LM90-0905)
280	001562-0257	JOE BROWN CO.	USPCI LONE MOUNTAIN	43940	24-Jan-91	44120	0.4 SPENT POTLINER (LM90-0905)
62284	SK51	SAFETY KLEEN	SAFETY-KLEEN AT CAPE	1404	30-Jan-91		SOLVENT FROM PARTS WASHERS
285	001562-0262	JOE BROWN CO.	USPCI LONE MOUNTAIN	37580	31-Jan-91	38240	1.7 SPENT POTLINER (LM90-0905)
289	001562-0266	TRIAD TRANSPORT	USPCI LONE MOUNTAIN	38420	31-Jan-91	38840	1.1 SPENT POTLINER (LM90-0905)
284	001562-0261	JOE BROWN CO.	USPCI LONE MOUNTAIN	43920	31-Jan-91	44080	0.4 SPENT POTLINER (LM90-0905)
288	001562-0265	TRIAD TRANSPORT	USPCI LONE MOUNTAIN	34200	31-Jan-91	34840	1.8 SPENT POTLINER (LM90-0905)
287	001562-0264	JOE BROWN CO.	USPCI LONE MOUNTAIN	35200	31-Jan-91	35800	1.7 SPENT POTLINER (LM90-0905)
282	001562-0259	TRIAD TRANSPORT	USPCI LONE MOUNTAIN	44420	31-Jan-91	45060	1.4 SPENT POTLINER (LM90-0905)
281	001562-0258	TRIAD TRANSPORT	USPCI LONE MOUNTAIN	37980	31-Jan-91	38080	0.3 SPENT POTLINER (LM90-0905)
286	001562-0263	JOE BROWN CO.	USPCI LONE MOUNTAIN	46060	31-Jan-91	46860	1.7 SPENT POTLINER (LM90-0905)
283	001562-0260	JOE BROWN CO.	USPCI LONE MOUNTAIN	43600	31-Jan-91	43780	0.4 SPENT POTLINER (LM90-0905)
290	001562-0267	TRIAD TRANSPORT	USPCI LONE MOUNTAIN	43680	31-Jan-91	43080	-1.4 SPENT POTLINER (LM90-0905)
299	001562-0276	JOE BROWN CO.	USPCI LONE MOUNTAIN	42480	25-Feb-91	42700	0.5 SPENT POTLINER (LM90-0905)

43

303	001562-0280	USPCI	USPCI LONE MOUNTAIN	43760	25-Feb-91	44320	1.3 SPENT POTLINER (LM90-0905)
298	001562-0275	JOE BROWN CO.	USPCI LONE MOUNTAIN	42100	25-Feb-91	42100	0.0 SPENT POTLINER (LM90-0905)
302	001562-0279	USPCI	USPCI LONE MOUNTAIN	43540	25-Feb-91	41420	-5.1 SPENT POTLINER (LM90-0905)
296	001562-0273	JOE BROWN CO.	USPCI LONE MOUNTAIN	46140	25-Feb-91	45240	-2.0 SPENT POTLINER (LM90-0905)
297	001562-0274	JOE BROWN CO.	USPCI LONE MOUNTAIN	41580	25-Feb-91	41180	-1.0 SPENT POTLINER (LM90-0905)
300	001562-0277	JOE BROWN CO.	USPCI LONE MOUNTAIN	41640	25-Feb-91	41920	0.7 SPENT POTLINER (LM90-0905)
301	001562-0278	USPCI	USPCI LONE MOUNTAIN	39560	25-Feb-91	39020	-1.4 SPENT POTLINER (LM90-0905)
295	001562-0272	TRIAD TRANSPORT	USPCI LONE MOUNTAIN	46360	27-Feb-91	45400	-2.1 SPENT POTLINER (LM90-0905)
306	001562-0283	TRIAD TRANSPORT	USPCI LONE MOUNTAIN	46440	27-Feb-91	45180	-2.8 SPENT POTLINER (LM90-0905)

291 001562-0271	USPCI LONE MOUNTAIN	34330	27-Feb-91	32800	-5.4 SPENT POTLINER (LM90-0905)
294 001562-0271	LONE MOUNTAIN	46800	27-Feb-91	493	5.1 SPENT POTLINER (LM90-0905)
293 001562-0270	USPCI LONE MOUNTAIN	44160	27-Feb-91	4244	-4.1 SPENT POTLINER (LM90-0905)
305 001562-0282	USPCI LONE MOUNTAIN	44800	27-Feb-91	43300	-3.5 SPENT POTLINER (LM90-0905)
292 001562-0269	USPCI LONE MOUNTAIN	27460	27-Feb-91	27460	0.0 SPENT POTLINER (LM90-0905)
324 001562-0301	USPCI LONE MOUNTAIN	43120	28-Feb-91	45940	6.1 SPENT POTLINER (LM90-0905)
307 001562-0284	USPCI LONE MOUNTAIN	38780	28-Feb-91	38780	0.0 SPENT POTLINER (LM90-0905)
309 001562-0286	USPCI LONE MOUNTAIN	41700	28-Feb-91	41720	0.0 SPENT POTLINER (LM90-0905)
308 001562-0285	USPCI LONE MOUNTAIN	42580	28-Feb-91	43040	1.1 SPENT POTLINER (LM90-0905)
311 001562-0288	USPCI LONE MOUNTAIN	43180	28-Feb-91	40600	-6.4 SPENT POTLINER (LM90-0905)
310 001562-0287	USPCI LONE MOUNTAIN	42360	28-Feb-91	42720	0.8 SPENT POTLINER (LM90-0905)
315 001562-0292	JOE BROWN CO.	36740	01-Mar-91	38100	3.6 SPENT POTLINER (LM90-0905)
313 001562-0290	JOE BROWN CO.	39320	01-Mar-91	39800	1.2 SPENT POTLINER (LM90-0905)
314 001562-0291	JOE BROWN CO.	41440	01-Mar-91	42620	2.8 SPENT POTLINER (LM90-0905)
312 001562-0289	JOE BROWN CO.	39460	01-Mar-91	38660	-2.1 SPENT POTLINER (LM90-0905)
316 001562-0293	JOE BROWN CO.	43860	01-Mar-91	41900	-4.7 SPENT POTLINER (LM90-0905)
317 001562-0294	JOE BROWN CO.	36200	01-Mar-91	35000	-3.4 SPENT POTLINER (LM90-0905)
10296 SK52	SAFETY KLEEN	3055	04-Mar-91		SOLVENT FROM PARTS WASHERS
322 001562-0299	USPCI	32380	07-Mar-91	31820	-1.8 SPENT POTLINER (LM90-0905)
321 001562-0298	USPCI	29620	08-Mar-91	31580	6.2 SPENT POTLINER (LM90-0905)
319 001562-0296	USCPI	31460	11-Mar-91	32120	2.1 SPENT POTLINER (LM90-0905)
318 001562-0295	USCPI	31580	11-Mar-91	28800	-9.7 SPENT POTLINER (LM90-0905)
320 001562-0297	USCPI	28760	11-Mar-91	28760	0.0 SPENT POTLINER (LM90-0905)
326 001562-0303	USCPI	32600	13-Mar-91	34480	5.5 SPENT POTLINER (LM90-0905)
325 001562-0302	USCPI	21280	13-Mar-91	21220	-0.3 SPENT POTLINER (LM90-0905)
SK53	SAFETY KLEEN	1521	25-Mar-91	1521	0.0 SPENT POTLINER (LM90-0905)
323 001562-0300	USCPI	25540	25-Mar-91	26380	3.2 SPENT POTLINER (LM90-0905)
328 001562-0305	USCPI	27820	25-Mar-91	27820	0.0 SPENT POTLINER (LM90-0905)
332 001562-0310	USCPI	33580	26-Mar-91	33580	0.0 SPENT POTLINER (GM90-3145)
333 001562-0311	USCPI	32340	26-Mar-91		ERR SPENT POTLINER (GM90-3145)
327 001562-0304	USCPI	31500	27-Mar-91	31500	0.0 SPENT POTLINER (GM90-3145)
329 001562-0306	USCPI	39240	27-Mar-91		ERR SPENT POTLINER (GM90-3145)
338 001562-0315	USCPI	32220	28-Mar-91	32220	0.0 SPENT POTLINER (GM90-3145)
337 001562-0314	USCPI	31880	28-Mar-91	31880	0.0 SPENT POTLINER (GM90-3145)

87 For Qtr 2 Report 1<sup>st</sup> Qtr = 25  
Not Lapsed = 62

21- SPL March ((a) Grassy 150 (H))

4- Safety Kleen = 7270 pounds

Grassy SPL = 200,760 pounds

UH SPL = 54,500 pounds  
498,060

29746	SK50	SAFETY-KLEEN	SAFETY-KLEEN AT CAPE	1290	03-Jan-91	SOLVENTS FROM PARTS WASHERS
250	001562-0227	USPCI	USPCI LONE MOUNTAIN	28520	10-Jan-91	SPENT POTLINER (LM90-0905) ALCOA MATERIAL
259	001562-0236	TRIAD TRANSPORT	USPCI LONE MOUNTAIN	43360	17-Jan-91	SPENT POTLINER (LM90-0905)
251	001562-0228	TRIAD TRANSPORT	USPCI LONE MOUNTAIN	39280	17-Jan-91	SPENT POTLINER (LM90-0905)
255	001562-0232	JOE BROWN CO.	USPCI LONE MOUNTAIN	44540	17-Jan-91	SPENT POTLINER (LM90-0905)
252	001562-0229	TRIAD TRANSPORT	USPCI LONE MOUNTAIN	42020	17-Jan-91	SPENT POTLINER (LM90-0905)
256	001562-0233	JOE BROWN CO.	USPCI LONE MOUNTAIN	43460	17-Jan-91	SPENT POTLINER (LM90-0905)
253	001562-0230	TRIAD TRANSPORT	USPCI LONE MOUNTAIN	42840	17-Jan-91	SPENT POTLINER (LM90-0905)
257	001562-0234	JOE BROWN CO.	USPCI LONE MOUNTAIN	43720	17-Jan-91	SPENT POTLINER (LM90-0905)
254	001562-0231	JOE BROWN CO.	USPCI LONE MOUNTAIN	42040	17-Jan-91	SPENT POTLINER (LM90-0905)
258	001562-0235	JOE BROWN CO.	USPCI LONE MOUNTAIN	42560	17-Jan-91	SPENT POTLINER (LM90-0905)
260	001562-0237	TRIAD TRANSPORT	USPCI LONE MOUNTAIN	44540	17-Jan-91	SPENT POTLINER (LM90-0905)
262	001562-0239	JOE BROWN CO.	USPCI LONE MOUNTAIN	42260	22-Jan-91	SPENT POTLINER (LM90-0905)
268	001562-0245	TRIAD TRANSPORT	USPCI LONE MOUNTAIN	41800	22-Jan-91	SPENT POTLINER (LM90-0905)
270	001562-0247	JOE BROWN CO.	USPCI LONE MOUNTAIN	46480	22-Jan-91	SPENT POTLINER (LM90-0905)
269	001562-0246	TRIAD TRANSPORT	USPCI LONE MOUNTAIN	43500	22-Jan-91	SPENT POTLINER (LM90-0905)
264	001562-0241	JOE BROWN CO.	USPCI LONE MOUNTAIN	43140	22-Jan-91	SPENT POTLINER (LM90-0905)
266	001562-0243	TRIAD TRANSPORT	USPCI LONE MOUNTAIN	45520	22-Jan-91	SPENT POTLINER (LM90-0905)
265	001562-0242	TRIAD TRANSPORT	USPCI LONE MOUNTAIN	45600	22-Jan-91	SPENT POTLINER (LM90-0905)
263	001562-0240	JOE BROWN CO.	USPCI LONE MOUNTAIN	47000	22-Jan-91	SPENT POTLINER (LM90-0905)
261	001562-0238	JOE BROWN CO.	USPCI LONE MOUNTAIN	37340	22-Jan-91	SPENT POTLINER (LM90-0905)
267	001562-0244	TRIAD TRANSPORT	USPCI LONE MOUNTAIN	39360	22-Jan-91	SPENT POTLINER (LM90-0905)
272	001562-0249	TRIAD TRANSPORT	USPCI LONE MOUNTAIN	48800	24-Jan-91	SPENT POTLINER (LM90-0905)
273	001562-0250	TRIAD TRANSPORT	USPCI LONE MOUNTAIN	43720	24-Jan-91	SPENT POTLINER (LM90-0905)
274	001562-0251	TRIAD TRANSPORT	USPCI LONE MOUNTAIN	46560	24-Jan-91	SPENT POTLINER (LM90-0905)
277	001562-0254	JOE BROWN CO.	USPCI LONE MOUNTAIN	38920	24-Jan-91	43020      9.5 SPENT POTLINER (LM90-0905)
275	001562-0252	TRIAD TRANSPORT	USPCI LONE MOUNTAIN	43780	24-Jan-91	43800      0.0 SPENT POTLINER (LM90-0905)
278	001562-0255	JOE BROWN CO.	USPCI LONE MOUNTAIN	38140	24-Jan-91	38060      -0.2 SPENT POTLINER (LM90-0905)
271	001562-0248	TRIAD TRANSPORT	USPCI LONE MOUNTAIN	43340	24-Jan-91	SPENT POTLINER (LM90-0905)
279	001562-256	JOE BROWN CO.	USPCI LONE MOUNTAIN	41440	24-Jan-91	41760      0.8 SPENT POTLINER (LM90-0905)
276	001562-0253	JOE BROWN CO.	USPCI LONE MOUNTAIN	42600	24-Jan-91	42660      0.1 SPENT POTLINER (LM90-0905)
280	001562-0257	JOE BROWN CO.	USPCI LONE MOUNTAIN	43940	24-Jan-91	44120      0.4 SPENT POTLINER (LM90-0905)
52284	SK51	SAFETY KLEEN	SAFETY-KLEEN AT CAPE	1404	30-Jan-91	SOLVENT FROM PARTS WASHERS
285	001562-0262	JOE BROWN CO.	USPCI LONE MOUNTAIN	37580	31-Jan-91	38240      1.7 SPENT POTLINER (LM90-0905)
289	001562-0266	TRIAD TRANSPORT	USPCI LONE MOUNTAIN	38420	31-Jan-91	38840      1.1 SPENT POTLINER (LM90-0905)
284	001562-0261	JOE BROWN CO.	USPCI LONE MOUNTAIN	43920	31-Jan-91	44080      0.4 SPENT POTLINER (LM90-0905)
288	001562-0265	TRIAD TRANSPORT	USPCI LONE MOUNTAIN	34200	31-Jan-91	34840      1.8 SPENT POTLINER (LM90-0905)
287	001562-0264	JOE BROWN CO.	USPCI LONE MOUNTAIN	35200	31-Jan-91	35800      1.7 SPENT POTLINER (LM90-0905)
282	001562-0259	TRIAD TRANSPORT	USPCI LONE MOUNTAIN	44420	31-Jan-91	45060      1.4 SPENT POTLINER (LM90-0905)
281	001562-0258	TRIAD TRANSPORT	USPCI LONE MOUNTAIN	37980	31-Jan-91	38080      0.3 SPENT POTLINER (LM90-0905)
286	001562-0263	JOE BROWN CO.	USPCI LONE MOUNTAIN	46060	31-Jan-91	46860      1.7 SPENT POTLINER (LM90-0905)
283	001562-0260	JOE BROWN CO.	USPCI LONE MOUNTAIN	43600	31-Jan-91	43780      0.4 SPENT POTLINER (LM90-0905)
290	001562-0267	TRIAD TRANSPORT	USPCI LONE MOUNTAIN	43680	31-Jan-91	43080      -1.4 SPENT POTLINER (LM90-0905)
299	001562-0276	JOE BROWN CO.	USPCI LONE MOUNTAIN	42480	25-Feb-91	42700      0.5 SPENT POTLINER (LM90-0905)

43

## NORANDA ALUMINUM HAZARDOUS WASTE SHIPMENTS MANIFEST FILE

303	001562-0280	USPCI	USPCI LONE MOUNTAIN	43760	25-Feb-91	44320      1.3 SPENT POTLINER (LM90-0905)
298	001562-0275	JOE BROWN CO.	USPCI LONE MOUNTAIN	42100	25-Feb-91	42100      0.0 SPENT POTLINER (LM90-0905)
302	001562-0279	USPCI	USPCI LONE MOUNTAIN	43540	25-Feb-91	41420      -5.1 SPENT POTLINER (LM90-0905)
296	001562-0273	JOE BROWN CO.	USPCI LONE MOUNTAIN	46140	25-Feb-91	45240      -2.0 SPENT POTLINER (LM90-0905)
297	001562-0274	JOE BROWN CO.	USPCI LONE MOUNTAIN	41580	25-Feb-91	41180      -1.0 SPENT POTLINER (LM90-0905)
300	001562-0277	JOE BROWN CO.	USPCI LONE MOUNTAIN	41640	25-Feb-91	41920      0.7 SPENT POTLINER (LM90-0905)
301	001562-0278	USPCI	USPCI LONE MOUNTAIN	39560	25-Feb-91	39020      -1.4 SPENT POTLINER (LM90-0905)
295	001562-0272	TRIAD TRANSPORT	USPCI LONE MOUNTAIN	46360	27-Feb-91	45400      -2.1 SPENT POTLINER (LM90-0905)
306	001562-0283	TRIAD TRANSPORT	USPCI LONE MOUNTAIN	46440	27-Feb-91	45180      -2.8 SPENT POTLINER (LM90-0905)
304	001562-0261	TRIAD TRANSPORT	USPCI LONE MOUNTAIN	41660	27-Feb-91	41120      -1.3 SPENT POTLINER (LM90-0905)
301	001562-0269	USPCI	USPCI LONE MOUNTAIN	34500	27-Feb-91	32000      -5.4 SPENT POTLINER (LM90-0905)

291	001562-0268	USPCI	USPCI LONE MOUNTAIN	34580	27-Feb-91	-5.4	SPENT POTLINER (LM90-0305)
294	001562-0271	TRIAD TRANSPORT	USPCI LONE MOUNTAIN	46800	27-Feb-91	0	5.1 SPENT POTLINER (LM90-0905)
293	001562-0270	TRIAD TRANSPORT	USPCI LONE MOUNTAIN	44160	27-Feb-91	-4.1	SPENT POTLINER (LM90-0905)
305	001562-0282	TRIAD TRANSPORT	USPCI LONE MOUNTAIN	44800	27-Feb-91	-3.5	SPENT POTLINER (LM90-0905)
292	001562-0269	USPCI	USPCI LONE MOUNTAIN	27460	27-Feb-91	0.0	SPENT POTLINER (LM90-0905)
324	001562-0301	TRIAD	USPCI LONE MOUNTAIN	43120	28-Feb-91	6.1	SPENT POTLINER (LM90-0905)
307	001562-0284	TRIAD TRANSPORT	USPCI LONE MOUNTAIN	38780	28-Feb-91	38780	0.0 SPENT POTLINER (LM90-0905)
309	001562-0286	TRIAD TRANSPORT	USPCI LONE MOUNTAIN	41700	28-Feb-91	41720	0.0 SPENT POTLINER (LM90-0905)
308	001562-0285	TRIAD TRANSPORT	USPCI LONE MOUNTAIN	42580	28-Feb-91	43040	1.1 SPENT POTLINER (LM90-0905)
311	001562-0288	TRIAD TRANSPORT	USPCI LONE MOUNTAIN	43180	28-Feb-91	40600	-6.4 SPENT POTLINER (LM90-0905)
310	001562-0287	TRIAD TRANSPORT	USPCI LONE MOUNTAIN	42360	28-Feb-91	42720	0.8 SPENT POTLINER (LM90-0905)
315	001562-0292	JOE BROWN CO.	USPCI LONE MOUNTAIN	36740	01-Mar-91	38100	3.6 SPENT POTLINER (LM90-0905)
313	001562-0290	JOE BROWN CO.	USPCI LONE MOUNTAIN	39320	01-Mar-91	39800	1.2 SPENT POTLINER (LM90-0905)
314	001562-0291	JOE BROWN CO.	USPCI LONE MOUNTAIN	41440	01-Mar-91	42620	2.8 SPENT POTLINER (LM90-0905)
312	001562-0289	JOE BROWN CO.	USPCI LONE MOUNTAIN	39460	01-Mar-91	38660	-2.1 SPENT POTLINER (LM90-0905)
316	001562-0293	JOE BROWN CO.	USPCI LONE MOUNTAIN	43860	01-Mar-91	41900	-4.7 SPENT POTLINER (LM90-0905)
317	001562-0294	JOE BROWN CO.	USPCI LONE MOUNTAIN	36200	01-Mar-91	35000	-3.4 SPENT POTLINER (LM90-0905)
10296	SK52	SAFETY KLEEN	SAFETY-KLEEN AT CAPE	3055	04-Mar-91		SOLVENT FROM PARTS WASHERS
322	001562-0299	USPCI	USPCI LONE MOUNTAIN	32380	07-Mar-91	31820	-1.8 SPENT POTLINER (LM90-0905)
321	001562-0298	USPCI	USPCI LONE MOUNTAIN	29620	08-Mar-91	31580	6.2 SPENT POTLINER (LM90-0905)
319	001562-0296	USPCI	USPCI LONE MOUNTAIN	31460	11-Mar-91	32120	2.1 SPENT POTLINER (LM90-0905)
318	001562-0295	USPCI	USPCI LONE MOUNTAIN	31580	11-Mar-91	28800	-9.7 SPENT POTLINER (LM90-0905)
320	001562-0297	USPCI	USPCI LONE MOUNTAIN	28760	11-Mar-91	28760	0.0 SPENT POTLINER (LM90-0905)
326	001562-0303	USPCI	USPCI LONE MOUNTAIN	32600	13-Mar-91	34480	5.5 SPENT POTLINER (LM90-0905)
325	001562-0302	USPCI	USPCI LONE MOUNTAIN	21280	13-Mar-91	21220	-0.3 SPENT POTLINER (LM90-0905)
SK53		SAFETY KLEEN	SAFETY-KLEEN AT CAPE	1521	25-Mar-91	1521	0.0 SPENT POTLINER (LM90-0905)
323	001562-0300	USPCI	USPCI LONE MOUNTAIN	25540	25-Mar-91	26380	3.2 SPENT POTLINER (LM90-0905)
328	001562-0305	USPCI	USPCI LONE MOUNTAIN	27820	25-Mar-91	27820	0.0 SPENT POTLINER (LM90-0905)
332	001562-0310	USPCI	USPCI GRASSY MTN.	33580	26-Mar-91	33580	0.0 SPENT POTLINER (GM90-3145)
333	001562-0311	USPCI	USPCI GRASSY MTN.	32340	26-Mar-91		ERR SPENT POTLINER (GM90-3145)
327	001562-0304	USPCI	USPCI GRASSY MTN.	31500	27-Mar-91	31500	0.0 SPENT POTLINER (GM90-3145)
329	001562-0306	USPCI	USPCI GRASSY MTN.	39240	27-Mar-91		ERR SPENT POTLINER (GM90-3145)
338	001562-0315	USPCI	USPCI GRASSY MTN.	32220	28-Mar-91	32220	0.0 SPENT POTLINER (GM90-3145)
337	001562-0314	USPCI	USPCI GRASSY MTN.	31880	28-Mar-91	31880	0.0 SPENT POTLINER (GM90-3145)

87 For Qtr: Report 1<sup>st</sup> Qtr = 25  
 Not posted = 62

21- SPL March ((@ Grassy 150 CH))

4- Safety Kleen = 7270 pounds

Grassy SPL = 200,760 pounds

LM SPL = ~~51,100~~ pounds  
 498,060

## ATTACHMENT (1)

NORANDA ALUMINUM HAZARDOUS WASTE SHIPMENTS MANIFEST FILE 06/14/91

EPA NUMBER	STATE	NUMBER	TRANSPORTER	FACILITY	POUNDS	SHIP DATE	FACILITY	X	WEIGHT	COMMENTS
SK53			SAFETY KLEEN	SAFETY-KLEEN AT CAPE	1521	25-Mar-91	1521	0.0	SPENT POTLINER (LM90-0905)	
1 01562-0001	LWD INC		LWD INC	CALVERT CITY	4174	05-Aug-87			MIXER CLEANOUT WASTES. (A) IS PCB EU57 (B) IS PCB EX71	
2 IL1721153	CWM		T.W.I. SAUGET, IL		8905	10-Sep-87			(A) CB REACTOR BAGS; (B) MOBILTAC-C; (C)EP-2; (D) MOBLTEP-78	
3 CWMA402378	CHEMICAL WASTE MGT.	CWM AT EMEILLE, AL.			2640	08-Jun-88			FUME DUCT SLUDGE FROM GREEN MILL; D008	
4 1562-0002	LWD, INC.		LWD CALVERT CITY, KY		1716	11-Apr-88			WASTE FROM GREEN MILL HOT OIL SYSTEM CLEANOUT; F002	
5 1562-0003	SLAY TRANSPORTATION	MONSANTO; ST LOUIS, MO			39180	17-Aug-88			MANIFEST NOT NEEDED ACCORDING TO BOB BOLAND OF MONSANTO	
6 1562-0004	LWD TRUCKING		LWD; CALVERT CITY, KY		250	17-Aug-88			WASTE SOLVENTS FROM THE LAB; F001-F005	
7 CWMA377921	CHEMICAL WASTE MGT.	CWM-EMEILLE, AL.			5320	28-Sep-88			CARBON BAKE REACTOR BAGS; D006	
8 CWMA438650	CHEMICAL WASTE MTG.	CWM-EMEILLE, AL.			2080	19-Oct-88			CARBON BAKE REACTOR BAGS; D006	
9 CWMA438651	CHEMICAL WASTE MGT.	CWM-EMEILLE, AL.			4060	02-Nov-88			CARBON BAKE REACTOR BAGS; D006	
10 CWMA438652	CHEMICAL WASTE MGT.	CWM-EMEILLE, AL,			5380	21-Nov-88			CARBON BAKE REACTOR BAGS; D006	
11 01562-0005	LWD TRUCKING, INC.		LWD; CALVERT CITY, KY		991	16-Jan-89			WASTE PAINT FROM LAB AND PES; OLD UNUSED TCE FROM WAREHOUSE	
12 01562-0006	LWD TRUCKING, INC.		LWD, - CALVERT CITY		250	22-Mar-89			WASTE SOLVENTS FROM THE LAB; F001-F005	
13 LA1111852	JACK GRAY TRANSPORT	CWM CARLYSS, LA			44980	16-Mar-89			SPL THAT CONTAINED >500 PPM FREE CN	
14 LA1111854	JACK GRAY TRANSPORT	CWM CARLYSS, LA			47400	16-Mar-89			SPL THAT CONTAINED >500 PPM FREE CN	
15 LA1111853	JACK GRAY TRANSPORT	CWM CARLYSS, LA			40640	16-Mar-89			SPL THAT CONTAINED >500 PPM FREE CN	
16 LA1171998	CHEMICAL WASTE	CWM-LAKE CHARLES LA			5120	22-Jan-90			CARBON BAKE REACTOR BAGS; D006	
17 LA1176991	CHEMICAL WASTE	CWM-CARLYSS LA			8560	30-Jan-90			CARBON BAKE REACTOR BAGS (D006)	
18 LA1176992	CHEMICAL WASTE	CWM-CARLYSS LA			6560	12-Feb-90			CARBON BAKE REACTOR BAGS	
19 LA1176993	CHEMICAL WASTE	CWM-CARLYSS LA			3320	26-Feb-90			CARBON BAKE REACTOR BAGS	
20 LA1176994	CHEMICAL WASTE	CWM-CARLYSS LA			4500	02-Apr-90			CARBON BAKE REACTOR BAGS	
21 LA1176995	CHEMICAL WASTE	CWM-CARLYSS LA			5680	09-Jul-90			CARBON BAKE REACTOR BAGS	
22 LA1204728	JACK GRAY TRANSPORT	CWM-CARLYSS LA			48040	24-Jul-90			SPENT POTLINER (J13906)	
23 LA1204729	JACK GRAY TRANSPORT	CWM-CARLYSS LA			43780	24-Jul-89			SPENT POTLINER (J13906)	
24 LA1204727	JACK GRAY TRANSPORT	CWM-CARLYSS LA			42660	24-Jul-90			SPENT POTLINER (J13906)	
25 LA1204726	JACK GRAY TRANSPORT	CWM-CARLYSS LA			45000	24-Jul-90			SPENT POTLINER (J13906)	
26 001562-0007	JACK GRAY TRANSPORT	USPCI LONE MOUNTAIN			43860	09-Aug-90			SPENT POTLINER (LM90-0905)	
27 001562-0008	JACK GRAY TRANSPORT	USPCI LONE MOUNTAIN			48380	09-Aug-90			SPENT POTLINER (LM90-0905)	
28 001562-0009	JACK GRAY TRANSPORT	USPCI LONE MOUNTAIN			46340	09-Aug-90			SPENT POTLINER (LM90-0905)	
29 001562-0010	JACK GRAY TRANSPORT	USPCI LONE MOUNTAIN			44480	09-Aug-90			SPENT POTLINER (LM90-0905)	
30 001562-0011	JACK GRAY TRANSPORT	USPCI LONE MOUNTAIN			42120	09-Aug-90			SPENT POTLINER (LM90-0905)	
31 001562-0012	FORT TRANSFER	USPCI LONE MOUNTAIN			48840	15-Aug-90			SPENT POTLINER (LM90-0905)	
32 001562-0013	FORT TRANSFER	USPCI LONE MOUNTAIN			45180	15-Aug-90			SPENT POTLINER (LM90-0905)	
33 001562-0014	FORT TRANSFER	USPCI LONE MOUNTAIN			47340	15-Aug-90			SPENT POTLINER (LM90-0905)	
34 001562-0015	FORT TRANSFER	USPCI LONE MOUNTAIN			46720	15-Aug-90			SPENT POTLINER (LM90-0905)	
35 001562-0016	FORT TRANSFER	USPCI LONE MOUNTAIN			46500	15-Aug-90			SPENT POTLINER (LM90-0905)	
36 001562-0017	FORT TRANSFER	USPCI LONE MOUNTAIN			47160	15-Aug-90			SPENT POTLINER (LM90-0905)	
37 001562-0018	FORT TRANSFER	USPCI LONE MOUNTAIN			43460	15-Aug-90			SPENT POTLINER (LM90-0905)	
38 001562-0019	FORT TRANSFER	USPCI LONE MOUNTAIN			46840	15-Aug-90			SPENT POTLINER (LM90-0905)	
39 001562-0020	FORT TRANSFER	USPCI LONE MOUNTAIN			48740	15-Aug-90			SPENT POTLINER (LM90-0905)	
40 001562-0021	FORT TRANSFER	USPCI LONE MOUNTAIN			47080	15-Aug-90			SPENT POTLINER (LM90-0905)	
41 001562-0022	FORT TRANSFER	USPCI LONE MOUNTAIN			47720	15-Aug-90			SPENT POTLINER (LM90-0905)	
42 001562-0023	FORT TRANSFER	USPCI LONE MOUNTAIN			47060	15-Aug-90			SPENT POTLINER (LM90-0905)	

## NORANDA ALUMINUM HAZARDOUS WASTE SHIPMENTS MANIFEST FILE 06/14/91

43	001562-0024	FORT TRANSFER	USPCI LONE MOUNTAIN		15-Aug-90	SPENT POTLINER (LM90-0905) VOIDED 8/15/90
44	001562-0025	FORT TRANSFER	USPCI LONE MOUNTAIN	47860	15-Aug-90	SPENT POTLINER (LM90-0905)
45	001562-0026	FORT TRANSFER	USPCI LONE MOUNTAIN	46200	15-Aug-90	SPENT POTLINER (LM90-0905)
46	001562-0027	JOE BROWN CO., INC.	USPCI LONE MOUNTAIN	48900	15-Aug-90	SPENT POTLINER (LM90-0905)
47	001562-0028	JOE BROWN CO., INC	USPCI LONE MOUNTAIN	46960	15-Aug-90	SPENT POTLINER (LM90-0905)
48	001562-0029	JOE BROWN CO., INC	USPCI LONE MOUNTAIN	47960	15-Aug-90	SPENT POTLINER (LM90-0905)
49	001562-0030	FORT TRANSFER	USPCI LONE MOUNTAIN	46500	15-Aug-90	SPENT POTLINER (LM90-0905)
50	001562-0031	FORT TRANSFER	USPCI LONE MOUNTAIN	47480	21-Aug-90	SPENT POTLINER (LM90-0905)
51	001562-0032	FORT TRANSFER	USPCI LONE MOUNTAIN	47580	21-Aug-90	SPENT POTLINER (LM90-0905)
52	001562-0033	FORT TRANSFER	USPCI LONE MOUNTAIN	47800	21-Aug-90	SPENT POTLINER (LM90-0905)
53	001562-0034	FORT TRANSFER	USPCI LONE MOUNTAIN	44280	21-Aug-90	SPENT POTLINER (LM90-0905)
54	001562-0035	FORT TRANSFER	USPCI LONE MOUNTAIN	45900	21-Aug-90	SPENT POTLINER (LM90-0905)
55	001562-0036	FORT TRANSFER	USPCI LONE MOUNTAIN	46640	21-Aug-90	SPENT POTLINER (LM90-0905)
56	001562-0037	FORT TRANSFER	USPCI LONE MOUNTAIN	46660	21-Aug-90	SPENT POTLINER (LM90-0905)
57	001562-0038	LIBERTY	USPCI LONE MOUNTAIN	47540	21-Aug-90	SPENT POTLINER (LM90-0905)
58	001562-0039	LIBERTY	USPCI LONE MOUNTAIN	46160	21-Aug-90	SPENT POTLINER (LM90-0905)
59	001562-0040	LIBERTY	USPCI LONE MOUNTAIN	45740	21-Aug-90	SPENT POTLINER (LM90-0905)
60	001562-0041	LIBERTY	USPCI LONE MOUNTAIN	48340	21-Aug-90	SPENT POTLINER (LM90-0905)
61	001562-0042	LIBERTY	USPCI LONE MOUNTAIN	49200	21-Aug-90	SPENT POTLINER (LM90-0905)
62	001562-0043	LIBERTY	USPCI LONE MOUNTAIN	47500	21-Aug-90	SPENT POTLINER (LM90-0905)
63	001562-0044	FORT TRANSFER	USPCI LONE MOUNTAIN	46940	23-Aug-90	SPENT POTLINER (LM90-0905)
64	001562-0045	FORT TRANSFER	USPCI LONE MOUNTAIN	48900	23-Aug-90	SPENT POTLINER (LM90-0905)
65	001562-0046	FORT TRANSFER	USPCI LONE MOUNTAIN	45500	23-Aug-90	SPENT POTLINER (LM90-0905)
66	001562-0047	FORT TRANSFER	USPCI LONE MOUNTAIN	46560	23-Aug-90	SPENT POTLINER (LM90-0905)
67	001562-0048	LIBERTY	USPCI LONE MOUNTAIN	48680	23-Aug-90	SPENT POTLINER (LM90-0905)
68	001562-0049	LIBERTY	USPCI LONE MOUNTAIN	48540	23-Aug-90	SPENT POTLINER (LM90-0905)
69	001562-0050	LIBERTY	USPCI LONE MOUNTAIN	47060	23-Aug-90	SPENT POTLINER (LM90-0905)
70	001562-0051	LIBERTY	USPCI LONE MOUNTAIN	49060	23-Aug-90	SPENT POTLINER (LM90-0905)
71	001562-0052	LIBERTY	USPCI LONE MOUNTAIN	46900	23-Aug-90	SPENT POTLINER (LM90-0905)
72	001562-0053	LIBERTY	USPCI LONE MOUNTAIN	49280	23-Aug-90	SPENT POTLINER (LM90-0905)
73	001562-0054	BEELMAN TRUCK COMPANY	USPCI LONE MOUNTAIN	45500	28-Aug-90	SPENT POTLINER (LM90-0905)
74	001562-0055	BEELMAN TRUCK COMPANY	USPCI LONE MOUNTAIN	50380	28-Aug-90	SPENT POTLINER (LM90-0905)
75	001562-0056	BEELMAN TRUCK COMPANY	USPCI LONE MOUNTAIN	48440	28-Aug-90	SPENT POTLINER (LM90-0905)
76	001562-0057	BEELMAN TRUCK COMPANY	USPCI LONE MOUNTAIN	47120	28-Aug-90	SPENT POTLINER (LM90-0905)
77	001562-0058	BEELMAN TRUCK COMPANY	USPCI LONE MOUNTAIN	41580	28-Aug-90	SPENT POTLINER (LM90-0905)
78	001562-0059	BEELMAN TRUCK COMPANY	USPCI LONE MOUNTAIN	46720	28-Aug-90	SPENT POTLINER (LM90-0905)
79	001562-0060	BEELMAN TRUCK COMPANY	USPCI LONE MOUNTAIN	49380	28-Aug-90	SPENT POTLINER (LM90-0905)
80	001562-0061	BEELMAN TRUCK COMPANY	USPCI LONE MOUNTAIN	49060	28-Aug-90	SPENT POTLINER (LM90-0905)
81	001562-0062	BEELMAN TRUCK COMPANY	USPCI LONE MOUNTAIN	48680	28-Aug-90	SPENT POTLINER (LM90-0905)
82	001562-0063	BEELMAN TRUCK COMPANY	USPCI LONE MOUNTAIN	50100	28-Aug-90	SPENT POTLINER (LM90-0905)
83	001562-0064	BEELMAN TRUCK COMPANY	USPCI LONE MOUNTAIN	45360	30-Aug-90	SPENT POTLINER (LM90-0905)
84	001562-0065	BEELMAN TRUCK COMPANY	USPCI LONE MOUNTAIN	45260	30-Aug-90	SPENT POTLINER (LM90-0905)
85	001562-0066	BEELMAN TRUCK COMPANY	USPCI LONE MOUNTAIN	50020	30-Aug-90	SPENT POTLINER (LM90-0905)
86	001562-0067	BEELMAN TRUCK COMPANY	USPCI LONE MOUNTAIN	50920	30-Aug-90	SPENT POTLINER (LM90-0905)

## NORANDA ALUMINUM HAZARDOUS WASTE SHIPMENTS MANIFEST FILE 06/14/91

87	001562-0068	BEELMAN TRUCK COMPANUSPCI LONE MOUNTAIN	47620	30-Aug-90	SPENT POTLINER (LM90-0905)
88	001562-0069	BEELMAN TRUCK COMPANUSPCI LONE MOUNTAIN	46880	30-Aug-90	SPENT POTLINER (LM90-0905)
89	001562-0070	BEELMAN TRUCK COMPANUSPCI LONE MOUNTAIN	49480	30-Aug-90	SPENT POTLINER (LM90-0905)
90	001562-0071	BEELMAN TRUCK COMPANUSPCI LONE MOUNTAIN	46560	30-Aug-90	SPENT POTLINER (LM90-0905)
91	001562-0072	BEELMAN TRUCK COMPANUSPCI LONE MOUNTAIN	48960	30-Aug-90	SPENT POTLINER (LM90-0905)
92	001562-0073	BEELMAN TRUCK COMPANUSPCI LONE MOUNTAIN	50700	30-Aug-90	SPENT POTLINER (LM90-0905)
93	001562-0074	BEELMAN TRUCK COMPANUSPCI LONE MOUNTAIN	50060	30-Aug-90	SPENT POTLINER (LM90-0905)
94	001562-0075	FORT TRANSFER USPCI LONE MOUNTAIN	46360	04-Sep-90	SPENT POTLINER (LM90-0905)
95	001562-0076	LIBERTY USPCI LONE MOUNTAIN	43760	04-Sep-90	SPENT POTLINER (LM90-0905)
96	001562-0077	LIBERTY USPCI LONE MOUNTAIN	44060	04-Sep-90	SPENT POTLINER (LM90-0905)
97	001562-0078	LIBERTY USPCI LONE MOUNTAIN	49420	04-Sep-90	SPENT POTLINER (LM90-0905)
98	001562-0079	BEELMAN TRUCK COMPANUSPCI LONE MOUNTAIN	48900	04-Sep-90	SPENT POTLINER (LM90-0905)
99	001562-0080	BEELMAN TRUCK COMPANUSPCI LONE MOUNTAIN	45320	04-Sep-90	SPENT POTLINER (LM90-0905)
100	001562-0081	BEELMAN TRUCK COMPANUSPCI LONE MOUNTAIN	48040	04-Sep-90	SPENT POTLINER (LM90-0905)
101	001562-0082	LIBERTY USPCI LONE MOUNTAIN	47680	04-Sep-90	SPENT POTLINER (LM90-0905)
102	001562-0083	BEELMAN TRUCK COMPANUSPCI LONE MOUNTAIN	40880	04-Sep-90	SPENT POTLINER (LM90-0905)
103	001562-0084	LIBERTY USPCI LONE MOUNTAIN	44300	04-Sep-90	SPENT POTLINER (LM90-0905)
104	001562-0085	LIBERTY USPCI LONE MOUNTAIN	48940	04-Sep-90	SPENT POTLINER (LM90-0905)
105	001562-0086	LIBERTY USPCI LONE MOUNTAIN	48020	04-Sep-90	SPENT POTLINER (LM90-0905)
106	001562-0087	LIBERTY USPCI LONE MOUNTAIN	47880	04-Sep-90	SPENT POTLINER (LM90-0905)
107	001562-0088	LIBERTY USPCI LONE MOUNTAIN	45960	06-Sep-90	SPENT POTLINER (LM90-0905)
108	001562-0089	LIBERTY USPCI LONE MOUNTAIN	46700	06-Sep-90	SPENT POTLINER (LM90-0905)
109	001562-0090	LIBERTY USPCI LONE MOUNTAIN	47200	06-Sep-90	SPENT POTLINER (LM90-0905)
110	001562-0091	LIBERTY USPCI LONE MOUNTAIN	42220	06-Sep-90	SPENT POTLINER (LM90-0905)
111	001562-0092	FORT TRANSFER USPCI LONE MOUNTAIN	45340	06-Sep-90	SPENT POTLINER (LM90-0905)
112	001562-0093	LIBERTY USPCI LONE MOUNTAIN	49360	06-Sep-90	SPENT POTLINER (LM90-0905)
113	001562-0094	LIBERTY USPCI LONE MOUNTAIN	45780	06-Sep-90	SPENT POTLINER (LM90-0905)
114	001562-0095	LIBERTY USPCI LONE MOUNTAIN	44000	06-Sep-90	SPENT POTLINER (LM90-0905)
115	001562-0096	LIBERTY USPCI LONE MOUNTAIN	47120	06-Sep-90	SPENT POTLINER (LM90-0905)
116	001562-0097	FORT TRANSFER USPCI LONE MOUNTAIN	37940	06-Sep-90	SPENT POTLINER (LM90-0905)
117	001562-0098	LIBERTY USPCI LONE MOUNTAIN	48540	11-Sep-90	SPENT POTLINER (LM90-0905)
118	001562-0099	LIBERTY USPCI LONE MOUNTAIN	48860	11-Sep-90	SPENT POTLINER (LM90-0905)
119	001562-0100	LIBERTY USPCI LONE MOUNTAIN	48540	11-Sep-90	SPENT POTLINER (LM90-0905)
120	001562-0101	LIBERTY USPCI LONE MOUNTAIN	48340	11-Sep-90	SPENT POTLINER (LM90-0905)
121	001562-0102	LIBERTY USPCI LONE MOUNTAIN	49020	11-Sep-90	SPENT POTLINER (LM90-0905)
122	001562-0103	FORT TRANSFER USPCI LONE MOUNTAIN	47680	11-Sep-90	SPENT POTLINER (LM90-0905)
123	001562-0104	FORT TRANSFER USPCI LONE MOUNTAIN	47120	11-Sep-90	SPENT POTLINER (LM90-0905)
124	001562-0105	FORT TRANSFER USPCI LONE MOUNTAIN	47820	11-Sep-90	SPENT POTLINER (LM90-0905)
125	001562-0106	LIBERTY USPCI LONE MOUNTAIN	47140	11-Sep-90	SPENT POTLINER (LM90-0905)
126	001562-0107	FORT TRANSFER USPCI LONE MOUNTAIN	47620	11-Sep-90	SPENT POTLINER (LM90-0905)
127	001562-0108	LIBERTY USPCI LONE MOUNTAIN	49060	13-Sep-90	SPENT POTLINER (LM90-0905)
128		LIBERTY USPCI LONE MOUNTAIN		06-Sep-90	VOID, EPA NO. SKIPPED, MO NO. WAS NOT
129	001562-0109	LIBERTY USPCI LONE MOUNTAIN	48040	13-Sep-90	SPENT POTLINER (LM90-0905)
130	001562-0110	LIBERTY USPCI LONE MOUNTAIN	48760	13-Sep-90	SPENT POTLINER (LM90-0905)

## NORANDA ALUMINUM HAZARDOUS WASTE SHIPMENTS MANIFEST FILE 06/14/91

131	001562-0111	LIBERTY	USPCI LONE MOUNTAIN	47240	13-Sep-90	SPENT POTLINER (LM90-0905)
132	001562-0112	FORT TRANSFER	USPCI LONE MOUNTAIN	45780	13-Sep-90	SPENT POTLINER (LM90-0905)
133	001562-0113	FORT TRANSFER	USPCI LONE MOUNTAIN	44000	13-Sep-90	SPENT POTLINER (LM90-0905)
134	001562-0114	LIBERTY	USPCI LONE MOUNTAIN	48040	13-Sep-90	SPENT POTLINER (LM90-0905)
135	001562-0115	FORT TRANSFER	USPCI LONE MOUNTAIN	46380	13-Sep-90	SPENT POTLINER (LM90-0905)
136	001562-0116	LIBERTY	USPCI LONE MOUNTAIN	46860	13-Sep-90	SPENT POTLINER (LM90-0905)
137	001562-0117	FORT TRANSFER	USPCI LONE MOUNTAIN	44000	13-Sep-90	SPENT POTLINER (LM90-0905)
138	001562-0117	LIBERTY	USPCI LONE MOUNTAIN	48360	18-Sep-90	SPENT POTLINER (LM90-0905)
139	001562-0118	LIBERTY	USPCI LONE MOUNTAIN	48320	18-Sep-90	SPENT POTLINER (LM90-0905)
140	001562-0119	LIBERTY	USPCI LONE MOUNTAIN	46400	18-Sep-90	SPENT POTLINER (LM90-0905)
141	001562-0120	LIBERTY	USPCI LONE MOUNTAIN	46800	18-Sep-90	SPENT POTLINER (LM90-0905)
142	001562-0121	LIBERTY	USPCI LONE MOUNTAIN	45620	18-Sep-90	SPENT POTLINER (LM90-0905)
143	001562-0122	LIBERTY	USPCI LONE MOUNTAIN	45280	18-Sep-90	SPENT POTLINER (LM90-0905)
144	001562-0123	FORT TRANSFER	USPCI LONE MOUNTAIN	47000	18-Sep-90	SPENT POTLINER (LM90-0905)
145	001562-0124	FORT TRANSFER	USPCI LONE MOUNTAIN	45380	18-Sep-90	SPENT POTLINER (LM90-0905)
146	001562-0125	FORT TRANSFER	USPCI LONE MOUNTAIN	46920	18-Sep-90	SPENT POTLINER (LM90-0905)
147	001562-0126	FORT TRANSFER	USPCI LONE MOUNTAIN	44360	18-Sep-90	SPENT POTLINER (LM90-0905)
148	001562-0127	LIBERTY	USPCI LONE MOUNTAIN	48400	20-Sep-90	SPENT POTLINER (LM90-0905)
149	001562-0128	LIBERTY	USPCI LONE MOUNTAIN	48000	20-Sep-90	SPENT POTLINER (LM90-0905)
150	001562-0129	LIBERTY	USPCI LONE MOUNTAIN	48340	20-Sep-90	SPENT POTLINER (LM90-0905)
151	001562-0130	LIBERTY	USPCI LONE MOUNTAIN	46440	20-Sep-90	SPENT POTLINER (LM90-0905)
152	001562-0131	LIBERTY	USPCI LONE MOUNTAIN	48800	20-Sep-90	SPENT POTLINER (LM90-0905)
153	001562-0132	FORT TRANSFER	USPCI LONE MOUNTAIN	46640	20-Sep-90	SPENT POTLINER (LM90-0905)
154	001562-0133	LIBERTY	USPCI LONE MOUNTAIN	47000	20-Sep-90	SPENT POTLINER (LM90-0905)
155	001562-0134	FORT TRANSFER	USPCI LONE MOUNTAIN	45620	20-Sep-90	SPENT POTLINER (LM90-0905)
156	001562-0135	FORT TRANSFER	USPCI LONE MOUNTAIN	43520	20-Sep-90	SPENT POTLINER (LM90-0905)
157	001562-0136	FORT TRANSFER	USPCI LONE MOUNTAIN	48980	25-Sep-90	SPENT POTLINER (LM90-0905)
158	001562-0137	FORT TRANSFER	USPCI LONE MOUNTAIN	48780	25-Sep-90	SPENT POTLINER (LM90-0905)
159	001562-0138	FORT TRANSFER	USPCI LONE MOUNTAIN	45780	25-Sep-90	SPENT POTLINER (LM90-0905)
160	001562-0139	FORT TRANSFER	USPCI LONE MOUNTAIN	44860	25-Sep-90	SPENT POTLINER (LM90-0905)
161	001562-0140	JOE BROWN CO., INC.	USPCI LONE MOUNTAIN	42680	25-Sep-90	SPENT POTLINER (LM90-0905)
162	001562-0141	JOE BROWN CO., INC.	USPCI LONE MOUNTAIN	42780	25-Sep-90	SPENT POTLINER (LM90-0905)
163	001562-0142	JOE BROWN CO., INC.	USPCI LONE MOUNTAIN	42960	25-Sep-90	SPENT POTLINER (LM90-0905)
164	001562-0143	FORT TRANSFER	USPCI LONE MOUNTAIN	45000	25-Sep-90	SPENT POTLINER (LM90-0905)
165	001562-0144	JACK GRAY TRANSPORT	USPCI LONE MOUNTAIN	45880	11-Oct-90	SPENT POTLINER (LM90-0905)
166	001562-0145	JACK GRAY TRANSPORT	USPCI LONE MOUNTAIN	48200	11-Oct-90	SPENT POTLINER (LM90-0905)
167	001562-0146	JACK GRAY TRANSPORT	USPCI LONE MOUNTAIN	43980	11-Oct-90	SPENT POTLINER (LM90-0905)
168	001562-0147	JACK GRAY TRANSPORT	USPCI LONE MOUNTAIN	46620	11-Oct-90	SPENT POTLINER (LM90-0905)
169	001562-0148	JACK GRAY TRANSPORT	USPCI LONE MOUNTAIN	46980	11-Oct-90	SPENT POTLINER (LM90-0905)
170	001562-0149	JACK GRAY TRANSPORT	USPCI LONE MOUNTAIN	49380	11-Oct-90	SPENT POTLINER (LM90-0905)
171	001562-0150	JACK GRAY TRANSPORT	USPCI LONE MOUNTAIN	46200	11-Oct-90	SPENT POTLINER (LM90-0905)
172	001562-0151	JACK GRAY TRANSPORT	USPCI LONE MOUNTAIN	47240	11-Oct-90	SPENT POTLINER (LM90-0905)
173	001562-0152	JACK GRAY TRANSPORT	USPCI LONE MOUNTAIN	44660	11-Oct-90	SPENT POTLINER (LM90-0905)
174	001562-0153	SAFETY-KLEEN	S-K/NEW CASTLE, KY	880	12-Oct-90	2ND AND 3RD TRANSPORTER REGARDING THIS MANIFEST

## NORANDA ALUMINUM HAZARDOUS WASTE SHIPMENTS MANIFEST FILE 06/14/91

175	001562-0154	TRIAD TRANSPORT	USPCI LONE MOUNTAIN	44300	18-Oct-90	SPENT POTLINER (LM90-0905)
176	001562-0155	TRIAD TRANSPORT	USPCI LONE MOUNTAIN	45200	18-Oct-90	SPENT POTLINER (LM90-0905)
177	001562-0156	TRIAD TRANSPORT	USPCI LONE MOUNTAIN	46080	18-Oct-90	SPENT POTLINER (LM90-0905)
178	001562-0157	FORT TRANSFER	USPCI LONE MOUNTAIN	44100	18-Oct-90	SPENT POTLINER (LM90-0905)
179	001562-0158	TRIAD TRANSPORT	USPCI LONE MOUNTAIN	46540	18-Oct-90	SPENT POTLINER (LM90-0905)
180	001562-0158	TRIAD TRANSPORT	USPCI LONE MOUNTAIN	42740	18-Oct-90	SPENT POTLINER (LM90-0905)
181	001562-0159	FORT TRANSFER	USPCI LONE MOUNTAIN	43400	18-Oct-90	SPENT POTLINER (LM90-0905)
182	001562-0160	TRIAD TRANSPORT	USPCI LONE MOUNTAIN	46460	25-Oct-90	SPENT POTLINER (LM90-0905)
183	001562-0161	TRIAD TRANSPORT	USPCI LONE MOUNTAIN	44960	25-Oct-90	SPENT POTLINER (LM90-0905)
184	001562-0162	TRIAD TRANSPORT	USPCI LONE MOUNTAIN	43260	25-Oct-90	SPENT POTLINER (LM90-0905)
185	001562-0163	TRIAD TRANSPORT	USPCI LONE MOUNTAIN	37620	25-Oct-90	SPENT POTLINER (LM90-0905)
186	001562-0164	TRIAD TRANSPORT	USPCI LONE MOUNTAIN	43220	25-Oct-90	SPENT POTLINER (LM90-0905)
187	001562-0165	TRIAD TRANSPORT	USPCI LONE MOUNTAIN	39000	25-Oct-90	SPENT POTLINER (LM90-0905)
188	001562-0166	TRIAD TRANSPORT	USPCI LONE MOUNTAIN	40420	25-Oct-90	SPENT POTLINER (LM90-0905)
189	001562-0167	TRIAD TRANSPORT	USPCI LONE MOUNTAIN	40100	25-Oct-90	SPENT POTLINER (LM90-0905)
190	001562-0168	TRIAD TRANSPORT	USPCI LONE MOUNTAIN	39160	25-Oct-90	SPENT POTLINER (LM90-0905)
191	001562-0169	TRIAD TRANSPORT	USPCI LONE MOUNTAIN	48100	25-Oct-90	SPENT POTLINER (LM90-0905)
192	001562-0170	TRIAD TRANSPORT	USPCI LONE MOUNTAIN	41220	30-Oct-90	SPENT POTLINER (LM90-0905)
193	001562-0171	TRIAD TRANSPORT	USPCI LONE MOUNTAIN	38840	30-Oct-90	SPENT POTLINER (LM90-0905)
194	001562-0172	TRIAD TRANSPORT	USPCI LONE MOUNTAIN	43460	30-Oct-90	SPENT POTLINER (LM90-0905)
195	001562-0173	TRIAD TRANSPORT	USPCI LONE MOUNTAIN	41860	30-Oct-90	SPENT POTLINER (LM90-0905)
196	001562-0174	TRIAD TRANSPORT	USPCI LONE MOUNTAIN	40280	30-Oct-90	SPENT POTLINER (LM90-0905)
197	001562-0175	TRIAD TRANSPORT	USPCI LONE MOUNTAIN	43060	30-Oct-90	SPENT POTLINER (LM90-0905)
198	001562-0176	TRIAD TRANSPORT	USPCI LONE MOUNTAIN	45160	30-Oct-90	SPENT POTLINER (LM90-0905)
199	001562-0177	TRIAD TRANSPORT	USPCI LONE MOUNTAIN	44160	30-Oct-90	SPENT POTLINER (LM90-0905)
200	001562-0178	TRIAD TRANSPORT	USPCI LONE MOUNTAIN	43980	30-Oct-90	SPENT POTLINER (LM90-0905)
201	001562-0179	TRIAD TRANSPORT	USPCI LONE MOUNTAIN	47120	08-Nov-90	SPENT POTLINER (LM90-0905)
202	001562-0180	TRIAD TRANSPORT	USPCI LONE MOUNTAIN	41880	08-Nov-90	SPENT POTLINER (LM90-0905)
203	001562-0181	TRIAD TRANSPORT	USPCI LONE MOUNTAIN	43560	08-Nov-90	SPENT POTLINER (LM90-0905)
204	001562-0182	TRIAD TRANSPORT	USPCI LONE MOUNTAIN	45060	08-Nov-90	SPENT POTLINER (LM90-0905)
205	001562-0183	TRIAD TRANSPORT	USPCI LONE MOUNTAIN	33700	08-Nov-90	SPENT POTLINER (LM90-0905)
206	001562-0184	TRIAD TRANSPORT	USPCI LONE MOUNTAIN	44540	08-Nov-90	SPENT POTLINER (LM90-0905)
207	001562-0185	TRIAD TRANSPORT	USPCI LONE MOUNTAIN	39840	08-Nov-90	SPENT POTLINER (LM90-0905)
208	001562-0186	TRIAD TRANSPORT	USPCI LONE MOUNTAIN	44280	08-Nov-90	SPENT POTLINER (LM90-0905)
209	001562-0187	TRIAD TRANSPORT	USPCI LONE MOUNTAIN	45380	27-Nov-90	SPENT POTLINER (LM90-0905)
210	001562-0188	TRIAD TRANSPORT	USPCI LONE MOUNTAIN	45800	27-Nov-90	SPENT POTLINER (LM90-0905)
211	001562-0189	TRIAD TRANSPORT	USPCI LONE MOUNTAIN	47320	27-Nov-90	SPENT POTLINER (LM90-0905)
212	001562-0190	TRIAD TRANSPORT	USPCI LONE MOUNTAIN	44220	27-Nov-90	SPENT POTLINER (LM90-0905)
213	001562-0191	TRIAD TRANSPORT	USPCI LONE MOUNTAIN	40340	27-Nov-90	SPENT POTLINER (LM90-0905)
214	001562-0192	TRIAD TRANSPORT	USPCI LONE MOUNTAIN	46560	27-Nov-90	SPENT POTLINER (LM90-0905)
215	001562-0193	TRIAD TRANSPORT	USPCI LONE MOUNTAIN	42820	27-Nov-90	SPENT POTLINER (LM90-0905)
216	001562-0194	TRIAD TRANSPORT	USPCI LONE MOUNTAIN	44380	27-Nov-90	SPENT POTLINER (LM90-0905)
217	001562-0195	TRIAD TRANSPORT	USPCI LONE MOUNTAIN	41180	27-Nov-90	SPENT POTLINER (LM90-0905)
218	001562-0196	TRIAD TRANSPORT	USPCI LONE MOUNTAIN	43340	27-Nov-90	SPENT POTLINER (LM90-0905)

## NORANDA ALUMINUM HAZARDOUS WASTE SHIPMENTS MANIFEST FILE 06/14/91

219	001562-0197	TRIAD TRANSPORT	USPCI LONE MOUNTAIN	47900	29-Nov-90	SPENT POTLINER (LM90-0905)
220	001562-0198	TRIAD TRANSPORT	USPCI LONE MOUNTAIN	42720	29-Nov-90	SPENT POTLINER (LM90-0905)
221	001562-0199	TRIAD TRANSPORT	USPCI LONE MOUNTAIN	40860	29-Nov-90	SPENT POTLINER (LM90-0905)
222	001562-0200	TRIAD TRANSPORT	USPCI LONE MOUNTAIN	37180	29-Nov-90	SPENT POTLINER (LM90-0905)
223	001562-0201	TRIAD TRANSPORT	USPCI LONE MOUNTAIN	42020	29-Nov-90	SPENT POTLINER (LM90-0905)
224	001562-0202	TRIAD TRANSPORT	USPCI LONE MOUNTAIN	41040	29-Nov-90	SPENT POTLINER (LM90-0905)
225	001562-0203	TRIAD TRANSPORT	USPCI LONE MOUNTAIN	43360	29-Nov-90	SPENT POTLINER (LM90-0905)
226	001562-0204	TRIAD TRANSPORT	USPCI LONE MOUNTAIN	45320	29-Nov-90	SPENT POTLINER (LM90-0905)
227	001562-0205	TRIAD TRANSPORT	USPCI LONE MOUNTAIN	39920	29-Nov-90	SPENT POTLINER (LM90-0905)
228	001562-0206	TRIAD TRANSPORT	USPCI LONE MOUNTAIN	41260	29-Nov-90	SPENT POTLINER (LM90-0905)
229	001562-0207	JOE BROWN CO.	USPCI LONE MOUNTAIN	44160	06-Dec-90	SPENT POTLINER (LM90-0905)
230	001562-0208	TRIAD TRANSPORT	USPCI LONE MOUNTAIN	38660	06-Dec-90	SPENT POTLINER (LM90-0905)
231	001562-0209	TRIAD TRANSPORT	USPCI LONE MOUNTAIN	40980	06-Dec-90	SPENT POTLINER (LM90-0905)
232	001562-0210	JOE BROWN CO.	USPCI LONE MOUNTAIN	44180	06-Dec-90	SPENT POTLINER (LM90-0905)
233	001562-0211	TRIAD TRANSPORT	USPCI LONE MOUNTAIN	40240	06-Dec-90	SPENT POTLINER (LM90-0905)
234	001562-0212	FORT TRANSFER	USPCI LONE MOUNTAIN	46980	06-Dec-90	SPENT POTLINER (LM90-0905)
235	001562-0213	FORT TRANSFER	USPCI LONE MOUNTAIN	45180	06-Dec-90	SPENT POTLINER (LM90-0905)
236	001562-0214	LIBERTY TRANSPORT	USPCI LONE MOUNTAIN	48820	06-Dec-90	SPENT POTLINER (LM90-0905)
237	001562-0215	FORT TRANSFER	USPCI LONE MOUNTAIN	46260	06-Dec-90	SPENT POTLINER (LM90-0905)
238	001562-0216	FORT TRANSFER	USPCI LONE MOUNTAIN	44320	06-Dec-90	SPENT POTLINER (LM90-0905)
239	001562-0217	TRIAD TRANSPORT	USPCI LONE MOUNTAIN	44380	13-Dec-90	SPENT POTLINER (LM90-0905)
240	001562-0218	TRIAD TRANSPORT	USPCI LONE MOUNTAIN	42200	13-Dec-90	SPENT POTLINER (LM90-0905)
241	001562-0219	JOE BROWN CO.	USPCI LONE MOUNTAIN	44280	13-Dec-90	SPENT POTLINER (LM90-0905)
242	001562-0220	JOE BROWN CO.	USPCI LONE MOUNTAIN	43600	13-Dec-90	SPENT POTLINER (LM90-0905)
243	001562-0221	JOE BROWN CO.	USPCI LONE MOUNTAIN	42420	13-Dec-90	SPENT POTLINER (LM90-0905)
244	001562-0222	TRIAD TRANSPORT	USPCI LONE MOUNTAIN	45700	13-Dec-90	SPENT POTLINER (LM90-0905)
245	001562-0223	TRIAD TRANSPORT	USPCI LONE MOUNTAIN	42180	13-Dec-90	SPENT POTLINER (LM90-0905)
246	001562-0224	TRIAD TRANSPORT	USPCI LONE MOUNTAIN	42980	13-Dec-90	SPENT POTLINER (LM90-0905)
247	001562-0225	TRIAD TRANSPORT	USPCI LONE MOUNTAIN	42420	13-Dec-90	SPENT POTLINER (LM90-0905)
248	001562-0226	TRIAD TRANSPORT	USPCI LONE MOUNTAIN	44240	13-Dec-90	SPENT POTLINER (LM90-0905)
249	AR421515	CLEAN UP TRANSPORT	IRF	3340	20-Dec-90	SPENT POTLINER (LM90-0905)
250	001562-0227	USPCI	USPCI LONE MOUNTAIN	28520	10-Jan-91	SPENT POTLINER (LM90-0905) ALCOA MATERIAL
251	001562-0228	TRIAD TRANSPORT	USPCI LONE MOUNTAIN	39280	17-Jan-91	SPENT POTLINER (LM90-0905)
252	001562-0229	TRIAD TRANSPORT	USPCI LONE MOUNTAIN	42020	17-Jan-91	SPENT POTLINER (LM90-0905)
253	001562-0230	TRIAD TRANSPORT	USPCI LONE MOUNTAIN	42840	17-Jan-91	SPENT POTLINER (LM90-0905)
254	001562-0231	JOE BROWN CO.	USPCI LONE MOUNTAIN	42040	17-Jan-91	SPENT POTLINER (LM90-0905)
255	001562-0232	JOE BROWN CO.	USPCI LONE MOUNTAIN	44540	17-Jan-91	SPENT POTLINER (LM90-0905)
256	001562-0233	JOE BROWN CO.	USPCI LONE MOUNTAIN	43460	17-Jan-91	SPENT POTLINER (LM90-0905)
257	001562-0234	JOE BROWN CO.	USPCI LONE MOUNTAIN	43720	17-Jan-91	SPENT POTLINER (LM90-0905)
258	001562-0235	JOE BROWN CO.	USPCI LONE MOUNTAIN	42560	17-Jan-91	SPENT POTLINER (LM90-0905)
259	001562-0236	TRIAD TRANSPORT	USPCI LONE MOUNTAIN	43360	17-Jan-91	SPENT POTLINER (LM90-0905)
260	001562-0237	TRIAD TRANSPORT	USPCI LONE MOUNTAIN	44540	17-Jan-91	SPENT POTLINER (LM90-0905)
261	001562-0238	JOE BROWN CO.	USPCI LONE MOUNTAIN	37340	22-Jan-91	SPENT POTLINER (LM90-0905)
262	001562-0239	JOE BROWN CO.	USPCI LONE MOUNTAIN	42260	22-Jan-91	SPENT POTLINER (LM90-0905)

## NORANDA ALUMINUM HAZARDOUS WASTE SHIPMENTS MANIFEST FILE 06/14/91

263	001562-0240	JOE BROWN CO.	USPCI LONE MOUNTAIN	47000	22-Jan-91		SPENT POTLINER (LM90-0905)
264	001562-0241	JOE BROWN CO.	USPCI LONE MOUNTAIN	43140	22-Jan-91		SPENT POTLINER (LM90-0905)
265	001562-0242	TRIAD TRANSPORT	USPCI LONE MOUNTAIN	45600	22-Jan-91		SPENT POTLINER (LM90-0905)
266	001562-0243	TRIAD TRANSPORT	USPCI LONE MOUNTAIN	45520	22-Jan-91		SPENT POTLINER (LM90-0905)
267	001562-0244	TRIAD TRANSPORT	USPCI LONE MOUNTAIN	39360	22-Jan-91		SPENT POTLINER (LM90-0905)
268	001562-0245	TRIAD TRANSPORT	USPCI LONE MOUNTAIN	41800	22-Jan-91		SPENT POTLINER (LM90-0905)
269	001562-0246	TRIAD TRANSPORT	USPCI LONE MOUNTAIN	43500	22-Jan-91		SPENT POTLINER (LM90-0905)
270	001562-0247	JOE BROWN CO.	USPCI LONE MOUNTAIN	46480	22-Jan-91		SPENT POTLINER (LM90-0905)
271	001562-0248	TRIAD TRANSPORT	USPCI LONE MOUNTAIN	43340	24-Jan-91		SPENT POTLINER (LM90-0905)
272	001562-0249	TRIAD TRANSPORT	USPCI LONE MOUNTAIN	48800	24-Jan-91		SPENT POTLINER (LM90-0905)
273	001562-0250	TRIAD TRANSPORT	USPCI LONE MOUNTAIN	43720	24-Jan-91		SPENT POTLINER (LM90-0905)
274	001562-0251	TRIAD TRANSPORT	USPCI LONE MOUNTAIN	46560	24-Jan-91		SPENT POTLINER (LM90-0905)
275	001562-0252	TRIAD TRANSPORT	USPCI LONE MOUNTAIN	43780	24-Jan-91	43800	0.0 SPENT POTLINER (LM90-0905)
276	001562-0253	JOE BROWN CO.	USPCI LONE MOUNTAIN	42600	24-Jan-91	42660	0.1 SPENT POTLINER (LM90-0905)
277	001562-0254	JOE BROWN CO.	USPCI LONE MOUNTAIN	38920	24-Jan-91	43020	9.5 SPENT POTLINER (LM90-0905)
278	001562-0255	JOE BROWN CO.	USPCI LONE MOUNTAIN	38140	24-Jan-91	38060	-0.2 SPENT POTLINER (LM90-0905)
279	001562-256	JOE BROWN CO.	USPCI LONE MOUNTAIN	41440	24-Jan-91	41760	0.8 SPENT POTLINER (LM90-0905)
280	001562-0257	JOE BROWN CO.	USPCI LONE MOUNTAIN	43940	24-Jan-91	44120	0.4 SPENT POTLINER (LM90-0905)
281	001562-0258	TRIAD TRANSPORT	USPCI LONE MOUNTAIN	37980	31-Jan-91	38080	0.3 SPENT POTLINER (LM90-0905)
282	001562-0259	TRIAD TRANSPORT	USPCI LONE MOUNTAIN	44420	31-Jan-91	45060	1.4 SPENT POTLINER (LM90-0905)
283	001562-0260	JOE BROWN CO.	USPCI LONE MOUNTAIN	43600	31-Jan-91	43780	0.4 SPENT POTLINER (LM90-0905)
284	001562-0261	JOE BROWN CO.	USPCI LONE MOUNTAIN	43920	31-Jan-91	44080	0.4 SPENT POTLINER (LM90-0905)
285	001562-0262	JOE BROWN CO.	USPCI LONE MOUNTAIN	37580	31-Jan-91	38240	1.7 SPENT POTLINER (LM90-0905)
286	001562-0263	JOE BROWN CO.	USPCI LONE MOUNTAIN	46060	31-Jan-91	46860	1.7 SPENT POTLINER (LM90-0905)
287	001562-0264	JOE BROWN CO.	USPCI LONE MOUNTAIN	35200	31-Jan-91	35800	1.7 SPENT POTLINER (LM90-0905)
288	001562-0265	TRIAD TRANSPORT	USPCI LONE MOUNTAIN	34200	31-Jan-91	34840	1.8 SPENT POTLINER (LM90-0905)
289	001562-0266	TRIAD TRANSPORT	USPCI LONE MOUNTAIN	38420	31-Jan-91	38840	1.1 SPENT POTLINER (LM90-0905)
290	001562-0267	TRIAD TRANSPORT	USPCI LONE MOUNTAIN	43680	31-Jan-91	43080	-1.4 SPENT POTLINER (LM90-0905)
291	001562-0268	USPCI	USPCI LONE MOUNTAIN	34580	27-Feb-91	32800	-5.4 SPENT POTLINER (LM90-0905)
292	001562-0269	USPCI	USPCI LONE MOUNTAIN	27460	27-Feb-91	27460	0.0 SPENT POTLINER (LM90-0905)
293	001562-0270	TRIAD TRANSPORT	USPCI LONE MOUNTAIN	44160	27-Feb-91	42440	-4.1 SPENT POTLINER (LM90-0905)
294	001562-0271	TRIAD TRANSPORT	USPCI LONE MOUNTAIN	46800	27-Feb-91	49320	5.1 SPENT POTLINER (LM90-0905)
295	001562-0272	TRIAD TRANSPORT	USPCI LONE MOUNTAIN	46360	27-Feb-91	45400	-2.1 SPENT POTLINER (LM90-0905)
296	001562-0273	JOE BROWN CO.	USPCI LONE MOUNTAIN	46140	25-Feb-91	45240	-2.0 SPENT POTLINER (LM90-0905)
297	001562-0274	JOE BROWN CO.	USPCI LONE MOUNTAIN	41580	25-Feb-91	41180	-1.0 SPENT POTLINER (LM90-0905)
298	001562-0275	JOE BROWN CO.	USPCI LONE MOUNTAIN	42100	25-Feb-91	42100	0.0 SPENT POTLINER (LM90-0905)
299	001562-0276	JOE BROWN CO.	USPCI LONE MOUNTAIN	42480	25-Feb-91	42700	0.5 SPENT POTLINER (LM90-0905)
300	001562-0277	JOE BROWN CO.	USPCI LONE MOUNTAIN	41640	25-Feb-91	41920	0.7 SPENT POTLINER (LM90-0905)
301	001562-0278	USPCI	USPCI LONE MOUNTAIN	39560	25-Feb-91	39020	-1.4 SPENT POTLINER (LM90-0905)
302	001562-0279	USPCI	USPCI LONE MOUNTAIN	43540	25-Feb-91	41420	-5.1 SPENT POTLINER (LM90-0905)
303	001562-0280	USPCI	USPCI LONE MOUNTAIN	43760	25-Feb-91	44320	1.3 SPENT POTLINER (LM90-0905)
304	001562-0281	TRIAD TRANSPORT	USPCI LONE MOUNTAIN	41660	27-Feb-91	41120	-1.3 SPENT POTLINER (LM90-0905)
305	001562-0282	TRIAD TRANSPORT	USPCI LONE MOUNTAIN	44800	27-Feb-91	43300	-3.5 SPENT POTLINER (LM90-0905)
306	001562-0283	TRIAD TRANSPORT	USPCI LONE MOUNTAIN	46440	27-Feb-91	45180	-2.8 SPENT POTLINER (LM90-0905)

## NORANDA ALUMINUM HAZARDOUS WASTE SHIPMENTS MANIFEST FILE 06/14/91

307	001562-0284	TRIAD TRANSPORT	USPCI LONE MOUNTAIN	38780	28-Feb-91	38780	0.0	SPENT POTLINER (LM90-0905)
308	001562-0285	TRIAD TRANSPORT	USPCI LONE MOUNTAIN	42580	28-Feb-91	43040	1.1	SPENT POTLINER (LM90-0905)
309	001562-0286	TRIAD TRANSPORT	USPCI LONE MOUNTAIN	41700	28-Feb-91	41720	0.0	SPENT POTLINER (LM90-0905)
310	001562-0287	TRIAD TRANSPORT	USPCI LONE MOUNTAIN	42360	28-Feb-91	42720	0.8	SPENT POTLINER (LM90-0905)
311	001562-0288	TRIAD TRANSPORT	USPCI LONE MOUNTAIN	43180	28-Feb-91	40600	-6.4	SPENT POTLINER (LM90-0905)
312	001562-0289	JOE BROWN CO.	USPCI LONE MOUNTAIN	39460	01-Mar-91	38660	-2.1	SPENT POTLINER (LM90-0905)
313	001562-0290	JOE BROWN CO.	USPCI LONE MOUNTAIN	39320	01-Mar-91	39800	1.2	SPENT POTLINER (LM90-0905)
314	001562-0291	JOE BROWN CO.	USPCI LONE MOUNTAIN	41440	01-Mar-91	42620	2.8	SPENT POTLINER (LM90-0905)
315	001562-0292	JOE BROWN CO.	USPCI LONE MOUNTAIN	36740	01-Mar-91	38100	3.6	SPENT POTLINER (LM90-0905)
316	001562-0293	JOE BROWN CO.	USPCI LONE MOUNTAIN	43860	01-Mar-91	41900	-4.7	SPENT POTLINER (LM90-0905)
317	001562-0294	JOE BROWN CO.	USPCI LONE MOUNTAIN	36200	01-Mar-91	35000	-3.4	SPENT POTLINER (LM90-0905)
318	001562-0295	USCPI	USPCI LONE MOUNTAIN	31580	11-Mar-91	28800	-9.7	SPENT POTLINER (LM90-0905)
319	001562-0296	USCPI	USPCI LONE MOUNTAIN	31460	11-Mar-91	32120	2.1	SPENT POTLINER (LM90-0905)
320	001562-0297	USCPI	USPCI LONE MOUNTAIN	28760	11-Mar-91	28760	0.0	SPENT POTLINER (LM90-0905)
321	001562-0298	USCPI	USPCI LONE MOUNTAIN	29620	08-Mar-91	31580	6.2	SPENT POTLINER (LM90-0905)
322	001562-0299	USCPI	USPCI LONE MOUNTAIN	32380	07-Mar-91	31820	-1.8	SPENT POTLINER (LM90-0905)
323	001562-0300	USCPI	USPCI LONE MOUNTAIN	25540	25-Mar-91	26380	3.2	SPENT POTLINER (LM90-0905)
324	001562-0301	TRIAD	USPCI LONE MOUNTAIN	43120	28-Feb-91	45940	6.1	SPENT POTLINER (LM90-0905)
325	001562-0302	USCPI	USPCI LONE MOUNTAIN	21280	13-Mar-91	21220	-0.3	SPENT POTLINER (LM90-0905)
326	001562-0303	USCPI	USPCI LONE MOUNTAIN	32600	13-Mar-91	34480	5.5	SPENT POTLINER (LM90-0905)
327	001562-0304	USCPI	USPCI GRASSY MTN.	31500	27-Mar-91	31500	0.0	SPENT POTLINER (GM90-3145)
328	001562-0305	USCPI	USPCI LONE MOUNTAIN	27820	25-Mar-91	27820	0.0	SPENT POTLINER (LM90-0905)
329	001562-0306	USCPI	USPCI GRASSY MTN.	39240	27-Mar-91	39240	0.0	SPENT POTLINER (GM90-3145)
330	001562-0307	USCPI	USPCI LONE MOUNTAIN	36540	02-Apr-91	37440	2.4	SPENT POTLINER (LM90-0905)
331	SKIPPED	USCPI	USPCI GRASSY MTN.		25-Oct-90		ERR SKIPPED	
332	001562-0310	USCPI	USPCI GRASSY MTN.	33580	26-Mar-91	33580	0.0	SPENT POTLINER (GM90-3145)
333	001562-0311	USCPI	USPCI GRASSY MTN.	32340	26-Mar-91	32340	0.0	SPENT POTLINER (GM90-3145)
334	SKIPPED	USCPI	USPCI GRASSY MTN.		25-Oct-90		ERR SKIPPED	
335	001562-0312	USCPI	USPCI GRASSY MTN.	32000	01-Apr-91	33160	3.5	SPENT POTLINER (GM90-3145)
336	001562-0313	USCPI	USPCI GRASSY MTN.	38780	01-Apr-91	40000	3.1	SPENT POTLINER (GM90-3145)
337	001562-0314	USCPI	USPCI GRASSY MTN.	31880	28-Mar-91	31880	0.0	SPENT POTLINER (GM90-3145)
338	001562-0315	USCPI	USPCI GRASSY MTN.	32220	28-Mar-91	32220	0.0	SPENT POTLINER (GM90-3145)
339	001562-0316	USCPI	USPCI GRASSY MTN.	28180	09-Apr-91	28180	0.0	SPENT POTLINER (GM90-3145)
340	001562-0317	USCPI	USPCI GRASSY MTN.	33960	08-Apr-91	34400	1.3	SPENT POTLINER (GM90-3145)
341	001562-0318	USCPI	USPCI GRASSY MTN.	26620	08-Apr-91	26620	0.0	SPENT POTLINER (GM90-3145)
342	001562-0319	USCPI	USPCI GRASSY MTN.	35740	12-Apr-91	37120	3.7	SPENT POTLINER (GM90-3145)
343	001562-0320	USCPI	USPCI GRASSY MTN.	24080	10-Apr-91	24080	0.0	SPENT POTLINER (GM90-3145)
344	001562-0321	USCPI	USPCI GRASSY MTN.	34040	23-Apr-91	34040	0.0	SPENT POTLINER (GM90-3145)
345	001562-0322	USCPI	USPCI GRASSY MTN.	32080	10-Apr-91	32580	1.5	SPENT POTLINER (GM90-3145)
346	001562-0323	USCPI	USPCI GRASSY MTN.	35600	09-Apr-91	36040	1.2	SPENT POTLINER (GM90-3145)
347	001562-0324	USCPI	USPCI GRASSY MTN.	32480	11-Apr-91	32960	1.5	SPENT POTLINER (GM90-3145)
348	001562-0325	USCPI	USPCI GRASSY MTN.	30420	01-May-91		ERR SPENT POTLINER (GM90-3145)	
349	001562-0326	USCPI	USPCI GRASSY MTN.	35440	16-Apr-91	35820	1.1	SPENT POTLINER (GM90-3145)
350	001562-0327	USCPI	USPCI GRASSY MTN.	32520	12-Apr-91	32520	0.0	SPENT POTLINER (GM90-3145)

## NORANDA ALUMINUM HAZARDOUS WASTE SHIPMENTS MANIFEST FILE 06/14/91

351	001562-0328	USCPI	USPCI GRASSY MTN.	30080	13-Apr-91	31580	4.7 SPENT POTLINER (GM90-3145)
352	001562-0329	USCPI	USPCI GRASSY MTN.	24540	24-Apr-91		ERR SPENT POTLINER (GM90-3145)
353	001562-0330	USCPI	USPCI GRASSY MTN.	33000	15-Apr-91	33800	2.4 SPENT POTLINER (GM90-3145)
354	001562-0331	USCPI	USPCI GRASSY MTN.	34840	03-May-91		ERR SPENT POTLINER (GM90-3145)
355	5123548	SAFETY-KLEEN CORP.	SAFETY-KLEEN DOLTON	40	11-Apr-91		ERR DOLTON, IL - PAINT THINNER AND INK
356	001562-0332	USCPI	USPCI GRASSY MTN.	31840	07-May-91		ERR SPENT POTLINER (GM90-3145)
357	001562-0333	USCPI	USPCI GRASSY MTN.	37000	22-Apr-91		ERR SPENT POTLINER GM90-3145
358	001562-0334	USCPI	USPCI GRASSY MTN.	33380	08-May-91	33360	0.0 SPENT POTLINER (GM90-3145)
359	001562-0335	USCPI	USPCI GRASSY MTN.	33160	01-May-91		ERR SPENT POTLINER (GM90-3145)
360	001562-336	USCPI	USPCI GRASSY MTN.	35240	06-May-91	33980	-3.7 SPENT POTLINER (GM90-3145)
361	001562-0337	USCPI	USPCI GRASSY MTN.	37580	05-May-91	37840	0.7 SPENT POTLINER (GM90-3145)
362	001562-0338	USCPI	USPCI GRASSY MTN.	29280	13-May-91		ERR SPENT POTLINER (GM90-3145)
363	001562-339	USCPI	USPCI GRASSY MTN.	34740	06-May-91	34920	0.5 SPENT POTLINER (GM90-3145)
364	001562-0340	USCPI	USPCI GRASSY MTN.	30620	07-May-91	30620	0.0 SPENT POTLINER (GM90-3145)
365	001562-0341	USCPI	USPCI GRASSY MTN.	25260	17-May-91		ERR SPENT POTLINER (GM90-3145)
366	001562-0342	USCPI	USPCI GRASSY MTN.	32840	18-May-91		ERR SPENT POTLINER (GM90-3145)
367	001562-0343	USCPI	USPCI LONE MOUNTAIN	6380	23-Apr-91	7020	9.1 PITCH COATED REACTOR BAGS
368	001562-0344	USCPI	USPCI LONE MOUNTAIN	10820	23-Apr-91	10820	0.0 PITCH COATED REACTOR BAGS
369	001562-0345	USCPI	USPCI GRASSY MTN.	31160	17-May-91		ERR SPENT POTLINER (GM90-3145)
370	001562-0346	USCPI	USPCI GRASSY MTN.	32180	20-May-91		ERR SPENT POTLINER (GM90-3145)
371	001562-0347	USCPI	USPCI GRASSY MTN.	39840	20-May-91		ERR SPENT POTLINER (GM90-3145)
372	001562-0348	USCPI	USPCI GRASSY MTN.	37620	12-May-91		ERR SPENT POTLINER (GM90-3145)
373	001562-0349	USCPI	USPCI GRASSY MTN.	31480	18-May-91		ERR SPENT POTLINER (GM90-3145)
374	001562-0350	USCPI	USPCI GRASSY MTN.	34560	16-May-91		ERR SPENT POTLINER (GM90-3145)
375	001562-0351	USCPI	USPCI GRASSY MTN.	33600	19-May-91		ERR SPENT POTLINER (GM90-3145)
376	001562-0352	USCPI	USPCI GRASSY MTN.	33800	20-May-91		ERR SPENT POTLINER (GM90-3145)
377	001562-0353	USCPI	USPCI GRASSY MTN.	32860	20-May-91		ERR SPENT POTLINER (GM90-3145)
378	001562-0354	USCPI	USPCI GRASSY MTN.	32940	23-May-91		ERR SPENT POTLINER (GM90-3145)
379	IL3118799	CHEMICAL WASTE MGT.	TRADE WASTE INCINER.	90	22-May-91		ERR WASTE LAB SOLVENTS, WEIGHT IS IN GALLONS. 3 DRUMS
380	001562-0355	USCPI	USPCI GRASSY MTN.	33660	22-May-91		ERR SPENT POTLINER (GM90-3145)
381	001562-0356	USCPI	USPCI GRASSY MTN.	33460	22-May-91		ERR SPENT POTLINER (GM90-3145)
382	001562-0357	USCPI	USPCI GRASSY MTN.	32720	21-May-91		ERR SPENT POTLINER (GM90-3145)
383	001562-0358	USCPI	USPCI GRASSY MTN.	33040	21-May-91		ERR SPENT POTLINER (GM90-3145)
384	001562-0359	USCPI	USPCI GRASSY MTN.	32880	22-May-91		ERR SPENT POTLINER (GM90-3145)
385	001562-0360	USCPI	USPCI GRASSY MTN.	31380	22-May-91		ERR SPENT POTLINER (GM90-3145)
386	001562-0361	USCPI	USPCI GRASSY MTN.	27080	30-May-91		ERR SPENT POTLINER (GM90-3145)
387	001562-0362	USCPI	USPCI GRASSY MTN.	31340	23-May-91		ERR SPENT POTLINER (GM90-3145)
388	001562-0363	USCPI	USPCI GRASSY MTN.	32980	24-May-91		ERR SPENT POTLINER (GM90-3145)
389	001562-0364	USCPI	USPCI GRASSY MTN.	29520	31-May-91		ERR SPENT POTLINER (GM90-3145)
390	001562-0365	USCPI	USPCI GRASSY MTN.	32180	24-May-91		ERR SPENT POTLINER (GM90-3145)
391	001562-0366	USCPI	USPCI GRASSY MTN.	38640	29-May-91		ERR SPENT POTLINER (GM90-3145)
392	001562-0367	USCPI	USPCI GRASSY MTN.	34480	30-May-91		ERR SPENT POTLINER (GM90-3145)
394	001562-0369	USCPI	USPCI GRASSY MTN.	31189	14-Jun-91		ERR SPENT POTLINER (GM90-3145)
396	001562-0371	USCPI	USPCI GRASSY MTN.	33580	11-Jun-91		ERR SPENT POTLINER (GM90-3145)

## NORANDA ALUMINUM HAZARDOUS WASTE SHIPMENTS MANIFEST FILE 06/14/91

397	001562-0372	USCPI	USPCI GRASSY MTN.	32140	10-Jun-91	ERR SPENT POTLINER (GM90-3145)
398	001562-0373	USCPI	USPCI GRASSY MTN.	33060	14-Jun-91	ERR SPENT POTLINER (GM90-3145)
399	001562-0374	USCPI	USPCI GRASSY MTN.	32040	11-Jun-91	ERR SPENT POTLINER (GM90-3145)
400	001562-0375	USCPI	USPCI GRASSY MTN.	28340	12-Jun-91	ERR SPENT POTLINER (GM90-3145)
401	001562-0376	USCPI	USPCI GRASSY MTN.	33040	10-Jun-91	ERR SPENT POTLINER (GM90-3145)
405	001562-0380	USCPI	USPCI GRASSY MTN.	32860	13-Jun-91	ERR SPENT POTLINER (GM90-3145)
3045	SK54	SAFETY KLEEN	SAFETY-KLEEN AT CAPE	1167	23-Apr-91	0.0 SOLVENT FROM PARTS WASHERS
4503	SK25	SAFETY-KLEEN	SAFETY-KLEEN AT CAPE	4810	09-Jan-89	SOLVENT FROM PARTS WASHERS
4855	SK46	SAFETY-KLEEN	SAFETY-KLEEN AT CAPE	1978	11-Sep-90	SOLVENT FROM PARTS WASHERS
6255	SK03	SAFETY-KLEEN	SAFETY-KLEEN AT CAPE	435	03-Aug-87	SOLVENTS FROM THE PARTS WASHERS
6445	SK28	SAFETY-KLEEN	SAFETY-KLEEN AT CAPE	1650	31-Mar-89	SOLVENT FROM PARTS WASHERS
10296	SK52	SAFETY KLEEN	SAFETY-KLEEN AT CAPE	3055	04-Mar-91	SOLVENT FROM PARTS WASHERS
11111	SK15	SAFETY-KLEEN	SAFETY-KLEEN AT CAPE	3250	05-May-88	SOLVENTS FROM PARTS WASHERS
11656	SK05	SAFETY-KLEEN	SAFETY-KLEEN AT CAPE	820	26-Aug-87	SOLVENTS FROM THE PARTS WASHERS
15378	SK21	SAFETY-KLEEN	SAFETY-KLEEN AT CAPE	1380	21-Sep-88	SOLVENTS FROM PARTS WASHERS
15754	SK33	SAFETY-KLEEN	SAFETY-KLEEN AT CAPE	2680	18-Aug-89	SOLVENT FROM PARTS WASHERS
16862	SK32	SAFETY-KLEEN	SAFETY-KLEEN AT CAPE	705	18-Jul-89	SOLVENT FROM PARTS WASHERS
17109	SK12	SAFETY-KLEEN	SAFETY-KLEEN AT CAPE	585	09-Feb-88	SOLVENTS FROM PARTS WASHERS
17140	SK31	SAFETY-KLEEN	SAFETY-KLEEN AT CAPE	2650	21-Jun-89	SOLVENT FROM PARTS WASHERS
17201	SK34	SAFETY-KLEEN	SAFETY-KLEEN AT CAPE	2724	19-Oct-89	SOLVENT FROM PARTS WASHERS
19114	SK35	SAFETY-KLEEN	SAFETY-KLEEN AT CAPE	430	09-Nov-89	SOLVENT FROM PARTS WASHERS
19734	SK06	SAFETY-KLEEN	SAFETY-KLEEN AT CAPE	760	23-Sep-87	SOLVENTS FROM THE PARTS WASHERS
20944	SK36	SAFETY KLEEN	SAFETY-KLEEN AT CAPE	1253	05-Dec-89	SOLVENT FROM PARTS WASHERS
22695	SK30	SAFETY-KLEEN	SAFETY-KLEEN AT CAPE	650	24-May-89	SOLVENT FROM PARTS WASHERS
22962	SK48	SAFETY-KLEEN	SAFETY-KLEEN AT CAPE	1290	06-Nov-90	SOLVENT FROM PARTS WASHERS
25377	SK01	SAFETY-KLEEN	SAFETY-KLEEN AT CAPE	360	03-Jun-87	SOLVENTS FROM THE PARTS WASHERS
26181	SK16	SAFETY-KLEEN	SAFETY-KLEEN AT CAPE	1410	31-May-88	SOLVENTS FROM PARTS WASHERS
27457	SK07	SAFETY-KLEEN	SAFETY-KLEEN AT CAPE	780	19-Oct-87	SOLVENTS FROM PARTS WASHERS
27477	SK29	SAFETY-KLEEN	SAFETY-KLEEN AT CAPE	1489	25-Apr-89	SOLVENT FROM PARTS WASHERS
28111	SK43	SAFETY KLEEN	SAFETY-KLEEN AT CAPE	1290	18-Jun-90	SOLVENT FROM PARTS WASHERS
29746	SK50	SAFETY-KLEEN	SAFETY-KLEEN AT CAPE	1290	03-Jan-91	SOLVENTS FROM PARTS WASHERS
32666	SK38	SAFETY KLEEN	SAFETY-KLEEN AT CAPE	1290	30-Jan-90	SOLVENT FROM PARTS WASHERS
37123	SK08	SAFETY-KLEEN	SAFETY-KLEEN AT CAPE	780	19-Nov-87	SOLVENTS FROM PARTS WASHERS
37425	SK37	SAFETY KLEEN	SAFETY-KLEEN AT CAPE	1376	03-Jan-90	SOLVENT FROM PARTS WASHERS
37584	SK22	SAFETY-KLEEN	SAFETY-KLEEN AT CAPE	2645	18-Oct-88	SOLVENTS FROM PARTS WASHERS
39036	SK39	SAFETY KLEEN	SAFETY-KLEEN AT CAPE	888	02-Mar-90	SOLVENT FROM PARTS WASHERS
40946	SK17	SAFETY-KLEEN	SAFETY-KLEEN AT CAPE	1325	28-Jun-88	SOLVENTS FROM PARTS WASHERS
45917	SK45	SAFETY KLEEN	SAFETY-KLEEN AT CAPE	602	13-Aug-90	SOLVENT FROM PARTS WASHERS
46193	SK40	SAFETY KLEEN	SAFETY-KLEEN AT CAPE	1892	28-Mar-90	SOLVENT FROM PARTS WASHERS
46654	SK55	SAFETY KLEEN	SAFETY-KLEEN AT CAPE	2373	23-May-91	ERR SOLVENT FROM PARTS WASHERS
51436	SK26	SAFETY-KLEEN	SAFETY-KLEEN AT CAPE	1400	31-Jan-89	SOLVENT FROM PARTS WASHERS
52116	SK47	SAFETY-KLEEN	SAFETY-KLEEN AT CAPE	774	08-Oct-90	SOLVENT FROM PARTS WASHERS
55978	SK09	SAFETY KLEEN	SAFETY-KLEEN AT CAPE	760	14-Dec-87	SOLVENTS FROM PARTS WASHERS
57387	SK41	SAFETY KLEEN	SAFETY-KLEEN AT CAPE	819	25-Apr-90	SOLVENT FROM PARTS WASHERS

## NORANDA ALUMINUM HAZARDOUS WASTE SHIPMENTS MANIFEST FILE 06/14/91

60237 SK02	SAFETY-KLEEN	SAFETY-KLEEN AT CAPE	360	01-Jul-87	SOLVENTS FROM THE PARTS WASHERS
60919 SK23	SAFETY-KLEEN	SAFETY-KLEEN AT CAPE	1690	15-Nov-88	SOLVENTS FROM PARTS WASHERS
62284 SK51	SAFETY KLEEN	SAFETY-KLEEN AT CAPE	1404	30-Jan-91	SOLVENT FROM PARTS WASHERS
63412 SK10	SAFETY-KLEEN	SAFETY-KLEEN AT CAPE	1220	11-Jan-88	SOLVENTS FROM PARTS WASHERS
67777 SK19	SAFETY-KLEEN	SAFETY-KLEEN AT CAPE	4800	01-Aug-88	SOLVENTS FROM PARTS WASHERS
68029 SK49	SAFETY-KLEEN	SAFETY-KLEEN AT CAPE	2110	06-Dec-90	SOLVENTS FROM PARTS WASHERS
69783 SK11	SAFETY-KLEEN	SAFETY-KLEEN AT CAPE	1430	08-Feb-88	SOLVENTS FROM PARTS WASHERS
75995 SK24	SAFETY-KLEEN	SAFETY-KLEEN AT CAPE	2280	09-Dec-88	SOLVENT FROM PARTS WASHERS
78183 SK27	SAFETY-KLEEN	SAFETY-KLEEN AT CAPE	1380	01-Mar-89	SOLVENT FROM PARTS WASHERS
79377 SK13	SAFETY-KLEEN	SAFETY-KLEEN AT CAPE	2015	07-Mar-88	SOLVENTS FROM PARTS WASHERS
81320 SK18	SAFETY-KLEEN	SAFETY-KLEEN AT CAPE	240	01-Aug-88	SOLVENTS FROM PARTS WASHERS
85464 SK42	SAFETY KLEEN	SAFETY-KLEEN AT CAPE	1204	25-May-90	SOLVENT FROM PARTS WASHERS
87181 SK20	SAFETY-KLEEN	SAFETY-KLEEN AT CAPE	1475	24-Aug-88	SOLVENTS FROM PARTS WASHERS
89198 SK04	SAFETY-KLEEN	SAFETY-KLEEN AT CAPE	425	12-Aug-87	SOLVENTS FROM THE PARTS WASHERS
98787 SK44	SAFETY KLEEN	SAFETY-KLEEN AT CAPE	1290	17-Jul-90	SOLVENT FROM PARTS WASHERS
99011 SK14	SAFETY-KLEEN	SAFETY-KLEEN AT CAPE	1755	04-Apr-88	SOLVENTS FROM PARTS WASHERS